

**Docket No. 272 – Development and Management Plan Inspection**

The Connecticut Light and Power Company Certificate of Environmental Compatibility and Public Need for the construction of a new 345-kV electric transmission line and associated facilities between Scovill Rock Switching Station in Middletown and Norwalk Substation in Norwalk, Connecticut, including reconstruction of portions of existing 115-kV and 345-kV electric transmission line, the construction of Beseck Switching Station in Wallingford, East Devon Substation in Milford, (and Singer Substation in Bridgeport), modifications at Scovill Rock Switching Station and Norwalk Substation, and the reconfiguration of certain interconnections.

**Segment 2b Inspection**

**Date:** February 1, 2008

**Inspector:** Matt Kelly

**Location:** Segment 2b – Cheshire/Hamden Town Line to East Devon Substation

**Rainfall:** 1.88” of precipitation were recorded since the last inspection with 1.80” of the total reported on 2/1. (NOAA data at New Haven, CT).

Areas of Inspection	Observation	Recommended Action	Corrected Action
Access roads and adjacent roadways	Clearing and access road construction appear to be complete in these sections at this time. 2/1/08	Continue to monitor active work areas and add controls as necessary. See EC section. 2/1/08	Not Applicable (NA)
Milford, CT, Orange CT, Woodbridge CT, Bethany CT, and Hamden CT	Stone pads remain in place at all entrances to access roads. New stone is being added to pads as necessary. 2/1/08	Continue to monitor for sediment tracking in active areas. Sweep roadways as necessary. 2/1/08	Active areas need regular attention
All access roads	Mats remain at the wetland crossings in these sections. 2/1/08	Continue to monitor. 2/1/08	NA
Milford, CT Caswell St/Bic Dr	All access points (overhead & underground) have been stabilized with stone pads, but the adjacent catch basin is still not protected. 12/14-2/1/08	Continue to monitor and sweep roadway as necessary. If sediment tracking continues, catch basin protection should be provided. 2/1/08	The remaining access points (overhead & underground) have been stabilized with stone pads
Woodbridge, CT Pease Rd	Sediment tracking was observed on Pease Road. Catch basin/curb inlet protection has not been provided. 1/24-2/1/08	Provide catch basin/curb inlet protection and sweep roadway as necessary. 2/1/08	Needs attention
Hamden, CT	Catch basin/curb inlet protection has not been	Provide catch basin/curb inlet protection and sweep	Needs attention

Areas of Inspection	Observation	Recommended Action	Corrected Action
Old Ln Rd	provided here. 1/24-2/1/08	roadway as necessary. 2/1/08	
<p>Foundation and site construction  <b>All sections</b></p> <p><b>Bethany, and Hamden CT</b></p> <p><b>Milford, CT</b></p> <p><b>Orange, CT</b></p> <p><b>Woodbridge, CT</b></p>	<p>H- frame structure and lattice tower removal continues in all sections. 2/1/08</p> <p>115-kV foundation work appears to be complete at this time within the ROW. 2/1/08</p> <p>Crane pads associated with the 115-kV work are being removed and transferred to the 345-kV portion of the line (pad reclamation) in these sections. 2/1/08</p> <p>Foundation work appears to be complete at this time. Structure installation continues off Wheelers Farm Rd, Eisenhower Park, West River St, North St, and Fresh Meadow Lane. 2/1/08</p> <p>345-kV foundation work continues off Treat Ln, Orange Center Rd, and Russell Ave. Structure installation continues off Pine Tree Dr, Lambert Rd, Sunset Dr, Hall Dr, and Dogburn Rd. 2/1/08</p> <p>Foundation work and structure installation continues within the Rimmon Rd/B'Nai Jacob section and Cowpath Ln. 2/1/08</p>	<p>Continue to monitor. 2/1/08</p> <p>Continue to monitor. See EC Section. 2/1/08</p> <p>Continue to monitor. See EC and Stabilization Sections. 2/1/08</p> <p>Continue to monitor active work areas. See EC Section. 2/1/08</p> <p>Continue to monitor active work areas. See EC Section. 2/1/08</p> <p>Continue to monitor active work areas. See EC Section. 2/1/08</p>	<p>NA</p> <p>NA</p> <p>NA</p> <p>NA</p> <p>NA</p> <p>NA</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
Hamden, CT	Foundation work continues between Downs Road (Bethany) to Gaylord Mtn. Rd. No active foundation work was observed this week. 2/1/08	Continue to monitor active work areas. See EC Section. 2/1/08	NA
Erosion and sediment controls  Milford & Orange, Woodbridge, CT          Plains Rd          West River St	<p>Roots have been retained in most cleared areas to maintain some soil stability. Crews have made good efforts to temporarily stabilize most disturbed areas with hay mulch. Timber mats and erosion controls are in place in and adjacent to wetland areas. 2/1/08</p> <p>Pad reclamation is complete in most areas at this time. Exposed soils have been graded and mulched. 2/1/08</p> <p>Spoil piles remain within upland portions of the ROW off Caswell St, Plains Rd, Oronoque Rd, E. Rutland Rd, Orange Center Rd, Hall Dr, Edward Crt, Russell Ave, and Cowpath Ln. Piles appear to be contained in upland portions of the ROW. 2/1/08</p> <p>Exposed soils remain within the drainage swale located to the south of the substation. An erosive gully was observed here this week. 2/1/08</p> <p>Silt fence has been repaired at structures #24023 &amp; #24025. 2/1/08</p>	<p>None at this time. Continue to utilize the appropriate erosion control measures and stabilize disturbed soils as necessary. 2/1/08</p> <p>Continue to monitor. Additional erosion controls are recommended in some areas during 345-kV foundation work. See Stabilization Section. 2/1/08</p> <p>Remove spoil piles when feasible. 2/1/08</p> <p>Fill gully with the appropriate material and stabilize exposed soils. 2/1/08</p> <p>Repair and maintain controls as necessary. 2/1/08</p>	<p>NA</p> <p>NA</p> <p>Needs attention when feasible</p> <p>Needs attention</p> <p>Silt fence has been repaired</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
Eisenhower Park	<p>2/1/08</p> <p>Excess sediment from foundation drilling was observed on wetland timbermats in this section. 1/24--2/1/08</p> <p>Excess sediment from foundation drilling was observed on wetland timbermats in this section. 1/25/07-2/1/08</p>	<p>Remove excess sediment from timbermat pads and add controls as necessary. See Wetland Section. 2/1/08</p> <p>Remove excess sediment from timbermat pads and add controls as necessary. See Wetland Section. 2/1/08</p>	<p>Needs attention when feasible</p> <p>Needs attention when feasible</p>
North St	<p>Silt fence controls remain at capacity near structure #24027. 1/4-2/1/08</p> <p>Silt fence is in need of repair at structure #24026. 2/1/08</p> <p>Excess sediment from foundation drilling was observed on wetland timbermats near structure #24030. 1/10-2/1/08</p>	<p>Repair/add controls as necessary. Remove excess sediment to restore capacity/function of controls. 2/1/08</p> <p>Repair/add controls as necessary. 2/1/08</p> <p>Remove excess sediment from mats and add controls as necessary. See Wetlands Section. 2/1/08</p>	<p>Efforts were made to repair controls but the controls remain overwhelmed with sand</p> <p>Needs attention</p> <p>Needs attention when feasible</p>
Pine Tree Dr	<p>Silt fence is in need of repair at structures #24030 &amp; #24032. 2/1/08</p> <p>Silt fence is in need of repair at structure #24042. 2/1/08</p>	<p>Repair/add controls as necessary. 2/1/08</p> <p>Repair/add controls as necessary. 2/1/08</p>	<p>Needs attention</p> <p>Needs attention</p>
Woodbridge, CT Glen Dam Reservoir	<p>Exposed soils remain on the slope adjacent to structure #3950. 8/24-2/1/08</p>	<p>Continue to monitor and stabilize disturbed areas when work is complete and activity will not return within 21 days. Add/maintain controls as necessary. Ensure sufficient stabilization during winter months. 2/1/08</p>	<p>Needs attention when feasible</p>
JCC	<p>Spoil piles remain within the ROW near structure #24022. 2/1/08</p>	<p>Remove spoil piles when feasible. 2/1/08</p>	<p>Needs attention when feasible</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p><b>Hamden, CT</b>  West Todd Street/  Gaylord Mountain</p> <p>Willow Street</p>	<p>#3932. Piles appear to be contained on site. 2/1/08</p> <p>In approximately three areas, stormwater pooled along the perimeter controls and filtered through as concentrated flow off the ROW (4/27/07). This only occurs during large rain events and wetland resource areas were not affected by this off site flow. 2/1/08</p> <p>Additional waterbars have been installed within the ROW access road and additional haybales were added at the sediment basin in an attempt to control and filter stormwater runoff. 2/1/08</p> <p>Sediment had once again breached the controls at structure #3993 (1/24/08). Additional haybales have been added to the sediment basin. 2/1/08</p> <p>Excess sediment has been removed from the timbermat crossing (wetland # 100) within the access road here. See Wetland Section. 2/1/08</p> <p>Spoils from foundation/grounding work remain on some of the timber mats at structure #4009. 9/21-2/1/08</p>	<p>Monitor during large rain events and investigate additional solutions to prevent stormwater conveyances off site. Although good efforts were made to control stormwater flow, continue to improve on-site containment. 2/1/08</p> <p>Monitor and maintain controls as necessary. 2/1/08</p> <p>Repair/add controls as necessary. See Wetlands Section. 2/1/08</p> <p>Continue to monitor and maintain controls to prevent further sedimentation to the wetlands. See Wetland Section. 2/1/08</p> <p>Continue to monitor and stabilize disturbed soils. Remove spoils from timber mats. 2/1/08</p>	<p>Good efforts were made but <i>needs additional evaluation/monitoring</i></p> <p>Additional controls have been installed within the ROW</p> <p>Additional haybales have been added to the sediment basin</p> <p>Excess sediment has been removed from the timbermat crossing within the access road here, but <i>needs further attention</i></p> <p>Needs attention when feasible</p>
<p>Inland Wetland and Watercourse encroachment and mitigation</p>	<p>The ACOE permit is in hand and approved wetland work continues. 2/1/08</p>	<p>Follow general guidelines of the permit whenever work in wetlands occurs. 2/1/08</p>	<p>NA</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p><b>Milford, CT</b></p> <p>Naugatuck Ave, Rt 121 and Oronoque Rd</p> <p>West River Street, Eisenhower Park, and North St</p>	<p>Timber mat crane pads remain adjacent to/in wetlands in these sections. 2/1/08</p> <p>A stone access road remains within the wetland accessed from West River Street. Timber mat crane pads remain within the wetland areas in these sections. 2/1/08</p> <p>Excess sediment from foundation drilling was observed on wetland timbermats in the ROW off West River St, North Street, and within Eisenhower Park. 2/1/08</p> <p>Equipment ruts have been graded and stabilized with mulch in the wetland near structure #24023. 2/1/08</p> <p>A disassembled lattice tower was observed in the wetland near proposed structure #24023. 2/1/08</p>	<p>Continue to monitor and add controls as necessary. 2/1/08</p> <p>Continue to monitor and add controls as necessary. 2/1/08</p> <p>Remove sediment from wetland area. Evaluate sediment accumulation within the wetland when mats are removed. Carefully remove sediment during the dry season if it is found to be greater than 2” in depth. See EC Section. 2/1/08</p> <p>Continue to monitor. See stabilization section. 2/1/08</p> <p>Remove the structure from the wetland. 2/1/08</p>	<p>NA at this time</p> <p>NA at this time</p> <p>Needs evaluation</p> <p>Equipment ruts have been graded and stabilized with mulch</p> <p>Needs attention</p>
<p>East Rutland Road (western access point)</p> <p><b>Orange, CT</b></p> <p>Sunset Drive, Pine Tree Rd (east), Treat Lane, Lambert Rd, Russell Ave, Hunting hill Road, Racebrook Rd, and Route 34</p>	<p>A stone access road remains at the wetland crossing off East Rutland. An existing stone culvert was already in place here. 2/1/08</p> <p>Timber mat crane pads/crossings remain at the wetland areas here. Stone wetland crossings are in place at Lambert Rd and Treat Lane. 2/1/08</p>	<p>Continue to monitor. Install controls as necessary. 2/1/08</p> <p>Continue to monitor. 2/1/08</p>	<p>NA at this time</p> <p>NA at this time.</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
Clearview Lane to Rt 15	Stone access roads and timber mat crossings remain in the wetland areas here. 2/1/08	Continue to monitor. 2/1/08	NA at this time
<b>Woodbridge, CT</b> Pease Road	Mats remain in the potential wetland area here. 2/1/08	Continue to monitor. The contractor states that this wetland was removed from the most recent version of the D&M plan, but flags were staked in the field. 2/1/08	NA at this time
	Tire ruts were noted in a wetland area within the abandoned ROW here. 11/16-2/1/08	Fill and stabilize ruts with appropriate material. In general, timber mats (or similar) should be used when it becomes necessary to access a wetland. 2/1/08	Needs attention
JCC/B’Nai Jacob	The wetland areas near the JCC and B’Nai Jacob have been cleared as a result of the permitted re-location of the ROW. Stone access roads remain in portions of the wetlands in these sections. 2/1/08	Continue to monitor. Adjust controls as necessary. 2/1/08	NA at this time
	Sediment was noted in the stream channel near structure #24119 at the JCC (8/7/07). No further accumulation has been observed. 2/1/08	Continue to monitor. Evaluate sediment accumulation within the stream channel. Carefully remove sediment during the dry season if it is greater than 2” in depth. See EC Section. 2/1/08	Needs evaluation
Rimmon Rd	A timbermat crane pad (installed 12/7/07)remains adjacent to/within a tributary stream of Race Brook near structure #24105. 2/1/08	Continue to monitor. 2/1/08	NA
Oak Lane CC, Cow Path Lane, Salem Rd, Rimmon Rd, Brookwood Dr, Center Rd, Ansonia Rd, Manville Rd and Clear	Timber mat crane pads remain within the wetlands in these sections. 2/1/08	Continue to monitor. 2/1/08	NA at this time

Areas of Inspection	Observation	Recommended Action	Corrected Action
Ln to Rte 15			
<b>Bethany, CT</b>	A stone access road and timber mats are in place in the wetland areas in this section. 2/1/08	Continue to monitor. 2/1/08	NA
Morris to Hatfield			
Litchfield Turnpike	Excess sediment has accumulated on the timber mat crossings within the access road here. Sediment has seeped through the mats and into wetlands #119 (near structure #3961), #116 (between structures #3964 and #3965), #115 (between structures #3965 and #3966) and #114 (between structure #3966 and #3967). 2/1/08	Carefully remove sediment from wetland areas when timber mats are removed. See EC Section. 2/1/08	Needs evaluation/attention
<b>Hamden, CT</b>			
West Todd St, Tom Swamp/Arrow Rd, Willow Street, Brooksvale Ave, and Old Lane Rd	Temporary stone access roads and timber mats remain in some of the wetland areas in these sections. 2/1/08	Continue to monitor. 2/1/08	NA at this time
West Todd Street	Sediment remains in the wetland area located to the southwest of structure #3992. 12/20- 2/1/08	Evaluate sediment accumulation within the wetland. Carefully remove sediment from wetland if it is greater than 2” in depth. 2/1/08	Needs attention
Brooksvale Ave	Excess sediment has been removed from the timber mat crossing within the access road here, but sediment had seeped through the mats and into wetland #100. 2/1/08	Carefully remove sediment from wetland areas when timber mats are removed. 2/1/08	Needs evaluation/attention
Old Lane Road	Sediment remains in wetland #94. 10/5-2/1/08	Continue to monitor and add/maintain controls as necessary. Carefully remove sediment from the wetland if it is greater than 2” in depth. See EC	Needs evaluation/attention



Areas of Inspection	Observation	Recommended Action	Corrected Action
115-kV underground transmission line Old Lane Road	Sediment accumulation was evaluated in a portion of the wetland here. Less than 2” of sediment was observed at the catch basin outlet in the wetland across from the overhead access road. (115-kV underground). 2/1/08	Section. 2/1/08  Continue to evaluate sediment accumulation within the adjacent wetland. Carefully remove sediment from the wetland if it is greater than 2’ in depth. 2/1/08	Needs further evaluation
State species of concern, threatened and endangered species.	According to the D&M plan, Wood Turtles are known to occur near the Wepawaug River at Eisenhower Park. 2/1/08	Wood turtles are considered dormant from November 1 <sup>st</sup> to April 1 <sup>st</sup> and therefore will not be disturbed when construction occurs during these months. If active work continues/resumes in this area after April 1st, field crews should receive the appropriate training in the recognition and removal of individual wood turtles from the construction area. “Sweeps should be performed prior to the commencement of construction activities. 2/1/08	NA at this time
Vegetative clearing or stabilization  All active roads (all towns)	Vegetative clearing was noted within the ROW. Most species were invasive and were removed. “Hedgerows”, including cedars and similar short tree species were retained along the ROW where feasible. Select shrubs, especially those adjacent to wetlands, also remain in most areas. 2/1/08  Soils remain exposed as a result of grounding activities. 10/5-2/1/08	Continue to retain appropriate vegetation for stabilization. Retain as much vegetation as possible for screening. Confirm that clearing/cutting is limited only to areas defined in D&M plan. Provide as much buffer as possible for homeowners. 2/1/08  Continue to monitor and stabilize disturbed areas when work is complete and activity will not return within 21 days. Continue	NA          Needs evaluation/attention

Areas of Inspection	Observation	Recommended Action	Corrected Action
Milford and Orange, CT	<p>115 kV crane pad reclamation and restoration work appear complete at this time. Disturbed soils are being graded and mulched for temporary stabilization. 2/1/08</p>	<p>to monitor until stabilization is achieved. 2/1/08</p> <p>Continue to monitor until stabilization is achieved. 2/1/08</p>	<p>Disturbed soils are being graded and mulched for temporary stabilization</p>
	<p>Construction of the wetland mitigation area in Eisenhower Park appears to be complete at this time. Temporary stabilization measures are in place. 2/1/08</p>	<p>Continue to monitor until final stabilization is achieved. 2/1/08</p>	<p>NA</p>
	<p>Equipment ruts have been graded and stabilized with mulch in the wetland near structure #24023. 2/1/08</p>	<p>Continue to monitor until final stabilization is achieved. 2/1/08</p>	<p>NA</p>
	<p>Wood chip piles remain in the ROW off Russell Ave in Orange. 2/1/08</p>	<p>Wood chip piles should be removed from the ROW or spread in appropriate upland areas to a depth of 3" or less. 2/1/08</p>	<p>Needs attention when feasible</p>
Woodbridge, CT	<p>115 kV crane pad reclamation and restoration work continues at this time. Disturbed soils are being graded and mulched for temporary stabilization. 2/1/08</p>	<p>Continue to monitor until stabilization is achieved. 2/1/08</p>	<p>Disturbed soils are being graded and mulched for temporary stabilization</p>
JCC	<p>Hydro-seed was applied to disturbed areas. 2/1/08</p>	<p>Continue to monitor until <i>final stabilization</i> is achieved. Re-seed if necessary. 2/1/08</p>	<p>NA</p>
B'Nai Jacob	<p>Disturbed areas have been seeded and mulched for</p>	<p>Continue to monitor until <i>final stabilization</i> is</p>	<p>NA</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p><b>Bethany and Hamden, CT</b></p> <p>Gaylord Mtn Rd/West Todd St</p> <p>Old Lane Road</p>	<p>temporary stabilization. 2/1/08</p> <p>115 kV crane pad reclamation and restoration work continues at this time. Disturbed soils are being graded and mulched for temporary stabilization. 2/1/08</p> <p>Mulch has been spread in washout areas near structure #3989 in an effort to temporarily stabilize disturbed soils. 2/1/08</p> <p>The overhead access road has been stabilized with stone. Hydroseed was applied to exposed soils. 2/1/08</p>	<p>achieved. Re-seed if necessary. 2/1/08</p> <p>Continue to monitor until <i>final stabilization</i> is achieved. 2/1/08</p> <p>Continue to monitor. Mulched areas should be seeded for further stabilization. Stone fill or similar may be needed to stabilize gullies/ washouts. 2/1/08</p> <p>Continue to monitor until <i>final stabilization</i> is achieved. 2/1/08</p>	<p>Disturbed soils are being graded and mulched for temporary stabilization</p> <p>NA</p> <p>NA</p>
<p>Dewatering</p> <p><b>Milford, CT</b>  Naugatuck Ave,  Caswell St, Plains Rd,  and Oronoque Rd</p> <p><b>Orange, CT  Woodbridge,  Bethany, and  Hamden CT</b></p> <p>Rimmon Rd/B'Nai</p> <p>Rimmon Rd</p>	<p>Dewatering basins remain in place at new and proposed drilling sites in these sections. 2/1/08</p> <p>Dewatering basins remain for 345kV foundation work. 2/1/08</p> <p>A dewatering basin was constructed from a spoil pile near structure #24108 in Woodbridge. Erosion controls have been installed along the perimeter. 2/1/08</p> <p>Dewatering was being performed with dewatering trucks at structure #24105. 2/1/08</p>	<p>Continue to monitor active areas and adjust controls as necessary. 2/1/08</p> <p>Continue to monitor. 2/1/08</p> <p>Continue to monitor and add controls as necessary. 2/1/08</p> <p>Continue to monitor and add controls as necessary. 2/1/08</p>	<p>Dewatering containment areas were installed proactively.</p> <p>NA</p> <p>Erosion controls were installed around the perimeter of the dewatering basin</p> <p>NA</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
Pease Rd	<p>Foundation dewatering is occurring within an upland portion of the ROW here. Filter bags are in place but the haybale perimeter has not yet been installed. The water appears to be contained on the upland portion of the site. 2/1/08</p> <p>Water from foundation drilling (in the Pease Road area) is being pumped to frac tanks, which are then hauled to the ROW off Pease Rd for dewatering. During transportation, a frac tank overflowed releasing slurry onto the Pease Rd ROW access. 1/24/08-. Sediment has been swept from Pease Rd. 2/1/08</p>	<p>Install haybale perimeter. Continue to monitor and add controls as necessary. 2/1/08</p> <p>Contain water within frac tanks during transportation. Evaluate alternate access roads and upland ROW areas for dewatering, as the Pease Road access is fairly steep. Contain and/or remove existing sediment from the access road. Sweep roadway as necessary. 2/1/08</p>	<p>Needs attention</p> <p>Sediment has been swept from Pease Rd</p> <p>Needs further attention/evaluation</p>
Blasting	No blasting is proposed at this time. 2/1/08	None. 2/1/08	NA
<p>Spills, soils and material storage.</p> <p><b>Milford/ Orange, CT</b> West River St</p>	<p>Contractor receiving yard is set up near Shelland St. in Milford. See segment 3 report. 2/1/08</p> <p>A small diesel fuel spill was observed on the timbermat pad near proposed structure #24023. The affected timbermats were removed from the ROW. 2/1/08</p>	<p>In general, store materials and equipment appropriately. Ensure that vehicles are equipped with spill kits. All construction vehicles should be parked at least 100 feet from a wetland or waterbody when feasible. 2/1/08</p> <p>Continue to monitor the wetland area for signs of the spill. In general, proactively check equipment for leaks and use spill control materials when performing maintenance during refueling. 2/1/08</p>	<p>NA</p> <p>Needs evaluation/attention</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
North St (North)	A dozer was observed parked within 100 feet of a wetland in this area. 1/24--2/1/08	In general, all construction vehicles should be parked at least 100 feet from a wetland or waterbody when feasible. Monitor for leaks and remove equipment from wetland areas as soon as possible. 2/1/08	Needs attention
Additional Observations	Non-project related activity was noted within the ROW off Sunset Dr. A trench was dug near the first structure and a pipe appears to have been installed to divert water from an unknown location. 1/18/07-2/1/08	Noted for the record. 1/18/07-2/1/08	NA

**Next likely scheduled inspection:** Thursday February 7, 2007

I have personally examined and am familiar with the information submitted in this document and all attachments and certify that based on reasonable investigation, including my inquiry of those individuals responsible for obtaining the information, the submitted information is true, accurate and complete to the best of my knowledge and belief, and I understand that any false statements made in this document or its attachments may be punishable as a criminal offense in accordance with Section 22a-6 under Section 53a-157 of the Connecticut General Statutes.

**Field Inspector:** Matt Kelly, BSC Group

**Reviewer:** Lee Curtis, BSC Group



Plains Rd (Milford): Erosion is evident along the exposed slopes of the drainage swale located to the south of the East Devon substation.



Russell Ave (Orange): Drilling continues at structure #24058. A pile of wood chips remains in the ROW here and new stone has been added to the tracking pad.



Gaylord Mtn Rd (Hamden): Additional waterbars were installed along the access road in an attempt to control stormwater runoff.



Gaylord Mtn Rd: Additional haybales were added to the sediment basin near structure #3992 to filter stormwater runoff.