Docket No. 272 - Development and Management Plan Inspection

The Connecticut Light and Power Company Certificate of Environmental Compatibility and Public Need for the construction of a new 345-kV electric transmission line and associated facilities between Scovill Rock Switching Station in Middletown and Norwalk Substation in Norwalk, Connecticut, including reconstruction of portions of existing 115-kV and 345-kV electric transmission line, the construction of Beseck Switching Station in Wallingford, East Devon Substation in Milford, (and Singer Substation in Bridgeport), modifications at Scovill Rock Switching Station and Norwalk Substation, and the reconfiguration of certain interconnections.

Segment 1b (Royal Oaks Bypass) Inspection

Date: April 2, 2007

Inspector: Matthew Creighton

Location: Segment 1b (Royal Oaks Bypass)

Rainfall: No precipitation was recorded in the week prior to inspection (NOAA data at Meriden, CT).

Areas of Inspection	Observation	Recommended Action	Corrected Action
Access roads and adjacent roadways	Traffic is using the existing ROW entrance off Black Walnut Drive and off Rte 17 across from the PAR shipping/receiving yard in order to access the new section. Sediment tracking was not observed on the roadways. 4/2/07	Continue to monitor construction entrance and clean/sweep roadways as needed. 4/2/07	Not Applicable (NA)
	Timber mats were installed off of Rte 17 to bring equipment onto the site and reduce sediment tracking on the roadway. 4/2/07	Monitor and add controls as needed and continue using timber mats to reduce impacts to wetlands. 4/2/07	Timber mats were used to access ROW off Rte. 17.
Foundation and site construction	Only tree removal, and chipping were occurring along the ROW. No foundation or line construction were underway yet. 4/2/07	Monitor slopes and wetland for erosion and run-off. Add controls as necessary to protect sensitive areas. 4/2/07	NA
Erosion and sediment controls	Clearing is complete; Mulch was added to the steeper slope and much of the root system remains in place to stabilize the soil. 4/2/07	As construction and soil disturbance progress, add controls where needed. 4/2/07	Mulch was added to the steeper slopes.
	Controls were not in place at the pond but the remaining root system	Continue to minimize impacts to the ponds/wetlands and	NA

Areas of Inspection	Observation	Recommended Action	Corrected Action
	stabilize the soil. 4/2/07	install controls where applicable. 4/2/07	
	Ruts from equipment access were noted in the wetland near Rte 17. Mats were not in place in this location to support the equipment. 4/2/07	Add controls at the wetland crossings and extend timber mats into the area to prevent impacts from the equipment. 4/2/07	Needs attention.
	Timber mats were installed to reduce tracking and for equipment storage off Rte. 17 and haybales were placed to filter run-off from the mats. 4/2/07	Continue to monitor and stabilize adjacent areas to avoid sediment tracking and accumulation on the mats. 4/2/07	Haybales and timber mats were installed off Rte. 17.
Inland Wetland and Watercourse encroachment and mitigation	Cutting, skidding, and equipment movement within the ROW has occurred, compacting soils and causing ruts and disturbance in some areas. 4/2/07	Continue to monitor wetlands and add controls as needed when soil is first disturbed. Install/extend mats into the wetlands for vehicle access. 4/2/07	Needs attention.
	Using multiple access points from Rt 17 and Black Walnut Dr. allowed equipment to stay out of the pond within the ROW. Controls were not in place here but roots help stabilize the soil. 4/2/07	Install controls where necessary. Continue to retain as much vegetation as possible in and adjacent to wetlands. 4/2/07	NA at this time. Continue to evaluate.
State species of concern, threatened and endangered species.	According to the D&M plan, state listed species are not located in this work area.	None	NA
Vegetative clearing or stabilization	Clearing along the ROW appears complete. Tree stockpiles along the ROW will have to be removed and taken off site. 4/2/07	Monitor slopes and wetland for erosion and run-off. Continue to retain the appropriate low growing vegetation and species to the extent feasible in accordance with the D&M Plan. 4/2/07	NA.

Areas of Inspection	Observation	Recommended Action	Corrected Action
Dewatering	Dewatering is not being performed at this time. 4/2/07	None	NA
Blasting	No blasting is proposed at this time. 4/2/07	None	NA
Spills, soils and material storage	No spills/drips were found on site. Operators have been advised to use spill controls when working on equipment 4/2/07	Always use spill control materials when working on equipment and during refueling. Replace as needed. 4/2/07	NA
	Spill cleanup materials were available on site. Spill kits move from site to site with equipment. 4/2/07	Continue to use and restock materials as needed. 4/2/07	NA
	Two large drums (55 gallon) one plastic, one metal were located within the ROW. These were not located near wetlands. 3/26-4/2/07	Unclear whether drums were stored as part of the work or were already present in the woods. Continue to store materials and equipment 100 ft from wetlands where feasible. 3/26-4/2/07	NA
Additional Observations	NA	NA	NA

Next likely scheduled	
inspection:	Monday April 9, 2007

I have personally examined and am familiar with the information submitted in this document and all attachments and certify that based on reasonable investigation, including my inquiry of those individuals responsible for obtaining the information, the submitted information is true, accurate and complete to the best of my knowledge and belief, and I understand that any false statements made in this document or its attachments may be punishable as a criminal offense in accordance with Section 22a-6 under Section 53a-157 of the Connecticut General Statutes.

Field Inspector:	Matthew Creighton, BSC Group	
Reviewer:	Diana Walden, BSC Group	



View from the contractor yard, looking across Rte. 17 at the access to the 1b ROW. The access is matted and sediment tracking was not an issue on the roadway.



Ruts were observed from equipment through wetlands near Rte 17. Mats should be installed to support vehicles before they access saturated/wetland areas.



View of the newly cleared ROW looking toward the Black Walnut Dr. area. $\,$



View from the ROW off Black Walnut Dr. Slopes have been mulched to temporarily stabilize the soils.