Individual Station Report

Beacon Falls

CONTENTS: Stakeholder Interview Customer Opinion Survey Parking Inventory & Utilization **Station Condition Inspection** Lease Narrative and Synopsis Station Operations Review **Station Financial Review**



Ν

Α

R

Ε

Ρ

Ο

R

Т

Prepared to Connecticut Department of Transportation

Submitted by Urbitran Associates, Inc.

July 2003

Stakeholder Interview

U	R	В	I	Т	R	Α	Ν	R	Е	Ρ	Ο	R	Т



Prepared to Connecticut Department of Transportation

Submitted by Urbitran Associates, Inc.

Beacon Falls

Beacon Falls is a small station on the Waterbury Branch with a high platform, three shelters, and a state parking lot. The town has no financial interest in the station and spends nothing on it, although they do plow snow from the lot in the winter. There is no lease with the town so there are no requirements by CDOT. At the same time, the First Selectman reported that the town is not happy with the station, and as people are moving in to the community who commute to Norwalk and Stamford, the feeling is that there needs to be more service and better stations on the line. The Town wants a better sheltered waiting area, preferably an enclosed station building.

The Town did not know why a portion of the lot has been partitioned off, and said that they have received customer complaints about parking as a result. Parking is free.

As far as the future, the Town would like to see the lot paved and striped, better lighting, and the construction of a small building, which they would be willing to maintain. They would also like to be able to sublease a concession stand in the building.

Parking Inventory and Utilization

U	R	В	I	т	R	Α	Ν	R	Е	Ρ	0	R	Т



Prepared to Connecticut Department of Transportation

Submitted by Urbitran Associates, Inc.

Beacon Falls

The Beacon Falls Rail Station has a surface lot with 28 spaces. The lot is a small gravel lot. There is what appears to be another portion of what would have been parking for the rail station, but this area has a guardrail fencing it in completely. The lot has 25 daily spaces and 3 handicapped spaces. The usage rate for the lot was 21.4%, all of which was daily parking.

Parking Area Ownership

The State of Connecticut owns the gravel parking area at the Beacon Falls Rail Station. Figure 35 outlines the parking lot location and ownership.

Fee Structure

There is no charge for parking at the Beacon Falls Rail Station.

Table 35 presents specific information on parking at the Beacon Falls Rail Station.

Table 35: Beacon Falls Rail Station Parking Capacity and Utilization

Туре	Capacity	Vehicle Count	Utilization	Ownership
Permit	0	0	N/A	
Daily	25	6	24.0%	
Handicap	3	0	0.0%	state
TOTAL PARKING	28	6	21.4%	

Note: This is a gravel lot with no striped spaces. There is a fenced lot adjacent to the rail station parking area but it does not appear to be available for rail commuter parking.



Figure 35: Beacon Falls Rail Station Parking Map

Station Condition Inspection

U	R	В	I	Т	R	Α	Ν	R	Ε	Ρ	Ο	R	Т



Prepared to Connecticut Department of Transportation

Submitted by Urbitran Associates, Inc.

CONNECTICUT DEPARTMENT OF TRANSPORTATION



CONDITION INSPECTION FOR THE BEACON FALLS STATION

GENERAL RECOMMENDATION 3

PREPARED BY: URBITRAN ASSOCIATES, INC. DATE: 7/3/02

CONN. DEPT OF TRANSPORTATION STATION INSPECTION

INSPECTION RATING SCALE

The following rating scale is used for inspections:

- **1-** Totally deteriorated, or in failed condition.
- **2-** Serious deterioration, or not functioning as originally designed.
- **3-** Minor deterioration, but functioning as originally designed.
- 4- New condition. No deterioration.
- 5- Not applicable.
- 6- Condition and/or existence unknown.

STATION:	Beacon	Falls		
LINE:	Waterbu	ıry		
INSPECTIO	ON DATE:	11-17-01		
INSPECTIC	ON AGENCY /	FIRM:	UA	
INSPECTO	RS: <u>JFS, W\</u>	/, RGW		
WEATHER	: Sunny			

 CONN. DEPT OF TRANSPORTATION

 STATION INSPECTION REPORT

 SHEET
 1
 0F
 19

			PLAT	FOR	N ELE	MEN	Г					CAN	OPY		SUPER- STRUCTURE	FOUN	IDATI	ONS
SPAN NO.	1 RAILING	RAILING PAINT	6 STAIRS	A JOINTS	G TOP OF PLATFORM	9 BENCHES	SIGN / BILLBOARD	& WARNING STRIP	☞ PLATFORM EDGE RUBBING BOARD	B PEDESTRIAN TUNNEL	COLUMNS OVERALL	COLUMN BASE @ PLATFORM	5 ROOF FRAMING ELEMENTS	5 ROOFING MATERIAL	DOUBLE TEE	16	T FOOTING	B EROSION / SCOUR
1	3	2	4	5	3	4	2	3	5	5	5	5	5	5	5	5	5	5
2	3	2	5	3	3	5	5	5	5	5	5	5	5	5	5	5	5	5
3	3	2	5	3	3	5	5	5	5	5	5	5	5	5	5	5	5	5
4	. 3	2	5	1	3	5	5	5	5	5	5	5	5	5	5	5	5	5
Ę	3	2	5	5	3	5	5	5	5	5	5	5	5	5	5	5	5	5
<u> </u>																		
├ ─																		

STATION: <u>Beacon Falls</u> LINE: <u>Waterbury</u> INSPECTION DATE: <u>11-17-01</u>	CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET _ 2 OF _ 19
INSPECTION AGENCY / FIRM: <u>UA</u> INSPECTORS: <u>JFS, WV, RGW</u> WEATHER: <u>Sunny</u>	
PARKING ELEMENTS	
QUADRANT # I	
TYPE OF SURFACE: <u>asphalt x</u> PAVED; OTHER (DESCRIBE)	GRAVEL;DIRT;)
CONDITION OF PAVED SURFACE: 3	
CONDITION OF STRIPING: 1	
CONDITION OF BASIN / DRAINS / ETC: 5 (FOR LOCATION SEE SHEET:)	
SIGNAGE: 2	
FENCE AND GUARDRAIL: 4	
LANDSCAPE: 5	
SIDEWALK: 5	
CURB: 5	
QUADRANT # II	
TYPE OF SURFACE:PAVED; OTHER (DESCRIBE)	GRAVEL;DIRT;)
CONDITION OF PAVED SURFACE: 1	
CONDITION OF STRIPING: 5	
CONDITION OF BASIN / DRAINS / ETC: 5 (FOR LOCATION SEE SHEET:)	
SIGNAGE: 5	
FENCE AND GUARDRAIL: 4	
LANDSCAPE: 2	
SIDEWALK: 5	
CURB: 5	

STATION:	Beacon Falls
LINE:	New Haven-Waterbury Branch
INSPECTION DATE :	February 11, 2002
INSPECTION AGENCY / FIRM:	Parsons Brinckerhoff
INSPECTORS:	Jim Connell & Dave Lang
TIME OF INSPECTION:	A.M.
WEATHER:	Cold & Clear

CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET <u>3</u> OF <u>19</u>

PLATFORM --- LIGHTING

Span Number	Fixture Type	Manufacturer	Model Number	Rating	Support Condition	Estimated Age/Life(y/y)	Visual Condition
n/a	HID-HPS	Holophane	unknown	3	3	• • • • • •	minor deterioration
Remarks	13.6 fc.	tion of the platform					verage
	The platform	relies on a utility	pole mounted f	lood luminaire	located in the	e parking area	
	to illuminate	the platform.					

PLATFORM --- LIGHTING LEVELS (fc)

TRACKS{																		
	see r	emar	ks	see	rema	rks		avg 13.6		see	rema	arks	see	rema	arks	see	rema	arks
					NOR	THB	OUN	D/SO	UTH	BOU	ND F	PLAT	FOF	RM				

Beacon Falls
New Haven-Waterbury Branch
February 11, 2002
Parsons Brinckerhoff
Jim Connell & Dave Lang
A.M.
Cold & Clear

CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET <u>4</u> OF <u>19</u>

PLATFORM ---- SERVICE

Voltage Rating (V)	120/240	Type of 3 phase	connection	Delta	n/a	Wye	n/a
		Method of Entra	nce	Overhead	n/a	Underground	IX
Rating of Main Breaker (A)	100	Origin of Service	Pole	Х	Transformer	n/a	
-		Code Compliant	:	Yes	Х	No	n/a
Quantity of Phases	1	Pole Number	CL&P 7030	Wire Sizes	unk	nown	
		& Street	Railroad Ave				
Remarks:	-						

PLATFORM --- ELECTRICAL SYSTEMS

Electrical Device	Manufacturer	Model Number	Rating	Location	Estimated Age/Life(y/y)	Visual Condition
Main Distribution Panel	Square D	QOC124	3	parking lot	6/ 20	minor deterioration
Main Disconnect Switch	n/a	n/a	n/a	n/a	n/a	n/a
Transformer	n/a	n/a	n/a	n/a	n/a	n/a
Receptacles	unknown	unknown	3	parking lot	6/ 20	minor deterioration
Grounding	unknown	unknown	unknown	unknown	unknown	unknown
Lighting Controls	unknown	unknown	3	parking lot	6/ 20	minor deterioration
Public Telephone	unknown	n/a	n/a	platform	n/a	operational
Station Telephone	n/a	n/a	n/a	n/a	n/a	n/a

Remarks:

STATION: Beacon Falls

CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET _____5___OF ___19___

INSPECTORS: Jim Connell & Dave Lang

DATE: February 11, 2002

STATION PLATFORM --- ELECTRICAL AND LIGHTING SUMMARY

The electrical service is mounted in an outdoor enclosure on the utility pole adjacent to the platform. The enclosure is normally locked, but Metro North Railroad electricians were performing routine maintenance and allowed us access to the panelboard enclosure. The panleboard in the enclosure is in good working condition and is more than adequate for this station platform.

There is one floodlight mounted on the service pole that illuminates the platform. This floodlight maintains 13.6 foot-candles, which is above the minimal platform light levels as recommended by the IESNA.

STATION:	Beacon Falls
LINE:	New Haven - Waterbury Branch
INSPECTION DATE :	February 11, 2002
INSPECTION AGENCY / FIRM:	Parsons Brinckerhoff
INSPECTORS:	D. Lang
TIME OF INSPECTION:	A.M.
WEATHER:	Cold & Clear

CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET <u>6</u> OF <u>19</u>

PLATFORM - PLUMBING

SPAN NO.	GUTTER	DOWNSPOUT/ PIPING	CLEAN-OUTS	SPAN NO.	GUTTER	DOWNSPOUT/ PIPING	CLEAN-OUTS				
	Shelters	Shelters have no gutters or downspouts; shelters have plastic curbed roofs.									

PLATFORM - FIXTURES--N/A

SPAN #:	
MODEL:	
YEAR:	
MANUFACTURER:	
CONDITION:	

SPAN #:	SPAN [#] :
MODEL:	MODEL:
YEAR:	YEAR:
MANUFACTURER:	MANUFACTURER:
CONDITION:	CONDITION:

STATION: Beacon Falls	CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET 7OF9										
INSPECTORS: D. Lang	DATE: Feburary 11, 2002										
STATION MECHANICAL SUMMARY											
There are two small shelters with plastic curbe There is no maintenance required.	ed roofs. There are no gutters or downspouts.										

L

STATION:	Waterbury
LINE	New Haven-Waterbury Branch
INSPECTION DATE:	April 3, 2002
INSPECTION AGENCY/FIRM:	Warren & Panzer Engineers
INSPECTOR:	Josue Garcia/Bosun Ogunnaike
WEATHER:	Good

CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET <u>8 of 19</u>

HAZARDOUS MATERIALS INSPECTION

LEAD-BASED PAINT

Note: The LBP inspection was conducted using an RMD LPA-1 spectrum X-Ray Fluorescence Analyzer (XRF). The Department of Housing and Urban Development (HUD) recommend XRF analysis for inspection of lead in paint. XRF readings were taken of surfaces coated with suspect LBP. The XRF was operated in "Quick Mode" for this project. In Quick Mode, the measurement time is determined by the LPA-1 Analyzer to achieve a 95% confidence measurement compared to an action level (1.0 mg/cm2).

<u>Platform</u>


Surfaces Tested	# of Locations Tested	Lead Presence (>1 mg/cm2)	Rating
Canopy Columns	1	No	4
Gutter	2	No	3
Canopy Deck	1	No	3
Telephone Booth	2	No	3
Platform Warning Strip	4	No	3
Canopy Beams	2	No	4

SUSPECT ASBESTOS-CONTAINING MATERIALS

Listed below are suspect asbestos-containing materials that were observed during a visual inspection. Materials were found to be in good to fair condition. Any future disturbance of these materials should be preceded by the collection of samples and laboratory analysis of these samples. This work must be performed by a certified inspector.

Platform

Suspect Materials	Rating
Platform Seam Caulking	3



STATION: Becon Falls

CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET <u>10</u> OF <u>19</u>

INSPECTORS: JFS, WV, RGW DATE: 11-17-01

	TINGS	РНОТО	REMARKS:							
NEW	PREV	NO.								
2		6	Span I-V 1,2 - The railing paint is rusted and chipped							
1		7	Span IV 4 - The joint is missing and the adjacent concrete							
			is cracked and spalled							
3		8	Span IV 5 - There is spalled concrete on the west side of the							
			ramp.							
2		9	Span I 7 -The sign's lettering is damaged							
2		10	Quad I Surface - There are minor cracks in the surface							
1		5	Quad I Stripping - The striping is faded							
1		5	Quad I Signage - The signs are bent and rusted; one of the							
			handicap signs are missing.							
1		3-4	Quad II Surface - The gravel riding surface is uneven and area							
			are missing with vegetation growing within the							
	_		parking area.							
2		1-4	Quad II Landscape - Generally the vegetation adjacent to							
	-		this area is dead.							
	+									
	+									

Beacon Falls Station				
Description	Units	Quantity	Price / Unit	Total Cost
Replace asphalt pavement				
-Remove asphalt	yd ³	61.00	\$30.00	\$1,830.00
-Remove dirt and gravel	yd ³	843.00	\$30.00	\$25,290.00
-6" asphalt top course and binder course	yd ²	2500.00	\$25.00	\$62,500.00
-7" aggregate base	yd ³	904.00	\$20.00	\$18,080.00
Paint Railing	ft	230.00	\$9.00	\$2,070.00
Repair spalled Concrete	ft ²	2.00	\$40.00	\$80.00
Repair expansion joint	ft	15.00	\$9.00	\$135.00
Mobilization / Demobilization (10%)				\$10,998.50
Sub-total				\$120,983.50
Contingency (20%)				\$24,196.70
Grand Total				\$145,180.20
Say				\$146,000.00

Station Operations Review

U	R	В	I	Т	R	Α	Ν	R	Ε	Ρ	Ο	R	Т



Prepared to Connecticut Department of Transportation

Submitted by Chance Management

Under Contract to Urbitran Associates, Inc.

BEACON FALLS Beacon Falls Station

Town officials indicated that the town does not actively participate in the operations and governance of its station, although they would like to change this situation. The town is developing a Beacon Falls Master Plan. The Master Plan includes moving the station platform from its present location to a place opposite Depot Street where it would be more visible from the bridge. It is anticipated that the Town would use community development funds for this project. This plan would also move the commuter lot from Exit 24 off Route 8 to the present railroad parking lot. The objective would be to create an economic stimulus to the Town through these actions.

Agreements

There is no lease agreement with the Town. However, as mentioned above, town officials indicated that they would like to have more interest and control in the condition and use of the station.

Organizational Structure

Although there is no lease with the town, the Town Engineer, Jim Galigan, indicated that the Town's Department of Public Works removes snow at no charge to the State. The State operates all other aspects of the station and lot.



Town of Beacon Falls Department of Public Works Snow Removal



Operating Procedures

The State maintains the platform area. The Town's Department of Public Works plows the gravel lot, but does not bill the State for this service. The State (Metro-North) shovels the platform.

Procedure	Responsible Party
Opening and Closing of Station	N/A
Housekeeping Inside Station	N/A
Housekeeping Outside Station	N/A
Daily Maintenance	Town DPW State/ Metro-North
Preventative Maintenance	State/ Metro-North
Landscaping	N/A
Security	N/A
Customer Service	N/A
Tenant Performance	N/A
Parking Enforcement	N/A
Parking Fees and Permits	N/A
Parking Operation Maintenance	N/A

Station Financial Review

U	R	В	Т	R	Α	Ν	R	Ε	Ρ	Ο	R	т



Prepared to Connecticut Department of Transportation

Submitted by Seward and Monde

Under Contract to Urbitran Associates, Inc.

BEACON FALLS FINANCES

ACCOUNTING ENTITY / BASIS

There is no separate fund at the State or local level used to manage this property. There is no lease from the State to the Town and parking is free.

FINANCIAL REPORTING TO STATE

There is no financial reporting to the State by the Town because there is no lease and the parking operations are handle directly by the State. The property is maintained primarily through Metro-North contracted services (see below).

REVENUES

The State does not charge for parking therefore no revenues are derived other than advertising (if any) at the platforms would be received through the Metro-North service agreement.

EXPENSES

The Town 's Public Works Department plows the area at its own expense.

Metro-North and ConnDOT – The State also incurs station expenses through its service agreement with Metro-North / Metropolitan Transit Authority. These expenses are accounted for by Metro-North and included in the charge to the State. The expenses generally relate to maintaining the platform at each station. Metro-North performs cyclical maintenance and on-call repairs and maintenance as needed. Metro-North is also responsible to maintain any ticketing area on railroad property. Such costs have been identified and included in the financial presentation.

The Metro-North service agreement also provides that the State pay for the allocated cost of station maintenance forces. These allocated indirect costs have not been included in the financial presentation.

The local government is not in direct control of the services rendered by Metro-North. These services are controlled by the service agreement. The service agreement is outside of any arrangement or agreement with the local government

ConnDOT also incurs indirect expense for its administrative oversight of the railroad property. These expenses were not compiled or presented in the financial presentation.

FINANCIAL PRESENTATION IN COMPARISON TO THE PARKING INVENTORY

A parking inventory and utilization report is presented separately as Task 2 in this study. Since all railroad parking is free, there is currently no financial reporting to the State. The finances shown herein are the State's cost for Metro-North general maintenance of the platforms as previously explained. The parking inventory covers only the 28 spaces owned by the State.

BEACON FALLS RAILROAD STATION AND PARKING OPERATIONS

	OPE	RATING AGREE	YEAR 1996 EMENTS			OPER	ATING AGRE	YEAR 1997 EEMENTS		
<u>REVENUES</u>	LOCAL G	OV'T METR	RO-NORTH	TOTAL	<u>%</u>	LOCAL G	OV'T MET	<u>ro-north</u>	TOTAL	<u>%</u>
PARKING RENTS INVESTED FUNDS OTHER	\$	- \$ - -	- \$ - - -	- - -	0.0% 0.0%	\$	- \$ - -	- \$ - - -	- - -	0.0% 0.0% 0.0% 0.0%
	\$	- \$	- \$	-	0.0%	\$	- \$	- \$	-	0.0%
STATION, PLATFORMS AND PARKING EXPENSES REPAIRS AND MAINTENANCE UTILITIES RENT SECURITY INSURANCE AND CLAIMS GENERALLY CLASSIFIED EXPENSES (INCLUDING UNSPECIFIED DIRECT, -INDIRECT, - ADMINISTRATIVE, -AND GENERAL ALLOCATIONS) CONNECTICUT SALES TAX	\$	- \$ - - - -	1,602 \$ - - - 634 -	1,602 - - - 634 -	71.6% 0.0% 0.0% 0.0% 28.4% 0.0%	\$	- \$ - - - -	3,419 \$ - - 1,032	3,419 - - - 1,032 -	76.8% 0.0% 0.0% 0.0% 23.2% 0.0%
	\$	- \$	2,236 \$	2,236	100.0%	\$	- \$	4,451 \$	4,451	100.0%
<u>NET PROFIT (LOSS)</u>	\$	- \$	(2,236) \$	(2,236)		\$	- \$	(4,451) \$	(4,451)	

LOCAL GOVERNMENT'S RAILROAD FUND

ACCUMULATED SURPLUS (DEFICIT) LESS - LOCAL GOVERNMENT'S SHARE	\$ - -	\$
NET AVAILABLE RAILROAD FUND SURPLUS (DEFICIT)	FREE LOTS NO LEASE, NO FUND	FREE LOTS NO LEASE, NO FUND
STATE'S AVAILABLE SHARE @ 50%	FREE LOTS NO LEASE, NO FUND	FREE LOTS NO LEASE, NO FUND

BEACON FALLS RAILROAD STATION AND PARKING OPERATIONS

	OPE	RATING AGI	YEAR 199 REEMENTS	98			OPEF	RATING	YEAR 19 AGREEMENTS	99	
REVENUES	LOCAL	GOV'T MI	ETRO-NORTH	I	OTAL	<u>%</u>	LOCAL C	OV'T	METRO-NORTH	TOTAL	<u>%</u>
PARKING RENTS INVESTED FUNDS OTHER	\$	- \$ - -	- - -	\$	- - -	0.0% 0.0% 0.0% 0.0%	\$	- - -	\$ - - - -	\$ - - - -	0.0% 0.0% 0.0% 0.0%
	\$	- \$	-	\$	-	0.0%	\$	-	\$ -	\$-	0.0%
STATION, PLATFORMS AND PARKING EXPENSES REPAIRS AND MAINTENANCE UTILITIES RENT SECURITY INSURANCE AND CLAIMS GENERALLY CLASSIFIED EXPENSES (INCLUDING UNSPECIFIED DIRECT, -INDIRECT, -ADMINISTRATIVE, -AND GENERAL ALLOCATIONS) CONNECTICUT SALES TAX	\$	- \$ - - - -	1,419 - - - 138 -	\$	1,419 - - - - 138 -	91.1% 0.0% 0.0% 0.0% 8.9% 0.0%	\$	-	\$ 1,200 - - - - -	\$ 1,200 - - - - -	100.0% 0.0% 0.0% 0.0% 0.0%
	\$	- \$	1,557	\$	1,557	100.0%	\$	-	\$ 1,200	\$ 1,200	100.0%
NET PROFIT (LOSS)	\$	- \$	(1,557)	\$	(1,557)		\$	-	\$ (1,200)	\$ (1,200)	

LOCAL GOVERNMENT'S RAILROAD FUND

ACCUMULATED SURPLUS (DEFICIT) LESS - LOCAL GOVERNMENT'S SHARE	\$ - -	\$ - -
NET AVAILABLE RAILROAD FUND SURPLUS (DEFICIT)	FREE LOTS NO LEASE, NO FUND	FREE LOTS NO LEASE, NO FUND
STATE'S AVAILABLE SHARE @ 50%	FREE LOTS NO LEASE, NO FUND	FREE LOTS NO LEASE, NO FUND

	YEAR 2000						
	OPERATING AGREEMENTS						
REVENUES	LOCAL	GOV'T	METE	RO-NORTH		TOTAL	<u>%</u>
PARKING	\$	-	\$	-	\$	-	0.0%
RENTS		-		-		-	0.0%
INVESTED FUNDS		-		-		-	0.0%
OTHER		-		-		-	0.0%
	\$	-	\$	-	\$		0.0%
STATION, PLATFORMS AND PARKING EXPENSES REPAIRS AND MAINTENANCE UTILITIES RENT SECURITY INSURANCE AND CLAIMS	\$	- - -	\$	2,332 - - - -	\$	2,332 - - - -	98.6% 0.0% 0.0% 0.0% 0.0%
GENERALLY CLASSIFIED EXPENSES (INCLUDING UNSPECIFIED DIRECT, -INDIRECT, - ADMINISTRATIVE, -AND GENERAL ALLOCATIONS) CONNECTICUT SALES TAX	-	-		32		32	1.4% 0.0%
	\$	-	\$	2,364	\$	2,364	100.0%
NET PROFIT (LOSS)	\$	-	\$	(2,364)	\$	(2,364)	

LOCAL GOVERNMENT'S RAILROAD FUND

ACCUMULATED SURPLUS (DEFICIT) LESS - LOCAL GOVERNMENT'S SHARE	\$ - -
NET AVAILABLE RAILROAD FUND SURPLUS (DEFICIT)	FREE LOTS NO LEASE, NO FUND
STATE'S AVAILABLE SHARE @ 50%	FREE LOTS NO LEASE, NO FUND

Traffic and Transportation

Bridge and Civil Engineering

Architecture

Parking Services

Construction Inspection

Environmental Services

Transit Services

Structural Engineering

U R B I T R A N <mark>R E P O R T</mark>

71 West 23rd Street New York, New York 10010 212.366.6200 Fax 212.366.6214

12 West 27th Street, 12th FLoor New York, NY 10001 212.366.6200 Fax 646.424.0835

New Jersey 2 Ethel Road - Suite 205B Edison, New Jersey 08817 732.248.5422 Fax 732.248.5424

150 River Road, Building E Montville, NJ 07045 973.299.2910 Fax 973.299.0347

Connecticut 50 Union Avenue Union Station, Third Floor East New Haven, CT 06519 203.789.9977 Fax 203.789.8809

California 1440 Broadway, Suite 500 Oakland, CA 94612 510.839.0810 Fax 510.839.0854

Massachusetts 275 Southampton Road Holyoke, MA 01040 413.539.9005

Albany 6 Meadowlark Drive Cohoes, NY 12047 P.O.Box 524 518.235.8429