Individual Station Report

Old Greenwich

CONTENTS:

Stakeholder Interview

Customer Opinion Survey

Parking Inventory & Utilization

Station Condition Inspection

Lease Narrative and Synopsis

Station Operations Review

Station Financial Review



Prepared to

Connecticut Department of Transportation

Submitted by

Urbitran Associates, Inc.

July 2003

Customer Opinion Survey

URBITRANREPORT



Prepared to

Connecticut Department of Transportation

Submitted by

Urbitran Associates, Inc.

Old Greenwich

The Old Greenwich Station also had a high survey distribution (400), and a fairly strong response rate of 24%. The percentage of customers who traveled daily by train was 84%, while 7% traveled at least once a week, 6% at least once a month, and 3% less often. Seven percent of respondents also indicated travel purposes other than commuting or other business, and notably 11% traveled during the off-peak periods.

Of those who parked at the station, 83% held a permit at the time of the survey and only 29% of those who did not hold a permit were on a waiting list. Roughly two-thirds of the survey population at Old Greenwich were male and 89% of all respondents were between 25 and 64 years old. At this station there was a slightly higher percentage of passengers over age 65 (10%). And, not surprisingly, customers' incomes fell largely in the upper ranges. Sixty-eight percent reported incomes over \$100,000 and nearly 30% were between \$50,000 and \$75,000.

Regarding customer ratings of the station elements, Old Greenwich was painted in a fairly positive light, with a notably higher number of 'excellent' ratings. Areas of concern did exist, although only 8 of the 39 elements surveyed received a majority of 'fair' or 'poor' ratings.

The parking facilities were generally rated favorably, and the three highest rated among these were the pavement condition, lot maintenance, and entrances. Conversely, four areas were rated negatively by over half of respondents, including the underpass, ease of car of bus drop-off, and most notably, lighting and security. Figure 160 shows the ratings of parking elements in Old Greenwich. The highest rated element (parking lot pavement condition) received 88% positive marks. The lowest rated element (parking security) had 55% negative ratings. Handicap accessibility had a majority of positive ratings but received the lowest number of actual favorable marks (10). Old Greenwich does not have an overpass.




Figure 160: Old Greenwich Station Parking Ratings

Only one aspect of the station building was rated poorly: the restrooms. The remaining station items surveyed were rated favorably, notably the absence of graffiti and the availability of maps and schedules. Figure 161 shows the ratings for all the station building elements in Old Greenwich. As with most stations, absence of graffiti was the highest rated station building element with 92% favorable ratings. Restrooms received the highest percentage of negative marks (52%) and handicap accessibility received the lowest number of actual positive marks (30). Sixty-nine percent of respondents were pleased with the overall condition of the building.




Figure 161: Old Greenwich Station Building Ratings

The station amenities received mixed reviews, although overall ratings were positive. Figure 162 displays the amenities ratings in Old Greenwich. The highest rated amenities were the news/magazine stand and the availability of trash containers. The highest rated element (news/magazine stand) received 81% positive ratings. Conversely, more than half of respondents gave poor ratings to the taxi stand and the bus drop-off/pick-up. Eighty-six percent of respondents were dissatisfied with the condition of the taxi stand.




Figure 162: Old Greenwich Station Amenities Ratings

Finally, the platform at Old Greenwich was rated favorably for the most part, with the exception once again of the shelters, for which 59% of respondents gave 'fair' or 'poor' ratings. However, overall condition, lighting, cleanliness, and maintenance of the platform were all rated highly. Eighty-eight percent of respondents were pleased with the overall condition of the platform. Figure 163 outlines the platform ratings in Old Greenwich.




Figure 163: Old Greenwich Station Platform Ratings

Using the results from the most recent Metro-North survey and the results of this survey, similar trends become apparent. Ratings from the 2 surveys were very similar (all within 10 percentage

points of each other). Following the standard trend on the New Haven Line, Metro-North respondents rated station and parking conditions higher than respondents to this survey and respondents to this survey rated platform conditions higher than Metro-North respondents. The exception in Old Greenwich was with the public address system where 64% of respondents were satisfied in both surveys.

Change

The change ratings in Old Greenwich were generally lower than the ratings of the current situation. Ten of the 39 elements had a majority of 'worsened' ratings. Six of the elements had the respondents split exactly in half over whether there had been an improvement or a worsening.

Figure 164 describes the change situation in Old Greenwich. Parking lot pavement condition was thought to have improved the most with 91% improvement ratings. At the other end, the underpass was the least improved element with 64% 'worsened' ratings. Four parking elements had a majority of 'worsened' ratings.



Figure 164: Old Greenwich Station Change in Parking Conditions

As with the current situation ratings, building change ratings were higher than parking change ratings. However, building change ratings were lower than building current situation ratings. Figure 165 shows the building change ratings for Old Greenwich. One hundred percent of respondents thought that map and schedule availability had improved during the previous 2 years. Security, lighting and graffiti absence were also highly rated. Unfortunately, 3 elements including the overall condition of the station were thought to have worsened by a majority of respondents. Fifty-four percent of respondents said the overall station condition had worsened. However, the two least improved elements (restrooms and building maintenance) only performed slightly worse than the overall condition with 55% 'worsened' ratings.




Figure 165: Old Greenwich Station Change in Building Conditions

Amenities change ratings were worse than change ratings for the building and for the parking but better than ratings of the current amenities situation. Figure 166 shows the amenities change ratings for Old Greenwich. Only 1 amenity (taxi stand) had a majority of 'worsened' marks with 78% of respondents saying that the condition had worsened during the previous 2 years. As was the case with several stations, availability of trash containers was the most improved amenity with 80% improvement ratings.




Figure 166: Old Greenwich Station Change in Amenities Conditions

Figure 167 displays how Old Greenwich respondents felt about the trend over the previous 2 years of the platform. Current platform ratings were pretty high but the platform change ratings were lower. Still, only 1 element (shelters) was thought to have worsened by a majority (60%) of respondents. The same situation was found in several other stations. Sixty-seven percent of respondents were pleased with the improvement in the overall platform. The most improved platform element was the lighting with 83% improvement ratings.




Figure 167: Old Greenwich Station Change in Platform Conditions

When looking at all the element categories together with regard to change, many elements are in serious need of improvement, but 3 elements stand out the most. Elements with 40% or fewer improvement ratings were: underpass, taxi stand, and shelters, and require attention.

Responsible Agencies

Old Greenwich respondents were generally under the impression that Metro-North was responsible for all of the station elements expect for parking. Figure 168 shows who respondents thought were responsible for which conditions in Old Greenwich. The following results show the major trends in responsibility as seen through the eyes of the respondents:

- The majority of respondents (63%) said the local municipality was in charge of parking.
- Most (45%) respondents thought Metro-North was responsible for the station building, but significant percentages also thought it was Connecticut DOT (20%) and the local municipality (18%).
- The majority (66%) of respondents thought that Metro-North had responsibility for the platform.
- Almost a majority (49%) of respondents said Metro-North was in charge of lighting. Seventeen percent of respondents thought that each Connecticut DOT and the local municipality were in charge of lighting and did not know who the responsible party was.
- Respondents were generally fairly evenly split between all 4 choices when
 deciding who they thought was responsible for security in Old Greenwich. Thirtyseven percent said it was Metro-North, as did 28% for local municipality and
 17% for each Connecticut DOT and not knowing.
- The vast majority (82%) of respondents said that Metro-North was responsible for the availability of maps and schedules.




Figure 168: Old Greenwich Station – Responsible Agencies

Written-In Customer Comments

Table 17 lists all of the customer comments written-in on the survey. The highest percentage of respondents (16%) noted the need for more parking, as did most customers who wrote in comments on the New Haven Line. In the element rating section, 70% of respondents were pleased with the current parking availability situation and only 45% said they had noticed improvement during the previous 2 years. Eleven percent of respondents commented on the need for improving lighting. Parking lighting was generally thought to have improved the least of parking, building, and platform lighting change ratings.




Figure 168: Old Greenwich Station – Responsible Agencies

Written-In Customer Comments

Table 17 lists all of the customer comments written-in on the survey. The highest percentage of respondents (16%) noted the need for more parking, as did most customers who wrote in comments on the New Haven Line. In the element rating section, 70% of respondents were pleased with the current parking availability situation and only 45% said they had noticed improvement during the previous 2 years. Eleven percent of respondents commented on the need for improving lighting. Parking lighting was generally thought to have improved the least of parking, building, and platform lighting change ratings.

Table 17: Old Greenwich Station – Written-In Customer Comments

Comment Code	Comment	# Responses	%
18	Need more parking areas	7	15.6%
10	Lighting needs improvement	5	11.1%
1	Another over/underpass needed	3	6.7%
14	Drop-off and pick-up areas need to be changed	3	6.7%
44	Parking too expensive	3	6.7%
49	Overall good comments	3	6.7%
7	Long wait on parking list	2	4.4%
12	Could use benches & protected shelters from rain/snow with heat/air	2	4.4%
22	Cleaner trains	2	4.4%
54	Interior of Old Greenwich could be updated	2	4.4%
24	Cleaner platforms	1	2.2%
27	Trash cans needed	1	2.2%
32	Many parking permit spaces empty	1	2.2%
57	Free shuttle	1	2.2%
59	Trains in terrible condition	1	2.2%
61	Better public address system needed	1	2.2%
63	Snow removal on stairs & walkways	1	2.2%
66	Lot needs to be paved	1	2.2%
68	Cleaner restrooms on trains and in stations	1	2.2%
75	Permit parking - allow day parking after certain hour	1	2.2%
82	Bring back coffee stands	1	2.2%
85	Only residents should be allowed parking permits	1	2.2%
88	Better signage	1	2.2%
	Total Comments	45	100.0%

Parking Inventory and Utilization

URBITRANREPORT



Prepared to

Connecticut Department of Transportation

Submitted by

Urbitran Associates, Inc.

Old Greenwich

Three parking lots serve rail commuters in Old Greenwich providing 578 parking spaces. Lots 1 (291 spaces) and 3 (181) provide permit and daily parking for 472 commuters. Lot 1 has 2 spaces designated as handicap. Lot 2 is used solely for permit parking with 106 spaces, of which 2 are designated for handicap use.

Overall, parking utilization exceeded 90%. Lot 2 exceeded capacity due to cars parking illegally. The parking capacity and utilization details are shown in Table 18.

Parking Area Ownership

Lots 1 and 2 are owned by the State of Connecticut. The street parking area north of Lot 1 is owned by the City of Greenwich. The City also owns Lot 3. The State owns 68.7% of the commuter parking at the Old Greenwich Station. Figure 18 displays the location and ownership of the lots.

Fee Structure

Parking fees for the Old Greenwich Station include an annual permit fee of \$200 and a \$5.00 daily fee. The waiting list for a permit currently houses 69 people, but it is speculated that the list will be eliminated by the end of 2002. The Greenwich Station sells 1015 permits annually, an over-sale ratio of over 100%.

Table 18: Old Greenwich Rail Station Parking Capacity and Utilization

Location	Capacity	Vehicle Count	Utilization	Ownership
Lot 1				
Permit	264	242	91.7%	
Daily	25	19	76.0%	state
Handicap	2	1	50.0%	
Total Lot 1	291	262	90.0%	
Eastbound Lot 2				
Permit*	104	106	101.9%	
Daily	0	0	N/A	state
Handicap	2	1	50.0%	
Total Lot 2	106	107	100.9%	
Lot 3 Lower Level				
Permit	138	122	88.4%	
Daily	43	41	95.3%	municipality
Handicap	0	0	N/A	
Total Lot 3	181	163	90.1%	
Permit	506	470	92.9%	state
Daily	68	60	88.2%	397
Handicap	4	2	50.0%	municipality
TOTAL PARKING	578	532	92.0%	181

^{*}Spaces in use exceed capacity for permit parking due to 2 cars parked illegally.



Figure 18: Old Greenwich Rail Station Parking Map

Station Condition Inspection

URBITRANREPORT



Prepared to

Connecticut Department of Transportation

Submitted by

Urbitran Associates, Inc.

CONNECTICUT DEPARTMENT OF TRANSPORTATION



CONDITION INSPECTION FOR THE OLD GREENWICH STATION

GENERAL RECOMMENDATION 3

PREPARED BY: URBITRAN ASSOCIATES, INC.

DATE: 11/22/02

CONN. DEPT OF TRANSPORTATION STATION INSPECTION

INSPECTION RATING SCALE

The following rating scale is used for inspections:

- **1-** Totally deteriorated, or in failed condition.
- **2-** Serious deterioration, or not functioning as originally designed.
- **3-** Minor deterioration, but functioning as originally designed.
- **4-** New condition. No deterioration.
- **5-** Not applicable.
- **6-** Condition and/or existence unknown.

STATION: _	Old G	Greenwich			CONN. DE	PT OF TRA	NSPORT.	ATION	
LINE:	New	Haven			STATION I	NSPECTIO	N REPOR	₹T	
INSPECTION	N DATE:	1/26/02			SHEET	1	OF	52	
INSPECTION	N AGENC	Y / FIRM:	UA						
INSPECTOR	S:	RGW		•					
WEATHER:		Sunny, 40's							

(Southbound) North Platform

			PLAT	FOR	M ELE	MEN	Τ					CAN	YAC		SUPER- STRUCTURE	FOUN	IDATI	ONS
SPAN NO.	ع RAILING	& RAILING PAINT	ω STAIRS	SLNIOF 4	9 TOP OF PLATFORM	9 BENCHES	4 SIGN / BILLBOARD	∞ WARNING STRIP	Φ PLATFORM EDGE RUBBING BOARD	5 PEDESTRIAN TUNNEL	COLUMNS OVERALL	COLUMN BASE @ PLATFORM	ROOF FRAMING ELEMENTS	ROOFING MATERIAL	15 DOUBLE TEE	16	POOTING 17	8 EROSION / SCOUR
I	2	2	5	3	3	5	3	3	5	5	5	5	5	5	3	5	3	3
П	3	2	3	3	3	5	3	3	5	5	5	5	5	5	3	3	3	3
III	3	2	5	3	3	5	3	3	5	5	5	5	5	5	3	5	3	3
IV	3	2	5	3	3	5	3	3	5	5	5	5	5	5	3	5	3	3
V	3	2	3	3	3	5	3	3	5	5	5	5	5	5	3	3	3	3
VI	3	2	5	3	3	5	3	3	5	5	3	3	3	3	3	5	3	3
VII	2	2	3	3	3	3	3	3	5	5	3	3	3	3	3	3	3	3
VIII	2	2	3	3	3	5	3	3	5	5	3	3	3	3	3	3	3	3
IX	3	2	5	3	3	5	2	3	5	5	3	3	3	3	3	5	3	3
Χ	3	2	5	3	3	3	3	3	5	5	3	3	3	3	3	5	3	3
XI	3	2	5	3	3	5	3	3	5	5	3	3	3	3	3	5	3	3
XII	3	2	3	3	3	5	3	3	5	5	5	5	5	5	3	3	3	3
XIII	2	2	5	5	3	5	3	3	5	5	5	5	5	5	3	5	3	3
		<u> </u>			<u> </u>													

STATION: _	Old Gr	eenwich			CONN. DE	PT OF	ΓRAN	SPORT	ATION	
LINE:	New H	aven			STATION I	NSPEC	TION	REPOR	₹T	
INSPECTION	N DATE:	1/26/02			SHEET	2		OF	52	
INSPECTION	N AGENCY	/	UA	_						
INSPECTOR	S: R	.GW		=						
WEATHER:	S	unny, 40's	<u></u>							

(Northbound) South Platform

			PLAT	FOR	M ELE	MEN	Т					CAN	OPY		SUPER- STRUCTURE	FOUN	IDATI	ONS
SPAN NO.	- RAILING	A RAILING PAINT	ω STAIRS	SLNIOF 4	9 TOP OF PLATFORM	9 BENCHES	4 SIGN / BILLBOARD	∞ WARNING STRIP	♥ PLATFORM EDGE RUBBING BOARD	5 PEDESTRIAN TUNNEL	COLUMNS OVERALL	COLUMN BASE @ PLATFORM	ROOF FRAMING ELEMENTS	ROOFING MATERIAL	DOUBLE TEE	16	5 FOOTING	8 EROSION / SCOUR
ı	3	2	3	3	3	3	3	3	5	5	5	5	5	5	3	3	3	3
П	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
III	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
IV	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
V	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
VI	3	2	5	3	3	5	3	3	5	5	5	5	5	5	3	5	3	3
VII	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
VIII	3	2	3	3	3	5	3	3	5	5	5	5	5	5	3	3	3	3
IX	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
Х	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
ΧI	3	2	5	3	3	3	3	3	5	5	5	5	5	5	3	5	3	3
XII	3	2	3	3	3	3	3	3	5	5	5	5	5	5	3	3	3	3
XIII	3	2	5	5	3	3	3	3	5	5	5	5	5	5	3	5	3	3

STATION: Old Greenwich LINE: New Haven		T OF TRANSPOR	
INSPECTION DATE: 11-30-01	SHEET	3 OF	52
INSPECTION AGENCY / FIRM: UA	_		
INSPECTORS: JFS, RGW	_		
WEATHER: 50's			
WEATHER. 303			
BUILDING ELEMENTS			
INTERIOR ELEMENTS			
19. FLOOR: 3			
20. CEILING: 3			
21. WINDOWS: 5			
22. DOORS: 3			
23. FINISH: 3			
24. HARDWARE: 3			
EXTERIOR ELEMENTS			
25. DOORS: 3			
26. WINDOWS: 3			
27. FACADE / FINISH: 3			
28. FOUNDATION: 3			
29. SETTLEMENT: 3			
30. ROOF: 3			
31. RAMP: 5			
32. SIDEWALK: 5			
33. HARDWARE: 3			
34. CURB: 5			
REMARKS:			
1. Roof show signs of deterioration; 3-5 yr life; roof shingles random locations.	s are starting to	buckle in	
2. The exterior paint is starting to chip and peel; there are is	solated areas v	where the wood	
façade is cracked.			
3. There is a gap between the top of the south east door ar	nd the door fran	ne.	

STATION: Old Greenwich	CONN. DEPT OF TRANSPORTATION
LINE: New Haven	STATION INSPECTION REPORT
INSPECTION DATE: 1/26/02	SHEET <u>4</u> OF <u>52</u>
INSPECTION AGENCY / FIRM: UA	_
INSPECTORS: RGW	
WEATHER: Sunny, 40's	
PARKING ELEMENTS	
QUADRANT # I	
TYPE OF SURFACE: asphalt x PAVED; OTHER (DESCRIBE)	GRAVEL;DIRT;
OTTER(DECORDE)	
CONDITION OF PAVED SURFACE: 2	
CONDITION OF STRIPING: 3	
CONDITION OF BASIN / DRAINS / ETC: 5 (FOR LOCATION SEE SHEET:)	
SIGNAGE: 3	
FENCE AND GUARDRAIL: 2	
LANDSCAPE: 3	
SIDEWALK: 2	
CURB: 2	
QUADRANT # II	
TYPE OF SURFACE: asphalt x PAVED; OTHER (DESCRIBE)	GRAVEL;DIRT;
CONDITION OF PAVED SURFACE: 2	
CONDITION OF STRIPING: 3	
CONDITION OF BASIN / DRAINS / ETC: 3 (FOR LOCATION SEE SHEET: see sketch)	
SIGNAGE: 3	
FENCE AND GUARDRAIL: 5	
LANDSCAPE: 3	
SIDEWALK: 5	
CURB: 2	

STATION:	CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET 5 OF 52
WEATHER: Sunny, 40's PARKING ELEMENTS	
TYPE OF SURFACE: asphalt x PAVED; OTHER (DESCRIBE)	_GRAVEL;DIRT;
CONDITION OF PAVED SURFACE: 3	
CONDITION OF STRIPING: 3	
CONDITION OF BASIN / DRAINS / ETC: 3 (FOR LOCATION SEE SHEET: see sketch)	
SIGNAGE: 3	
FENCE AND GUARDRAIL: 3	
LANDSCAPE: 3	
SIDEWALK: 3	
CURB: 2	
QUADRANT# IV	
TYPE OF SURFACE: asphalt x PAVED; OTHER (DESCRIBE)	_GRAVEL;DIRT;
CONDITION OF PAVED SURFACE:3	
CONDITION OF STRIPING: 3	
CONDITION OF BASIN / DRAINS / ETC: 3 (FOR LOCATION SEE SHEET: see sketch)	
SIGNAGE: 3	
FENCE AND GUARDRAIL: 3	
LANDSCAPE: 3	
SIDEWALK: 3	

CURB:

3

STATION:	Old Greenwich	CONN. D	EPT OF	TRAN	ISPORTATIO	NC
LINE:	New Haven	STATION	INSPE	CTION	REPORT	
INSPECTION DATE:	January 9, 2002	SHEET	6	OF	52	
INSPECTION AGENCY / FIRM:	Parsons Brinckerhoff	_				
INSPECTORS:	Jim Connell & Dave Lang					
TIME OF INSPECTION:	A.M.					
WEATHER:	Clear and Cool					

PLATFORM --- LIGHTING

Span Number	Fixture Type	Manufacturer	Model Number	Rating	Support Condition	Estimated Age/Life(y/y)	Visual Condition
all except canopy	HID-MH	Gardco	MA171FM	3	3		minor deterioration
canopy	4 ft fluorescent	unknown	unknown	3	1	18/ 20	minor deterioration

Remarks: A typical section of the platform was measured at the location indicated and found to average 8.47 under the canopy, 13.57 on the southbound platform and 12.8 on the northbound platform.

PLATFORM --- LIGHTING LEVELS (fc)

		ı	NORTHBOUNI	D PLATFORM								
	avg 12.8	see remarks	see remarks	see remarks	see remarks	see remarks						
!												
TRACKS{												
	avg	see remarks	see remarks	avg	see remarks	see remarks						
	13.57			8.47								
		SOUTHBOUND PLATFORM										

STATION:	Old Greenwich	CONN. D	EPT OF	TRAN	SPORTA	ATION
LINE:	New Haven	STATION	INSPE	CTION	REPOR'	Τ
INSPECTION DATE:	January 9, 2002	SHEET	7	_ OF _	52	
INSPECTION AGENCY / FIRM:	Parsons Brinckerhoff	•				
INSPECTORS:	Jim Connell & Dave Lang					
TIME OF INSPECTION:	A.M.					
WEATHER:	Clear and Cool					

PLATFORM --- SERVICE

Voltage Rat	ing (V)							n/a	
			Method of Entrand	æ	Overhead	n/a	Underground	Χ	
Rating of Ma	ain Breaker (A)	see	Origin of Service		Pole	Χ	Transformer	n/a	
		remarks	Code Compliant		Yes	Χ	No	n/a	
Quantity of I	Quantity of Phases 1 Pole Number no number Wire Sizes unknown & Street parking lot								
Remarks:	Remarks: Electrical service to the southbound platform originates from the station building. The northbound								
	platform receives power from a separate utility service. We were unable to gain access to the								
	electrical enclosure	mounted o	on the platform.						

PLATFORM --- ELECTRICAL SYSTEMS

Electrical Device	Manufacturer	Model Number	Rating	Location	Estimated Age/Life(y/y)	Visual Condition
Main Distribution Panel	unknown	unknown	unknown	platform	unknown	unknown
Main Disconnect Switch	n/a	n/a	n/a	n/a	n/a	n/a
Transformer	n/a	n/a	n/a	n/a	n/a	n/a
Receptacles	unknown	unknown	3	platform	15/ 20	minor deterioration
Grounding	unknown	unknown	unknown	unknown	unknown	unknown
Lighting Controls	unknown	unknown	unknown	unknown	unknown	unknown
Public Telephone	unknown	n/a	n/a	adjacent to platform	unknown	operational
Station Telephone	n/a	n/a	n/a	n/a	n/a	n/a

Remarks:			

STATION:	Old Greenwich	CONN. DEPT OF TRANSPORTATION
		STATION INSPECTION REPORT
		SHEET 8 OF 52

INSPECTORS: Jim Connell & Dave Lang DATE: January 9, 2002

STATION PLATFORM --- ELECTRICAL AND LIGHTING SUMMARY

The power to the southbound platform is derived from the station panelboard. The electrical service to the northbound platform terminates in an electrical enclosure mounted on the platform.

Several of the light poles have GFCI type receptacles with two of them missing their covers. We suggest that the receptacle covers be replaced to maintain electrical integrity.

The light poles were in good working condition and maintained an average of 13.57 foot-candles on the southbound platform and an average of 12.8 foot-candles on the northbound platform. The conduits for these light poles are prematurely corroding and will likely need replacement between five to ten years. The heavy use of salt on the platform during winter months may be the cause. The luminaires mounted under the canopy maintained an average of 8.47 foot-candles, but were missing their lenses. Without the lenses, the fixtures are exposed to harsh environmental conditions and do not perform as designed. We suggest that the under canopy luminaires be replaced with appropriate luminaires, as fixture failure is imminent.

INSPECTION A	STATIO LIN ECTION DATE AGENCY / FIR INSPECTOR F INSPECTIOI WEATHE		STAT SHEI	TION IN	ISPEC	CTIO	NSPOR' N REPO 52				
Fixture Type	Manufacture	r	Model Number	Ratin	g Support		Estim Age/Lif		V	isual Co	ndition
chain pendant	unknown	un	known	3	3		18/ 20		mino	or deterio	ration
Exit	unknown	un	known	3	3	1	15/ 20		mino	or deterio	ration
Emergency Egress	unknown	un	known	3	3	,	15/ 20		minc	or deterio	ration
Remarks: A ty	pical section o	f the v	vaiting room	was meas	sured and found	to a	average	8.3 fc	.		
		STA [*]	TION BUILD	ING LI	GHTING LEVE	LS (fc)				
ROOM DESC:	Α	В	С	D	ROOM DESC	C: ⊿Г	Α	E	3	С	D
waiting room					not used	<u>'</u>					
2				avg 8.3		2					
3						3					
4						4					
ROOM DESC:	Α	В	С	D	ROOM DESC	D:	Α	<u> </u>	3	С	D
not used					not used	1					
2						2					
3						3					
4						4					

STATION:	Old Greenwich	CONN. E	EPT OF	TRAN	ISPOR7	ΓΑΤΙΟΝ
LINE:	New Haven	STATION	N INSPE	CTION	REPO	RT
INSPECTION DATE:	January 9, 2002	SHEET	10	OF_	52	
INSPECTION AGENCY / FIRM:	Parsons Brinckerhoff					_
INSPECTORS:	Jim Connell & Dave Lang					
TIME OF INSPECTION:	A.M.					
WEATHER:	Clear and Cool					

STATION BUILDING --- SERVICE

Voltage Rating (V)	120/240	Type of 3 phase of	Delta	n/a	Wye	n/a	
		Method of Entrand	ce	Overhead	Χ	Underground	n/a
Rating of Main Breaker (A)	200	Origin of Service		Pole	Х	Transformer	n/a
		Code Compliant	Yes	Х	No	n/a	
Quantity of Phases	1	Pole Number	no number	Wire Sizes	unk	nown	
		& Street	parking lot				
Remarks:							

STATION BUILDING --- ELECTRICAL SYSTEMS

Electrical Device	Manufacturer	Model	Rating	Location	Estimated	Visual Condition
		Number			Age/Life(y/y)	
Main Distribution	Square D	QBL-34235	3	storage	3/ 20	minor deterioration
Panel				room		
Main Disconnect	Square D	n/a	3	storage	3/ 20	minor deterioration
Switch				room		
Transformer	n/a	n/a	n/a	n/a	n/a	n/a
Receptacles	unknown	unknown	3	throughout	18/ 20	minor deterioration
Grounding	unknown	unknown	unknown	unknown	unknown	unknown
Lighting Controls	unknown	unknown	3	throughout	18/ 20	minor deterioration
Public	unknown	n/a	n/a	on building	n/a	operational
Telephone						
Station	n/a	n/a	n/a	n/a	n/a	n/a
Telephone						
Sub Panel	Murray	LC02DS	3	storage room	2/ 20	minor deterioration

INSPECTION A	LINE: CTION DATE : GENCY / FIRM: INSPECTION: INSPECTION:	Parsons Brin Jim Connell & A.M. Clear and Co	002 ckerhoff & Dave Lang	FIRE ALAR	SI SI	TATION INSPE HEET <u>11</u>	TRANSPORTATION CTION REPORT OF 52
Fire Alarm Device	Manufacturer	Model Number	Rating	Quantity	Location	Estimated Age/Life(y/y)	Visual Condition
Fire Alarm Control Panel	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Heat Detector	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Smoke Detector Pull Station	n/a n/a	n/a n/a	n/a n/a	n/a n/a	n/a n/a	n/a n/a	n/a n/a
Annunciator	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Audio/Visual Device	n/a	n/a	n/a	n/a	n/a	n/a	n/a
		<u>STA</u>	TION BUILD	ING SKET	<u>CHES</u>		

		011555 40 05 50
		STATION INSPECTION REPORT
STATION:	Old Greenwich	CONN. DEPT OF TRANSPORTATION

SHEET 12 OF 52

INSPECTORS: Jim Connell & Dave Lang DATE: January 9, 2002

STATION BUILDING --- ELECTRICAL AND LIGHTING SUMMARY

The electrical panelboards are relatively new; the remaining electrical equipment has minor deterioration.

The waiting room lighting is maintained and is in good working condition with average light levels of 8.3 foot-candles. This value exceeds the minimum light level as recommended by the IESNA. The exit and emergency egress lighting is operational and meets the requirements of NFPA 101.

The building does not have any fire alarm system and, therefore, does not meet NFPA 72 or the ADA requirement of having visual signal devices located in all common spaces.

STATION: Old Greenwich CONN. DEPT OF TRANSPORTATION. LINE: New Haven STATION INSPECTION REPORT INSPECTION DATE: January 9, 2002 SHEET 13 OF NSPECTION AGENCY / FIRM: Parsons Brinckerhoff INSPECTORS: J. Duncan & T. Abrahamson TIME OF INSPECTION: A.M. WEATHER: Clear & Cool

BUILDING -- HVAC - Fire Protection - Ticket Counter and Waiting Area

Weil McLain, boiler probably 35-40 years old Rusted envelop with holes, but still working.

Needs replacement immediately. Breaching with damper in Good Repair

Combustion air openings not in accordance with the code (BOCA International Mechanical Code). BOILER:

WATER HEATER: No water heater No. 2 Oil. Fuel tank approximately **FUEL TYPE:** 200 gallons, there are leaks in fuel supply pipes **HEATING UNIT:** Cast iron old fashion radiators in Good Repair **FUEL TYPE:** N/A **HEATING FILTER:** N/A _____ N/A AC/HEATING UNIT: AC FILTER: N/A DUCTS: N/A # OF DAMPERS: N/A CONDITION OF DAMPERS: N/A THERMOSTATS: Manual thermostat in ticket office - Good Repair NIGHT SET BACK: none For Boiler, Hot water circulating pump, Taco PUMPS: 007-BE 3IW, in operation PIPING: Boiler piping rusted and needs replacement No sprinklers, 2 portable fire extinguishers - 1@10 lb, 1@2.5 lb - Good Repair Fire Protection:

STATION: Old Greenwic	h	CONN. DE	EPT OF	TRANS	SPORTATIO	N
LINE: New Haven		STATION	INSPE	CTION F	REPORT	
INSPECTION DATE: January, 9 20	02	SHEET	14	OF	52	
NSPECTION AGENCY / FIRM: Parsons Bring	kerhoff	_				
INSPECTORS: J. Duncan & T	. Abrahamson					
TIME OF INSPECTION: A.M.						
WEATHER: Clear & Cool						

BUILDING -- HVAC - Fire Protection- Cont.

Ticket Area Waiting Room

- 3 old fashion steel hot water radiators, in good working condition. Piping is in Good Repair.
- 2 ceiling fans in working condition.

Ticket Selling Office

- 1 radiator in Good Repair
- 1 wall air conditioner in acceptable condition
- 1 portable heater used in case of interruption of oil supply in Good Repair.

STATION:	Old Greenwich	CONN. D	EPT OF	TRA	NSPORTATION
LINE:	New Haven	STATION	INSPE	CTIO	N REPORT
INSPECTION DATE:	January 9, 2002	SHEET	15	OF	52
INSPECTION AGENCY / FIRM:	Parsons Brinckerhoff	_			
INSPECTORS:	J. Duncan & T. Abrahamson				
TIME OF INSPECTION:	A.M.				
WEATHER:	Clear & Cool				

PLATFORM - PLUMBING

SPAN NO.	GUTTER	DOWNSPOUT/ PIPING	CLEAN-OUTS	SPAN NO.	GUTTER	DOWNSPOUT/ PIPING	CLEAN-OUTS
110.		7 11 11 10		110.		1(5	
	There is a sh	elter on the Northbou	and side of the trac	ks with alumir	num		
	gutters and m	nissing downspouts.					
All	Platform gutte	ers and downspouts	are in good conditi	on.			

PLATFORM - FIXTURES -- N/A

SPAN ":	SPAN ":	SPAN ":
MODEL:	MODEL:	MODEL:
YEAR:	YEAR:	YEAR:
MANUFACTURER:	MANUFACTURER:	MANUFACTURER:
CONDITION:	CONDITION:	CONDITION:

STATION:	Old Greenwich			CONN. D	EPT OF TE	RANSPOR	RTATION
LINE:	New Haven			STATION	N INSPECT	ION REPO	ORT
INSPECTION DATE:	January 9, 2002			SHEET	16	OF	52
NSPECTION AGENCY / FIRM:	Parsons Brincker	hoff					
INSPECTORS:	J. Duncan & T. A	brahams	on				
TIME OF INSPECTION:							
WEATHER:	Clear & Cool						
	BUILDIN	IG - PLI	UMBING				
<u>RESTROOM</u>							
DIDING: Old			Men's	Room			
PIPING: Old WATER PRESSURE: Norr			2 wall	/floor urinals- fa	air condition		
DRAINS: OK	lai		_	ets - fair conditi			
FAUCET/FIXTURES:				all lavatory - fair			
* MODEL: Unknown				indicapped fixtu			
* YEAR: Unknown				ater conservation			
	Not Determined		Old pi	iping, fixtures, a	ınd etc.		
 CONDITION: Fair cond 	lition			compliance wit			
				t water availabl	е		
				iter heater			
<u>KITCHEN</u>				ng floor drain			
DIDING:			exnau	ıst fan works			
PIPING: WATER PRESSURE:			Mom	en's Room			
DRAINS:				fixtures (no ur	inals)		
FAUCET/FIXTURES:	N/A			conditions	iiiais)		
* MODEL:	14// (Carrio	Containonio			
* YEAR:							
* MANUFACTURER:							
* CONDITION:							
<u>EXTERIOR</u>							
SPRINKLER:							
FAUCET/FIXTURES:							
* MODEL:		N/A					
* YEAR:							
* MANUFACTURER:							
* CONDITION:							

The building has metal gutters and downspouts in good condition.

STATION: Old Greenwich CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT SHEET 17 OF 52

INSPECTORS: J. Duncan, T. Abrahamson DATE: January 9, 2002

STATION - SUMMARY

HVAC

The heating system consists of old cast iron radiators (using circulating hot water) in good condition. A Weil McLain boiler, which is probably over 30 years old, heats hot water. The envelop of the boiler is rusted, even has holes, but it was working at the time of inspection. This boiler is fueled with No. 2 oil. The fuel tank, which holds approximately 200 gallons, shows traces of oil leaks. There is a Taco hot water circulating pump in operation. The system is not up to current code that requires an expansion tank and a floor drain. The piping to the boiler is rusted, not insulated and requires replacement. In the inspectors opinion this system is severely deficient. It may be a hazard and needs to be replaced. In addition the combustion air openings are not in accordance with the code.

Fire Protection

There are no sprinklers in the facility. The station is equipped with two portable fire extinguishers that are 10 lb, and 2.5 lb.

Plumbing

Plumbing fixtures are old and deteriorated. There are no water conservation or handicapped type fixtures. There is no hot water at the lavatories. There is no water heater installed. The entire system should be fitted with new fixtures in conformance with ADA, water conservation and hot water. The new boiler installed should contain a coil for producing domestic hot water or a water heater should be installed.

Storm Drainage, Building and Platform

The building has metal gutters and downspouts that are in good condition. The shelter across the tracks has aluminum gutters but is missing downspouts. The Platform gutters and downspouts are in good condition.

STATION: Old Greenwich

LINE: New Haven-Main Branch

INSPECTION DATE: May 10, 2002

INSPECTION AGENCY/FIRM: Warren & Panzer Engineers

INSPECTORS: Hortense Oliveira

WEATHER: Good

CONN. DEPT OF TRANSPORTATION STATION INSPECTION REPORT

SHEET <u>18</u> OF <u>52</u>

HAZARDOUS MATERIALS INSPECTION

LEAD-BASED PAINT

Note: The LBP inspection was conducted using an RMD LPA-1 spectrum X-Ray Fluorescence Analyzer (XRF). The Department of Housing and Urban Development (HUD) recommend XRF analysis for inspection of lead in paint. XRF readings were taken of surfaces coated with suspect LBP. The XRF was operated in "Quick Mode" for this project. In Quick Mode, the measurement time is determined by the LPA-1 Analyzer to achieve a 95% confidence measurement compared to an action level (1.0 mg/cm2).

Platform

Surfaces Tested	# of Locations Tested	Lead Presence (>1 mg/cm2)	Rating
Canopy Columns	1	No	3
Platform Warning Strip	1	Yes	3

Station Building

Surfaces Tested	# of Locations Tested	Lead Presence (>1 mg/cm2)	Rating
Doors	2	Yes	3
Window Sill/Frame	3	Yes	3
Ext. Wall Columns/Boarders	2	Yes	3
Canopy Support/Deck	2	Yes	3

Surfaces Tested	# of Locations Tested	Lead Presence (>1 mg/cm2)	Rating
Door Frames	1	Yes	3
Ext. Wall	5	No	3
Window Sash	2	No	3
Drain Pipe	1	Yes	3

Lead-Based Paint was found on surfaces noted above. Painted surfaces observed were found to be in fair to good condition. The interior of the building was not accessible at the time of the inspection, therefore any painted surfaces that may be found shall be treated as lead containing until further testing is conducted. Any future disturbance of the lead-based painted surfaces noted above should be abated by an Environmental Protection Agency/Connecticut Abatement Contractor in accordance with the EPA's 40 CFR 745, HUD's 24 CFR Part 35

SUSPECT ASBESTOS-CONTAINING MATERIALS


Listed below are suspect asbestos-containing materials that were observed during a visual inspection. Materials were found to be in fair to good condition. Any future disturbance of these materials should be preceded by the collection of samples and laboratory analysis of these samples. This work must be performed by a certified inspector


<u>Platform</u>

Suspect Materials	Rating
Caulking on Platform Seams	3

Station House

Suspect Materials	Rating
Window Glazing	3
Roof Shingles	3






Urbitran Associates, Inc.

Connecticut Dept. of
Transportation
Old Greenwich Station
General Plan


Date: 1/26/02





NOTES (North-platform):


- 1. The base plates for the double tee are rusted and deteriorated throughout the platform.
- 1. The railing base plates are rusted and deteriorated throughout the platform.



(Northbound) South-Platform

NOTES (South-platform):

- 1. The base plates for the double tee are rusted and deteriorated throughout the platform.
- 2. The railing base plates are rusted and deteriorated throughout the platform.



Urbitran Associates, Inc.


Connecticut Dept. of
Transportation
Old Greenwich Station
Platform Plans

SHEET

20

Date: 1/26/02






NOTES:


- 1. The roofing shingles are buckling in random locations.
- 2. The exterior paint has started to chip and peel; also there are isolated areas where there are cracks in the timber facade.
- 3. There is a gap between the southeast corner door and the door frame.
- 4. The hinge is not aligned correctly and could not be moved.

Urbitran Associates, Inc.

Connecticut Dept. of
Transportation
Old Greenwich Station
Station House Plan

Date: 11/30/01





Pole with Missing Sign

NOTES:


- 1. In the parking area there are $2000'\pm$ of asphalt cracks.
- 2. There are $80'\pm$ of asphalt cracks in the sidewalk.

Urbitran Associates, Inc.

Connecticut Dept. of
Transportation
Old Greenwich Station
Quadrant | Plan

Date: 1/26/02






NOTES:

- 1. Most of the curb is missing throughout this Quadrant.
- 2. In the parking area there are $500'\pm$ of asphalt cracks.

Legend:



♦ Light


Urbitran Associates, Inc.

Connecticut Dept. of Transportation Old Greenwich Station Quadrant II Plan SHEET


23

. 9F

Date: 1/26/02




SHEET



NOTES:

1. In the parking area there are $300'\pm$ of asphalt cracks.



Urbitran Associates, Inc.

Connecticut Dept. of
Transportation
Old Greenwich Station
Quadrant IV Plan
Date: 1/26/02

STATION:	Old Greenwich	CONN. DE	PT OF	TRAN	ISPORT	ATION
		STATION I	NSPE	CTION	REPOR	RT
		SHEET	26	OF	52	

INSPECTORS: RGW, JFS DATE: 1/26/02

RA	TINGS	РНОТО	REMARKS:	
NEW	PREV	NO.		
2		13	Span VII,VIII, XIII (N-platform) 1 - The railing is bent in	
			isolated areas.	
2		14	All Spans 2 - The railing base plate is typically rusted	
			and deteriorated.	
3	+	15	Chan II (NI platform) 2. The congrete stair is shalled in	
		15	Span II (N-platform) 3 - The concrete stair is spalled in isolated areas.	
			Isolaleu aleas.	
3		16	Span VII (S-platform) 5 - There is a crack in one isolated	
			area.	
3		17	Span V, IX, X (N-platform) 5 - The concrete is spalled in	
			Span I,IV (S-platform) isolated areas.	
2		18	Span IX (N-platform) 7 - The sign/billboard post is cracked	
			at the base.	
2	+	19	Span VII (S-platform) NA - The cinder block façade is	
	+	19	damaged.	
			damaged.	
2		20	All Spans NA - The base plates for the double tees are	
			rusted and deteriorated.	
2		21	NA NA - The fence is dislocated from the fence posts.	
3		22	Station House 19 - There is an isolated area where the	
			timber floor finish is deteriorated.	
3		23	Station House 25 - One of the doors does not align	
		20	with the door frame.	
			marate door name.	
3		24	Station House 27 - There are isolated areas where the	
			paint is starting to chip and peel.	
3		25	Station House 27 -There are isolated areas where there	
			are cracks in the timber façade.	

STATION:	Old Greenwich	CONN. DEPT OF TRANSPORTATION
		STATION INSPECTION REPORT
		SHEET 27 OF 52

INSPECTORS: RGW, JFS DATE: 1/26/02

RA ⁻	TINGS	РНОТО	REMARKS:
NEW	PREV	NO.	
3		26	Station House 30 - The roof shingles are showing signs of
			deterioration. They are starting to
			buckle.
3		27	Station House 33 - There is an isolated location where the
			door hinge is not aligned and could not
			be moved.
3		28	Station House NA - The timber platform adjacent to the
			building is cracked in an isolated
			location.
2		29	Quad I Surface - There is an isolated area where the asphalt
			surface is deteriorated.
2		30, 31	Quad I, II Surface - There are areas where the asphalt
			surface is cracked; Also there are areas
			where there is an uneven driving surface
			with cracks.
2		32	Quad I Guardrail - The guardrail is leaning and disconnected
			in multiple locations.
2		33	Quad I Fence - The fence is leaning and rusted
2		34	Quad I Curb - There are multiple locations where the
			concrete curb is spalled.
2		35	Quad I,II,III Curb - There are multiple locations where the
			asphalt curb is displaced, missing, or
			damaged.
2		34	Quad I Sidewalk - The sidewalk is deteriorated in an isolated
			area.
3		36	Quad IV Curb - There is an isolated area where the curb
			is missing.

Old Greenwich Station				
Description	Units	Quantity	Price / Unit	Total Cost
Replacing asphalt sidewalk				
-Remove asphalt (6")	yd ³	5.00	\$22.00	\$110.00
-Installing asphalt (6" layer)	yd ²	30.00	\$25.00	\$750.00
Replacing asphalt pavement (uneven surface, potholes, etc.)				
-Remove asphalt	yd ³	160.00	\$22.00	\$3,520.00
-6" asphalt top course and binder course	yd ²	445.00	\$25.00	\$11,125.00
-7" aggregate base	yd ³	87.00	\$20.00	\$1,740.00
Fill in asphalt cracks	ft	2880.00	\$2.00	\$5,760.00
Replace pedestrian railing	ft	50.00	\$100.00	\$5,000.00
Repair spalled concrete	ft ²	10.00	\$40.00	\$400.00
Replace fencing	ft	285.00	\$48.00	\$13,680.00
Repaint timber	ft ²	1900.00	\$18.00	\$34,200.00
Remove curb	yd ³	400.00	\$80.00	\$32,000.00
Install curb	ft	1600.00	\$22.00	\$35,200.00
Install new guardrail	ft	40.00	\$24.00	\$960.00
Misc. (shingles, signs, etc.)	LS	-	-	\$10,000.00
Misc. (paint and clean structural steel)	LS	-	-	\$2,000.00
Heating Renovations	LS	-	-	\$17,000.00
Plumbing made ADA compliant	LS	-	-	\$10,000.00
Installing shelter downspouts	LS	-	-	\$300.00
Install a minimal fire alarm system to meet the requirements of ADA.*	LS	-	-	\$2,100.00
Repair/Replace platform receptacles	EACH	2.00	\$50.00	\$100.00
Replace canopy luminaires	EACH	10.00	\$700.00	\$7,000.00
Mobilization / Demobilization (10%)	LS	-	-	\$19,294.50
Sub-total				\$212,239.50
Contingency (20%)				\$42,447.90
Grand Total				\$254,687.40
Say				\$255,000.00

^{*} The Fire alarm system is an order-of-magnitude cost required to comply with ADA requirements. Performance of a fire alarm system design is required to develop a precise quantity estimate.

Lease Narrative and Synopsis

URBITRANREPORT



Prepared to

Connecticut Department of Transportation

Submitted by

Urbitran Associates, Inc.

Urbitran Associates

RAILROAD LEASE AGREEMENT NARRATIVE

STATION NAME: Old Greenwich/Riverside/Cos Cob

STATION OWNER: State of Connecticut Department of Transportation (DOT)

LESSEE: Town of Greenwich

The Lease Agreement dated August 25, 1998 (the "Lease"),] between the State of Connecticut DOT (the "State" or the "Lessor") and the Town of Greenwich provides for the lease of six parcels of land in the Town of Greenwich, Connecticut. The aggregate lease area is 20.22 acres, more or less. The lease covers two parcels of land at each of the following three MetroNorth stations: Old Greenwich, Riverside and Cos Cob.

The term of the lease, which began on April 1, 1998 and ends on March 31, 2008, is ten years. Lessee has the right to renew for one (1) additional ten (10) year period.

Lessee pays no annual fee to the State, but is required under the Lease to establish a separate account (the "Reinvestment Fund") to accrue surplus funds for the improvement and maintenance of rail station buildings, rail station parking and rail station services. All revenue generated from rail parking, rail-related leases and all other sources derived from the use of the leased properties (including accrued interest), minus mutually agreed upon operating and maintenance expenses, must be deposited annually into the Reinvestment Fund.

Lessee's duties under the Lease include day-to-day maintenance of the leased property, including, but not limited to, general repairs, snow removal, trash removal and security of all stations, platforms, railings, stairs, ramps and parking lots. The State's duties are explained with less specificity. Under the Lease, the State retains sole responsibility for maintaining all structural renovations and/or repairs. Where provision is not made in the Lease concerning the duties of the parties with respect to the parking lot, the Lease is supplemented by and made subject to each specification and covenant, unless specifically deleted therefrom, contained in the "Standard Railroad Lease Specifications & Covenants," dated October 1, 1997.

LEASE SYNOPSIS

STATION NAME:	Old Greenwich Station/Cos Cob
STATION IMAGE.	Station/Riverside Station
Lease Agreement(s) Reviewed	Lease Agreement dated 8/25/98
Least Agreement(s) Reviewed	Lease Agreement dated 6/25/76
Station Owner	State of Connecticut Department of Transportation
	(the "State")
Lessee	Town of Greenwich
Agreement Number	10.09-04(97)
	` '
Effective Date of Lease	4/1/98
Term	10 years
N 1 4 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1	
Number of Renewal Periods	1 (at Lessee's option)
Renewal Period	10 years
Renewal Period	10 years
Number of Lessee Renewals Executed in	0
Prior Years	
11101 Tears	
Number of Renewals Remaining	1
• · · · · · · · · · · · · · · · · · · ·	
Expiration Date of Lease	3/31/08
•	
Recorded?	Volume 3149, Page 297
Number of Parcels	6 (2 at Old Greenwich Station; 2 at Cos Cob
Total Acreage	20.22 acres
W	
How Is Revenue Earned?	1 6
A., C.,	
Are Separate Funds Accounts Required?	-
	agreed upon operating and/or maintenance
	expenses, shall be deposited annually into the
	Reinvestment Fund.
Allowable Direct Costs in Calculating	Improvement and maintenance of rail station
Surplus	building(s), rail station parking and rail station
~ WI 51W5	
Total Acreage How Is Revenue Earned? Are Separate Funds Accounts Required? Allowable Direct Costs in Calculating	Station; and 2 at Riverside Station) 20.22 acres Rail parking revenue and revenue from rail-related leases Yes. Lessee shall establish a separate account to accrue surplus funds (the "Reinvestment Fund"). All revenue generated from rail parking, rail-related leases and all other sources derived from the use of the properties described in the Lease (including accrued interest), minus mutually agreed upon operating and/or maintenance expenses, shall be deposited annually into the Reinvestment Fund. Improvement and maintenance of rail station

Allowable Indirect Costs in Calculating Surplus	Not specified.
Is Surplus Deposited in Capital Fund?	Yes
Is Surplus Shared with the State?	Yes
How Often is Surplus Shared? Are Certified Financial Statements Required?	At the end of each five (5) year period of the initial term and the one (1) renewal period thereafter, if any, the State shall be entitled to withdraw fifty percent (50%) of the surplus for use on other New Haven Line projects. Yes. See Appendix I.
Financial Statement Submission Period	Lessee must submit statement(s) of gross revenue to the State within ninety (90) days following the end of each year of the specified term of the Lease or any renewal period(s) thereafter, or other termination of the Lease.
Is Annual Budget Required?	No
Is Repayment of Debt Service Required?	No
Monthly Debt Repayment Amount	n/a
Does State Pay Lessee a Fee?	No
Amount of Fee Due Lessee	n/a
INSURANCE COVERAGE:	
Property Damage Insurance	Lessee shall carry Railroad Protective Liability Insurance for and on behalf of the railroad company as named insured, and the State and Lessee as named additional insureds, providing for coverage limits of (1) not less than Two Million Dollars (\$2,000,000) for all damages arising out of any one accident or occurrence, in connection with bodily injury or death and/or injury to or destruction of property; and (2) an aggregate limit of Six Million Dollars (\$6,000,000) for all injuries to persons or property during the policy period.
Bodily Injury Coverage	See above

Other Required Coverage	n/a
Voluntary Coverage	n/a
Is Lessee Self Insured?	
Is Certificate of Coverage on File?	
State Held Harmless?	Yes
Lessee Waives Immunity	Yes
MAINTENANCE:	
Enhance Aesthetic Appearance	Lessee
Not Erecting Signs on Premises	Lessee
Surface Grade Land	Lessee
Install and Maintain Fencing	Lessee
Install Suitable Drainage	Lessee
Ice Snow Control of Sidewalks	Lessee
Install and Maintain Electrical Systems for Lights	Lessee
Sweeping and Cleaning Litter	Lessee
Station Structures	Lessee
Platform Gutters	Lessee
Fences	Lessee
Signs	Lessee
Drains	Lessee
Platform Lights	Lessee
Equipment	Lessee
Electric and Mechanical Systems	Lessee
Live Rail Facilities	State

Platforms	Lessee
Railings	Lessee
Stairs	Lessee
Platform Shelters	Lessee
Platform Canopy	Lessee
Tunnels	Lessee
Parking Lots	Lessee
PARKING:	
Parking Fees	Where there is a charge for parking, the minimum annual parking fee per vehicle is \$100.00. The State reserves the right to review and approve any and all parking fees which exceed this minimum fee. Lessee has the right to establish and publish a Daily, Weekly, Monthly, Annual and/or other periodic Parking-Fee Schedule(s).
Nondiscrimination Clause	See Appendix II.
COSTS OF LEASEHOLD:	
Water	Lessee
Electricity	Lessee
Other Public Utilities	Lessee
Gas	
Sewer	
Owns Title to Property	State
Owns Title to Capital Improvements	State
Is Subleasing Allowed?	Not without prior written approval of the State and the appropriate Federal Regulatory Agency
Can Lease be Sold or Assigned?	Not without prior written approval of the State and the appropriate Federal Regulatory Agency
Is Security Bond Required?	No

If so, the Amount	n/a
OTHER:	
Termination	The State may terminate this Lease upon one year's notice to the Town for reasons of default or if the property is needed for transportation related purposes.
Is there a Lease to CT Transit?	No
Employment/Non Discriminatory Requirement	Yes
Miscellaneous	Lease is made subject to "Standard Railroad Lease Specifications & Covenants" dated 10/1/97

Station Operations Review

URBITRANREPORT



Prepared to

Connecticut Department of Transportation

Submitted by

Chance Management

Under Contract to

Urbitran Associates, Inc.

GREENWICH

Cos Cob, Old Greenwich, Riverside, and Greenwich Stations

Greenwich Station, the largest of the stations located in the Town, is privately owned and its corresponding garage is privately owned, with the ground floor assigned for rail parking. There are a number of town-owned surface lots located near Greenwich Station. These lots are designated for commuters and are operated, enforced, and maintained by the Town of Greenwich. These town-owned lots have no relation with the State and there are no leases regarding the ownership of the lots.

There are three other smaller stations within the Town of Greenwich in Cos Cob, Old Greenwich and Riverside. The lots that correspond to the stations are designated for railroad commuters and are also operated by the Town of Greenwich.

Agreements

The Town of Greenwich leases the Cos Cob, Old Greenwich and Riverside lots from the State. The Town is responsible for general and preventative maintenance for the lots. The State is responsible for all structural renovations and repairs, but there is no specific allocation of responsibility regarding the parking lots. The Town maintains and operates the lots.

A private company is contracted for landscaping and landscaping maintenance of the State-owned lots. Fannochi Brothers, a private company, has a contract with the Town to provide trash removal for the Cos Cob, Old Greenwich, and Riverside Stations and respective parking lots.

The State has absolutely no role in the privately owned and operated Greenwich Station. Albert B. Ashforth owns and operates the station. This private entity leases "Greenwich Plaza," the garage located below Greenwich Station, to the Town of Greenwich. A formal lease between Albert B. Ashforth and the Town of Greenwich was not available. There is also no State involvement with the town-owned surface lots located near Greenwich Station.

Organizational Structure


The Office of the First Selectman is the authority of the operations of the three stations and lots (Cos Cob, Riverside, and Old Greenwich). Fannochi Brothers and the private landscaping company indirectly report to the Office of the First Selectmen. The Police Department informally reports to the Office of the First Selectman. Employees of the Department of Public Works, the Office of the Comptroller, the Highways Department and the Department of Traffic Engineering report directly to the Office of the First Selectman with issues regarding the lots at Cos Cob, Riverside, and Old Greenwich stations. This is slightly different than the organization of the Greenwich Station lots, even those parcels owned by the Town. The lots surrounding the Greenwich Station are part of the Parking District, and therefore have a different organizational structure for operations and management.

Greenwich Station, itself, is owned and operated by Albert B. Ashforth. The parking garage located below the station is leased by the Town of Greenwich. The Office of the Comptroller, the Highways Department, and the Traffic Engineering Department report to the Town of Greenwich's Parking District. There is not a formal link between the Parking District and Albert B. Ashforth. However, there is most likely a working relationship between the two entities. This relationship would be best illustrated through the lease agreement that was not available. The Department of Public Works and the Police Department indirectly report to Albert B. Ashforth.


The Town-owned surface lots are operated by the Town of Greenwich. The State has no role with the lots and garage at Greenwich Station. As with the Greenwich Plaza parking garage, these lots have a similar organizational structure, minus the private entity.

Neither the Town of Greenwich nor the Parking District provided organization charts for the operations and maintenance of the four stations and parking lots located within Greenwich. The organization charts below were developed from data gathered from Town employees and administrators. The first chart represents the organization of operations for those stations and lots located outside of the Parking District: Cos Cob, Riverside and Old Greenwich. The second chart illustrates the operations of the surface lots located near Greenwich Station and the garage that is located below Greenwich Station.

Old Greenwich, Cos Cob, and Riverside Stations



Greenwich Station



Operating Procedures

At Cos Cob, Riverside and Old Greenwich stations, the authority is the Office of the First Selectman. Private companies are contracted for landscaping and trash removal. The Department of Public Works provides preventative maintenance while the Highways Department performs general maintenance (such as snow removal, paving, striping, cleaning, et cetera). The Department of Traffic Engineering provides wayfinding signs and the Office of the Comptroller provides permits and monitors the parking waitlist. The Police Department provides security and performs parking enforcement and violations.

Procedure	Responsible Party
Opening and Closing of Station	N/A
Housekeeping Inside Station	N/A
Housekeeping Outside Station	Highways Department
Daily Maintenance	Department of Traffic Engineering, Highways
-	Department and private company contract for trash
	removal
Preventative Maintenance	Department of Public Works
Landscaping	Private company contract
Security	Police Department
Customer Service	Office of First Selectman
Tenant Performance	N/A
Parking Enforcement	Police Department
Parking Fees and Permits	Office of the Comptroller
Parking Operation Maintenance	Highways Department

The Greenwich Station operates differently from the other three publicly operated stations in Greenwich. Albert B. Ashforth is responsible for the operations of the station itself. The Department of Public Works maintains the handicapped accessible elevator in the station. However, the Town of Greenwich's Parking District monitors the operations of the public lots. The Police Department provides security and enforcement for all lots and the privately owned garage. The Office of the Comptroller offers permits and maintains the parking waitlist for the lots surrounding Greenwich Station and the Greenwich Plaza Garage. The Highways Department provides general maintenance and the Department of Traffic Engineering provides signs for the lots.

Procedure	Responsible Party
Opening and Closing of Station	Albert B. Ashforth
Housekeeping Inside Station	Albert B. Ashforth
Housekeeping Outside Station	Albert B. Ashforth
Daily Maintenance	Albert B. Ashforth
Preventative Maintenance	Albert B. Ashforth
Landscaping	Albert B. Ashforth
Security	Police Department
Customer Service	Albert B. Ashforth
Tenant Performance	Albert B. Ashforth
Parking Enforcement	Police Department
Parking Fees and Permits	Office of the Comptroller
Parking Operation Maintenance	Department of Public Works, Highways
	Department, and Department of Traffic Engineering

Station Financial Review

URBITRANREPORT



Prepared to

Connecticut Department of Transportation

Submitted by

Seward and Monde

Under Contract to

Urbitran Associates, Inc.

OLD GREENWICH, RIVERSIDE AND COS COB FINANCES

ACCOUNTING ENTITY / BASIS

The Parking Fund is used by the Town of Greenwich to account for both State leased property and Town owned property used for railroad parking at these three stations. Any operating surplus is allocated to the State leased based on the percentage State-owned parking spaces to the total parking spaces for the combined stations. The cash basis of accounting was used to report the operations of these properties to the State. It should be noted that the Town also reports its operations in its annual government-wide financial statements as an enterprise fund that differs from the special report submitted to the State in that the enterprise fund accounting is on the accrual basis.

FINANCIAL REPORTING TO STATE

The Town submits an annual audited report to the State covering the lease operations at Old Greenwich, Cos Cob and Riverside stations. For 1997 and prior years the reporting covered the calendar year, subsequently the reports were converted to a June 30th fiscal year end. The reporting period has been converted to a June 30th fiscal year end for comparison to other stations in this report

Financial measurements such as unit values for revenues or costs per space, etc. and units further broken down for each lot, is not required by the lease and not included with the financial information.

REVENUES

Annual parking permits and one-day parking fees are the main sources of revenue. The Town also reports some rental income.

Parking Revenue Accounting - the Town's finance department accounts for Permit fees. A "transmittal form" is used to identify the property where the permit is used (town verses State – owned). An application/data base system is used to account for permit issuance and collection. The police department accounts for one-day fees. A mail-in ticketing system is used to issue and collect one-day fees. Enforcement officers ticket vehicles using a computerized hand-held device that dispenses pre-numbered tickets. Information is downloaded from these devices into a database that also provides information on outstanding unpaid tickets. The enforcement officers can utilize this information for on the spot notification of delinquencies. Violation tickets are issued frodelinquent parkers.

EXPENSES

Repairs and Maintenance expenses represent expenses paid to the Town for services rendered by the Town's public works department.

Generally Classified Expenses include certain costs allocated by the Town for indirect departmental support of the railroad parking operations and the Town's allocable share of net profits based on Town-owned parking spaces.

Metro-North and ConnDOT – The State also incurs station expenses through its service agreement with Metro-North / Metropolitan Transit Authority. These expenses are accounted for by Metro-North and included in the charge to the State. The expenses generally relate to maintaining the platform at each station.

The finances of the local government however do not include the station expenses paid by the State to Metro-North under the separate service agreement. These expenses include various maintenance responsibilities related to the stations and especially the platform area. Metro-North performs cyclical maintenance and on-call repairs and maintenance as needed. Metro-North also is responsible to maintain any ticketing area on railroad property. Such costs have been identified and included in the financial presentation.

The Metro-North service agreement also provides that the State pay for the allocated cost of station maintenance forces. These allocated indirect costs have not been included in the financial presentation.

The local government is not in direct control of the services rendered by Metro-North. These services are controlled by the service agreement. The service agreement is outside of the State lease agreement with the local government

ConnDOT also incurs expense for its administrative oversight of the operating leases and the physical properties. These expenses were not compiled or presented in the financial presentation.

EXPENSE ALLOCATION

The allocation of indirect expenses is a financial issue that would apply to most of the State lease agreements where the local government has determined that administrative charges are warranted and come under the "mutually determined charges" clause of the lease agreements. The lease is not clear as to exactly what charges are allowable. The allocations generally result from common costs such as administrative expenses or departmental expenses that do not exclusively service the railroad properties but service a number of funds and functional activities. The reasonableness or propriety of the allocation and method was not evaluated to determine if such costs were actually incremental or simply attributed to the leased property under a full absorption costing methodology.

PROFITABILITY / ACCUMULATED SURPLUS

The five-year period showed annual net profits and an accumulated surplus at June 30, 2000 of \$1.318,325 in the "reinvestment fund". The profits were sufficient to also cover Metro-North station expenses.

The balance at June 30, 2000 does not reflect an allocation of investment income to the "reinvestment fund." The fiscal 2001 report included three years of interest from July 1, 1998 to June 30, 2001.

SPECIAL REQUIREMENTS - SURPLUS/RESERVE/DEFICIT

The lease agreement does not specifically address the administration or funding of any deficit resulting from the State properties managed by the local government.

CAPITAL PROJECTS

During the five-year period, the only capital outlay reported by the Town was a charge against operations for the replacement of lighting fixtures at all three stations.

FINANCIAL PRESENTATION IN COMPARISON TO THE PARKING INVENTORY

A parking inventory and utilization report is presented separately as Task 2 in this study. The financial presentation herein and the parking inventory cover both the Town's and State-owned parking spaces at all three stations. As noted above, the Town's share of net income has been recorded among "Generally classified expenses" in order to derive net income available to the State.

YEAR 1996							YEAR 1997								
		OPERATING A					_	·	OPERATING AGREEMENTS						
<u>REVENUES</u>	LC	CAL GOV'T	ME	TRO-NORTH		TOTAL	<u>%</u>		LOCAL GOV'T	ME	ETRO-NORTH	TOTAL	<u>%</u>		
PARKING RENTS INVESTED FUNDS OTHER	\$	343,907 805 -	\$	- - -	\$	343,907 805 - -	99.8% 0.2% 0.0% 0.0%	\$	335,408 910 - -	\$	- \$ - -	335,408 910 - -	99.7% 0.3% 0.0% 0.0%		
	\$	344,712	\$		\$	344,712	100.0%	<u>\$</u>	336,318	\$	- \$	336,318	100.0%		
STATION, PLATFORMS AND PARKING EXPENSES															
REPAIRS AND MAINTENANCE UTILITIES RENT SECURITY INSURANCE AND CLAIMS (RECOVERY) GENERALLY CLASSIFIED EXPENSES (INCLUDING UNSPECIFIED -	\$	80,781 - - - -	\$	35,252 - - - (9,953)	\$	116,033 - - - (9,953)	58.9% 0.0% 0.0% 0.0% -5.0%	\$	91,742 - - - -	\$	24,485 \$ (148,421)	116,227 - - - (148,421)	207.2% 0.0% 0.0% 0.0% -264.7%		
DIRECT, -INDIRECT, - ADMINISTRATIVE , -AND GENERAL ALLOCATIONS) CONNECTICUT SALES TAX		86,718 -		4,354 -		91,072 -	46.2% 0.0%	_	85,124 -		3,151 -	88,275 -	157.4% 0.0%		
	\$	167,499	\$	29,653	\$	197,152	100.0%	\$	176,866	\$	(120,785) \$	56,081	100.0%		
<u>NET PROFIT (LOSS)</u>	<u>\$</u>	177,213	\$	(29,653)	\$	147,560		<u>.\$</u>	159,452	\$	120,785 \$	280,237			
LOCAL GOVERNMENT'S RAILROAD FUND															
ACCUMULATED SURPLUS (DEFICIT) LESS - LOCAL GOVERNMENT'S SHARE	\$	780,547						\$	940,000	_					
NET AVAILABLE RAILROAD FUND SURPLUS (DEFICIT)	\$	780,547						\$	940,000	-					
STATE'S AVAILABLE SHARE @ 50%	\$	390,274						\$	470,000	=					

YEAR 1998							YEAR 1999							
		<u>EMENTS</u>					OPERATING A	<u>AGREEMENTS</u>						
<u>REVENUES</u>	L	OCAL GOV'T	M	IETRO-NORTH		<u>TOTAL</u>	<u>%</u>	L	OCAL GOV'T	ME	TRO-NORTH	<u>TOTAL</u>	<u>%</u>	
PARKING	\$	303,782	\$	-	\$	303,782	99.7%	\$	270,233	\$	- \$	270,233	99.7%	
RENTS		887		-		887	0.3%		793		-	793	0.3%	
INVESTED FUNDS		-		-		-	0.0%		-		-	-	0.0%	
OTHER		-		-		-	0.0%		-		-	-	0.0%	
	\$	304,669	\$	<u>-</u>	\$	304,669	100.0%	\$	271,026	\$	- \$	271,026	100.0%	
STATION, PLATFORMS AND PARKING EXPENSES														
REPAIRS AND MAINTENANCE	\$	103,002	\$	46,579	\$	149,581	62.7%	\$	113,052	\$	24,370 \$	137,422	69.6%	
UTILITIES	•	-	•	-	•	-	0.0%	•	-	•	- 1,010	-	0.0%	
RENT		-		-		-	0.0%		-		-	-	0.0%	
SECURITY		-		-		-	0.0%		-		-	-	0.0%	
INSURANCE AND CLAIMS		-		550		550	0.2%		-		(9,762)	(9,762)	-4.9%	
GENERALLY CLASSIFIED EXPENSES (INCLUDING UNSPECIFIED -														
DIRECT, -INDIRECT, - ADMINISTRATIVE , -AND GENERAL		77.000		40.004		00.004	07.00/		00.000		0.500	00.700	05.00/	
ALLOCATIONS) CONNECTICUT SALES TAX		77,300		10,991		88,291	37.0% 0.0%		66,206		3,526	69,732	35.3% 0.0%	
CONNECTION SALES TAX				<u> </u>		-	0.0%				-	<u>-</u>	0.0%	
	\$	180,302	\$	58,120	\$	238,422	100.0%	\$	179,258	\$	18,134 \$	197,392	100.0%	
NET PROFIT (LOSS)	\$	124,367	\$	(58,120)	\$	66,247		\$	91,768	\$	(18,134) \$	73,634		
<u> </u>	<u> </u>	124,001	Ψ	(00,120)	Ψ	00,241		<u> </u>	31,700	Ψ	(10,104) ψ	70,004		
LOCAL GOVERNMENT'S RAILROAD FUND														
ACCUMULATED SURPLUS (DEFICIT) LESS - LOCAL GOVERNMENT'S SHARE	\$	1,064,439						\$	1,156,207					
NET AVAILABLE RAILROAD FUND SURPLUS (DEFICIT)	\$	1,064,439	ı					\$	1,156,207	_				
STATE'S AVAILABLE SHARE @ 50%	\$	532,220	:					\$	578,104	=:				

	YEAR 2000							
	OPERATING AGREEMENTS							
<u>REVENUES</u>	LC	OCAL GOV'T	METRO-NORTH		TOTAL	<u>%</u>		
PARKING	\$	383,837	\$ -	\$	383,837	99.8%		
RENTS		840	_		840	0.2%		
INVESTED FUNDS		-	-		-	0.0%		
OTHER		-	-		-	0.0%		
	\$	384,677	\$ -	\$	384,677	100.0%		
STATION, PLATFORMS AND PARKING EXPENSES								
REPAIRS AND MAINTENANCE	\$	126,916	\$ 36,370	\$	163,286	57.2%		
UTILITIES	•	-	-	•	-	0.0%		
RENT		-	-		-	0.0%		
SECURITY		-	-		-	0.0%		
INSURANCE AND CLAIMS		-	23,619		23,619	8.3%		
GENERALLY CLASSIFIED EXPENSES (INCLUDING UNSPECIFIED -								
DIRECT, -INDIRECT, - ADMINISTRATIVE , -AND GENERAL								
ALLOCATIONS)		95,643	2,729		98,372	34.5%		
CONNECTICUT SALES TAX		-	-		-	0.0%		
	\$	222,559	\$ 62,718	\$	285,277	100.0%		
NET PROFIT (LOSS)	\$	162,118	\$ (62,718)	\$	99,400			
<u></u>	<u> </u>	702,770	ψ (02,710)		00,400			
LOCAL CONFERMENTIO DAY DOAD FUND								
LOCAL GOVERNMENT'S RAILROAD FUND								
ACCUMULATED SURPLUS (DEFICIT) LESS - LOCAL GOVERNMENT'S SHARE	\$	1,318,325						
NET AVAILABLE RAILROAD FUND SURPLUS (DEFICIT)	\$	1,318,325						
STATE'S AVAILABLE SHARE @ 50%	\$	659,163	•					

Traffic and Transportation

Bridge and Civil Engineering

Architecture

Parking Services

Construction Inspection

Environmental Services

Transit Services

Structural Engineering

U R B I T R A N <mark>R E P O R T</mark>

71 West 23rd Street New York, New York 10010 212.366.6200 Fax 212.366.6214

12 West 27th Street, 12th FLoor New York, NY 10001 212.366.6200 Fax 646.424.0835

New Jersey

2 Ethel Road - Suite 205B Edison, New Jersey 08817 732.248.5422 Fax 732.248.5424

150 River Road, Building E Montville, NJ 07045 973.299.2910 Fax 973.299.0347

Connecticut

50 Union Avenue Union Station, Third Floor East New Haven, CT 06519 203.789.9977 Fax 203.789.8809

California

1440 Broadway, Suite 500 Oakland, CA 94612 510.839.0810 Fax 510.839.0854

Massachusetts

275 Southampton Road Holyoke, MA 01040 413.539.9005

Albany

6 Meadowlark Drive Cohoes, NY 12047 P.O.Box 524 518.235.8429