Memorandum

To: Dr. Michael Klemens

From: Roger Hurlbut Roger Hurlbut

Date: May 31, 2012

Re: Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 29 and 30 for the period May 19 through May 31, 2012.

Both inspections were undertaken after rain events. No problems or discharges were observed.

CC C Jones Civil 1
G Zupkus BNE Energy

| General Information | | | | | |
|---|--|-------------------|------------|--|--|
| Project Name: | Wind Colebrook South | | | | |
| Location: | Winsted- Norfolk Road | | | | |
| | Colebrook, Connecticut | | T | | |
| CT DEP Tracking No. | CSC Petition 983 | Report No. | 29 | | |
| Date of Inspection: | May 22, 2012 | Start / End Time: | 1PM to 2PM | | |
| Inspector's Name(s): | Roger Hurlbut Roger Hurlbut | | | | |
| Inspector's Title(s): | Project Engineer | | | | |
| Inspector's Contact Information: | LENARD ENGINEERING INC 860 379-6669 off | | | | |
| Describe present phase of construction: | No work has occurred since last inspection on 5/15/12 No problems observed, grass is starting to grow | | | | |
| Type of Inspection: ☐ Regular ☐ Pre-storm event ☐ During storm event ☐ Post-storm event | | | | | |
| Weather Information | | | | | |
| Has it rained since the last inspection? ☑Yes □No | | | | | |
| If yes, provide: Storm Start Date & Time: 5/21/12 – 6PM Storm Duration (hrs): Approximate Rainfall (in): 0.5+/- | | | | | |
| Storm Start Date & Time. 3/21/12 – of M. Storm Daration (ms). Approximate Raman (m). 0.3+/- | | | | | |
| Weather at time of this inspection? Overcast/lt drizzle light breeze 60° F | | | | | |
| Discharge Information (A) | | | | | |
| Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No | | | | | |
| Are there any discharges at the time of inspection? □Yes ☑No | | | | | |
| Describe location of any discharges from the site: | | | | | |
| | | | | | |

| General Information | | | | | |
|--|--|-------------------|---------------|--|--|
| Project Name: | Wind Colebrook South | | | | |
| Location: | Winsted- Norfolk Road | | | | |
| | Colebrook, Connecticut | | T | | |
| CT DEP Tracking No. | CSC Petition 983 | Report No. | 30 | | |
| Date of Inspection: | May 31, 2012 | Start / End Time: | 8:15AM to 9AM | | |
| Inspector's Name(s): | Roger Hurlbut Roger Hurlbut | | | | |
| Inspector's Title(s): | Project Engineer | | | | |
| Inspector's Contact Information: | LENARD ENGINEERING INC 860 379-6669 off | | | | |
| Describe present phase of construction: | No work has occurred since last inspection on 5/22/12 No problems observed, grass is starting to grow | | | | |
| Type of Inspection: ☐ Regular ☐ Pre-storm event ☐ During storm event ☐ Post-storm event | | | | | |
| Weather Information | | | | | |
| Has it rained since the last inspection? ☑Yes □No | | | | | |
| If yes, provide: >0.5 in last 36 Hrs showers & thunderstorms Storm Start Date & Time: Storm Duration (hrs): Approximate Rainfall (in): 0.5+/- | | | | | |
| Weather at time of this inspection? Sunny light breeze 59° F | | | | | |
| Discharge Information (A) | | | | | |
| Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No | | | | | |
| Are there any discharges at the time of inspection? □Yes ☑No | | | | | |
| Describe location of any discharges from the site: | | | | | |