Memorandum

To: Dr. Michael Klemens

From: Roger Hurlbut Roger Hurlbut

Date: August 13, 2012

Re: Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 40 through 43 for the period July 27 through Aug 10, 2012.

On July 28th (report # 40) we had a short intense storm (3-in in 1.5hr), however no problems or discharges were observed. Report # 41 was a normal weekly report and #'s 42 & 43 were after rainfall events.

No problems or discharges were observed. Greg Zupkus installed silt fence in the area noted in previous inspection reports

CC C Jones Civil 1 G Zupkus BNE Energy

General Information					
Project Name:	Wind Colebrook South	Wind Colebrook South			
Location:	Winsted- Norfolk Road				
CT DEP Tracking No.	Colebrook, Connecticut CSC Petition 983	Report No.	40		
Date of Inspection:	July 29, 2012	Start / End Time:	9.10 AM to 10.15 AM		
Inspector's Name(s):	Roger Hurlbut Start / End Time: 9.10 AM to 10.15 AM				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off				
Describe present phase of construction:	No work has occurred since last inspection on 7/24/12 No problems observed Silt fence should be installed in the area of Flags 445-450				
Type of Inspection: ☐ Regular ☐ Pre-storm event ☐ During storm event ☐ Post-storm event					
Weather Information					
Has it rained since the last ins ☑Yes ☐No	pection?				
If yes, provide: Storm Start Date & Time: 7/28/12 Storm Duration (hrs): 1.5 hrs Approximate Rainfall (in): 3in +/-					
Weather at time of this inspection? 78° F, overcast					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No					
Are there any discharges at the time of inspection? □Yes ☑No					
Describe location of any discharges from the site:					

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road				
	Colebrook, Connecticut	D W			
CT DEP Tracking No.	CSC Petition 983	Report No.	41		
Date of Inspection:	Aug 3, 2012	Start / End Time:	5:10 PM to 5:45 PM		
Inspector's Name(s):	Roger Hurlbut	Roger Hurlbut			
Inspector's Title(s):	Project Engineer	Project Engineer			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off				
Describe present phase of construction:	No work has occurred since last inspection on 7/29/12 No problems observed Silt fence should be installed in the area of Flags 445-450				
Type of Inspection: ☑ Regular □ Pre-storm event □ During storm event □ Post-storm event					
Weather Information					
Has it rained since the last inspection? □Yes ☑No					
If yes, provide: Storm Start Date & Time: Storm Duration (hrs): Approximate Rainfall (in):					
Weather at time of this inspection? 85° F, Sunny					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No					
Are there any discharges at the time of inspection? □Yes ☑No					
Describe location of any discharges from the site:					

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983	Report No.	42		
Date of Inspection:	Aug 6, 2012	Start / End Time:	7:15 AM to 8:00 AM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off				
Describe present phase of construction:	No work has occurred since last inspection on 8/3/12 No problems observed Silt fence should be installed in the area of Flags 445-450				
Type of Inspection: ☐ Regular ☐ Pre-storm event ☐ During storm event ☐ Post-storm event					
Weather Information					
Has it rained since the last inspection? ☑Yes □No					
If yes, provide: Storm Start Date & Time: 8-5-12 4PM Storm Duration (hrs): 45 min Approximate Rainfall (in): 0.63					
Weather at time of this inspection? 69° F, Sunny, light Breeze					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No					
Are there any discharges at the time of inspection? □Yes □No					
Describe location of any discharges from the site:					

General Information					
Project Name:	Wind Colebrook South				
Location:	winsted- Norfolk Road				
	Colebrook, Connecticut	D .X	42		
CT DEP Tracking No.	CSC Petition 983	Report No.	43		
Date of Inspection:	Aug 10, 2012	Start / End Time:	6:15PM to 7:00 PAM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off				
Describe present phase of construction:	No problems observed Silt fence installed in the area of Flags 442 to 449 appears to be adequate From 449 to 452/453 there is sufficient vegetation to prevent erosion or discharge				
Type of Inspection: ☐ Regular ☐ Pre-storm event ☐ During storm event ☐ Post-storm event					
Weather Information					
Has it rained since the last inspection? ☐Yes ☐No					
If yes, provide: Storm Start Date & Time: 8/10/12 1PM Storm Duration (hrs): 4 Approximate Rainfall (in): 0.49					
Weather at time of this inspection? 72° F, overcast, light showers/drizzle					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No					
Are there any discharges at the time of inspection? □Yes ☑No					
Describe location of any discharges from the site:					



Silt Fence Installed 8/8/2012



Silt Fence Installed 8/8/2012

