

## **Memorandum**

To:	Dr. Michael Klemens	
	Roger Hurlbut	Roper Hurlbut
Date:	August 24, 2012 Wind Colebrook South	
Re:	Wind Colebrook South	

Attached are environmental erosion and sediment control monitoring reports numbers 44 through 46 for the period Aug 11 through Aug 24, 2012.

Report #'s 44 & 45 were after rainfall events, # 46 was a normal weekly report. No problems or discharges were observed.

No problems or discharges were observed.

CC C Jones Civil 1 G Zupkus BNE Energy

General Information						
Project Name: Wind Colebrook South						
Location:	Winsted- Norfolk Road Colebrook, Connecticut					
CT DEP Tracking No.	CSC Petition 983	Report No.	44			
Date of Inspection:	Aug 15, 2012	Start / End Time:	6:15PM to 6:50 PM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off					
Describe present phase of construction:	No problems observed No work has been done since last inspection on 8-10-12					
Type of Inspection: Regular Pre-storm ev	vent During storm eve	nt 🗹 Post-storm ev	/ent			
Weather Information						
Has it rained since the last inspection? ☑Yes □No						
If yes, provide: Storm Start Date & Time: 8/15/12 4:30AM Storm Duration (hrs): 4 Approximate Rainfall (in): 0.4						
Weather at time of this inspection? 68° F, overcast						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						

General Information						
Project Name: Wind Colebrook South						
Location:	Winsted- Norfolk Road					
	Colebrook, Connecticut					
CT DEP Tracking No.	CSC Petition 983	Report No.	45			
Date of Inspection:	Aug 18, 2012	Start / End Time:	9:45 AM to 10:30 AM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off					
Describe present phase of construction:	t phase of No problems observed No work has been done since last inspection on 8-15-12					
Type of Inspection: □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ <th□< td=""></th□<>						
Weather Information						
Has it rained since the last inspection?						
If yes, provide: Storm Start Date & Time: 8/17/12 8:30AM Storm Duration (hrs): 12 Approximate Rainfall (in): 0.24						
Weather at time of this inspection? 62° F, overcast						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						
<u>L</u>						

General Information						
Project Name: Wind Colebrook South						
Location:	Winsted- Norfolk Road Colebrook, Connecticut					
CT DEP Tracking No.	CSC Petition 983	Report No.	46			
Date of Inspection:	Aug 23, 2012	Start / End Time:	6:45:PM to 7:30 PM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off					
Describe present phase of construction:	No problems observed No work has been done since last inspection on 8-18-12					
Type of Inspection: ☑ Regular □Pre-storm ev	vent During storm eve	nt Post-storm ev	ent			
Weather Information						
Has it rained since the last ins $\Box$ Yes $\Box$ No	pection?					
If yes, provide: Storm Start Date & Time: Storm Duration (hrs): Approximate Rainfall (in):						
Weather at time of this inspection? 70° F, clear						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						