

Memorandum

	Dr. Michael Klemens
From:	Roger Hurlbut September 21, 2012 Wind Colebrook South
Date:	September 21, 2012
Re:	Wind Colebrook South

ī

Attached are environmental erosion and sediment control monitoring reports numbers 49 through 51 for the period Sept 8 through Sept 21, 2012.

Inspections 49 & 51 were after rainfall events. Report # 50 was a normal weekly report. No problems or discharges were observed.

CC C Jones Civil 1 G Zupkus BNE Energy

General Information						
Project Name:	Wind Colebrook South					
Location: Winsted- Norfolk R						
CT DEP Tracking No.	Colebrook, Connecticut CSC Petition 983	Report No.	49			
Date of Inspection:	Sept 9, 2012	Start / End Time:	10:30:AM to 11:15 AM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off					
Describe present phase of construction:	No problems observed No work has been done since last inspection on 9/6/12 Between 183 & 185 fence is leaning over & 1 post is broken off at ground level. Silt is visible on bottom of fence but no discharge occurred					
Type of Inspection: Regular Pre-storm ev	vent During storm eve	nt Post-storm ev	ent			
Weather Information						
Has it rained since the last ins \square Yes \square No	pection?					
If yes, provide: Storm Start Date & Time: 9/8/12 1PM Storm Duration (hrs): 12 Approximate Rainfall (in): >1						
Weather at time of this inspection? 72° F, clear						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						

General Information						
Project Name: Wind Colebrook South						
Location:	Winsted- Norfolk Road Colebrook, Connecticut					
CT DEP Tracking No.	CSC Petition 983	Report No.	50			
Date of Inspection:	Sept 14, 2012	Start / End Time:	6:45:PM to 7:15 PM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off					
Describe present phase of construction:	No problems observed Gravel Driveway has been regraded & silt & sediment deposited at southeast corner of stripped topsoil area has been removed					
Type of Inspection: ☑ Regular □Pre-storm ev	vent During storm eve	nt	ent			
Weather Information						
Has it rained since the last ins □Yes ☑No	pection?					
If yes, provide: Storm Start Date & Time: Storm Duration (hrs): Approximate Rainfall (in):						
Weather at time of this inspection? 65° F, clear						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						

General Information							
Project Name: Wind Colebrook South							
Location:	Winsted- Norfolk Road						
CT DED Tracking No.	Colebrook, Connecticut CSC Petition 983	Demont No.	51				
CT DEP Tracking No.		Report No.	51 7AM to 9 AM				
Date of Inspection:	Sept 19, 2012	Start / End Time:	7AM to 8 AM				
Inspector's Name(s):	Roger Hurlbut						
Inspector's Title(s):	Project Engineer						
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off						
Describe present phase of construction:							
Type of Inspection: Regular Pre-storm ev	vent During storm eve	nt ⊡Post-storm ev	ent				
Weather Information							
Has it rained since the last ins \square Yes \square No	pection?						
If yes, provide: Storm Start Date & Time:9/18/12 7AM Storm Duration (hrs):18hrs Approximate Rainfall (in):>1.5-in							
Weather at time of this inspection? 52° F, clear							
Discharge Information (A)							
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No							
Are there any discharges at the time of inspection? □Yes ☑No							
Describe location of any discharges from the site:							