



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: January 13, 2012
Re: Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 6 and 7 for the period January 1 through January 13, 2012. Work at the site consisted of: Installation of sediment and erosion control fencing and clearing and grubbing for turbine site # 2.

Report # 6 inspection (1/5/12) was a normal weekly inspection.

Report # 7 inspections were conducted within 24 hrs of a rainfall/snowfall event E&S controls were in place and no erosion or sediment discharges had occurred.

As of 1/5/12 the tree cutting equipment had been removed from the site and no addition cutting has taken place.

Portions of E&S fencing in the vicinity clearing limit flags 26 through 29 is sagging and should be tied up. I will notify the contractor.

CC C Jones Civil 1
G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	6
Date of Inspection:	January 5 2012	Start / End Time:	1:15 / 2:30
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	<p>Haybales /silt fence in place from 198 through 192</p> <p>No change to Turbine 1 area: Erosion & sediment control fencing in from clearing limit flag #191 through #178 From 177 through 174+- ledge rock encountered and wood chips were installed From 174+- to 171 to 159 to 156+- Fencing installed - double row from 171 to 159</p> <p>Contractor had installed silt fence along access rd from 434 to 441</p> <p>Contractor removing stumps & preparing to install sediment control in Turbine 2 area.</p> <p>No new tree removal and cutting contractor off site</p>		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time:		Storm Duration (hrs):	Approximate Rainfall (in):
Weather at time of this inspection? Partly cloudy light breeze 33° to 35° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	7
Date of Inspection:	January 13 2012	Start / End Time:	8:10 / 9:15
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	<p>No work being done on 1/13/12</p> <p>Haybales /silt fence in place from 198 through 192</p> <p>No change to Turbine 1 area: Erosion & sediment control fencing in from clearing limit flag #191 through #178 From 177 through 174+- ledge rock encountered and wood chips were installed From 174+- to 171 to 159 to 156+- Fencing installed - double row from 171 to 159</p> <p>Contractor had installed silt fence along access rd from 434 to 441</p> <p>Contractor removing stumps & installing sediment control in Turbine 2 area. From 453 to 41 <i>Portions of the fence are sagging in vicinity of Clearing limit flags 26 to 29 and should be tied up. Contractor will be notified</i></p> <p>No new tree removal and cutting contractor off site as of 1/5/12</p>		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Snow & Rain ground has snow cover			
If yes, provide: Storm Start Date & Time: 1/12/12 Storm Duration (hrs): 24 hrs Approximate Rainfall (in): <1/2-in			
Weather at time of this inspection? Overcast with mist 31° to 33° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

