

Memorandum

	Dr. Michael Klemens		
From:	Roger Hurlbut	Roper Hurlbut	
Date:	July 12, 2013		
Re:	Roger Hurlbut July 12, 2013 BNE Wind Colebrook South		

Attached are environmental erosion and sediment control monitoring reports numbers 101, 102 and 103 for the period June 29 thru July 12, 2013.

No problems observed

CC G Zupkus BNE Energy

General Information						
Project Name:	Wind Colebrook South					
Location:	Winsted- Norfolk Road Colebrook, Connecticut					
CT DEP Tracking No.	CSC Petition 983	Report No.	101			
Date of Inspection:	July 2, 2013	Start / End Time:	7:30 AM to 8:00AM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off					
Describe present phase of construction:	No work No problems or discharges observed					
Type of Inspection: □Regular □Pre-storm ev	vent During storm eve	nt 🗹 Post-storm ev	vent			
Weather Information						
Has it rained since the last inspection?						
If yes, provide: Storm Start Date & Time:7/1/13—10AM Storm Duration (hrs): 3hr Approximate Rainfall: 0.5						
Weather at time of this inspection? 72° F, Overcast						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						

General Information						
Project Name:	Wind Colebrook South					
Location:	Winsted- Norfolk Road					
CT DEP Tracking No.	Colebrook, ConnecticutCSC Petition 983Report No.102					
Date of Inspection:	July 8, 2013	Start / End Time:	5:30 PM to 6:00PM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:						
Describe present phase of construction:						
Type of Inspection: Regular Pre-storm ev	vent During storm eve	nt 🗹 Post-storm ev	vent			
Weather Information						
Has it rained since the last inspection?						
If yes, provide: Storm Start Date & Time:7/7/13—4PM Storm Duration (hrs): 4hr Approximate Rainfall: 0.46						
Weather at time of this inspection? 80° F, Pt Cldy						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						

General Information						
Project Name:	Wind Colebrook South					
Location:	Winsted- Norfolk Road Colebrook, Connecticut					
CT DEP Tracking No.	CSC Petition 983	Report No.	103			
Date of Inspection:	July 12, 2013	Start / End Time:	7:00 AM to 7:30 AM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	nspector's Contact LENARD ENGINEERING INC					
Describe present phase of construction: No work No problems or discharges observed						
Type of Inspection: Regular Pre-storm ev	vent During storm eve	nt 🗹 Post-storm ev	/ent			
Weather Information						
Has it rained since the last inspection? ☑ Yes □No						
If yes, provide: Storm Start Date & Time:7/10/13—3PM Storm Duration (hrs): 4hr Approximate Rainfall: 086						
Weather at time of this inspection? 67° F, Pt Cldy						
Discharge Information (A)						
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No						
Are there any discharges at the time of inspection? □Yes ☑No						
Describe location of any discharges from the site:						