## **Memorandum**

**To:** Dr. Michael Klemens

From: Roger Hurlbut Roger Hurlbut

**Date:** Jan 9, 2014

**Re:** | BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 128 and 129 for the period Dec 27, 2013 thru Jan 9, 2014.

Contractor on site preparing crane pad for site 1

No problems observed

CC G Zupkus BNE Energy

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road				
CT DEP Tracking No.	Colebrook, Connecticut CSC Petition 983	Report No.	128		
Date of Inspection:	Dec 30, 2013	Start / End Time:	12:30PM to 1:30PM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off				
Describe present phase of construction:	Clearing and grubbing for revised road alignment & site 2 location Silt fencing in place  No problems or discharges observed				
Type of Inspection:  □Regular □Pre-storm event □ During storm event □Post-storm event					
Weather Information					
Has it rained since the last inspection?					
☑ Yes ☐No If yes, provide: Storm Start Date & Time: 12-29-13 12PM Storm Duration (hrs): 10 Approximate Rainfall: 074					
Weather at time of this inspection? 28° Clear breezy					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection?  □Yes ☑No					
Are there any discharges at the time of inspection?  □Yes ☑No					
Describe location of any discharges from the site:					

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road				
	CSC Potition 092	D AN	120		
CT DEP Tracking No.	CSC Petition 983	Report No.	129		
Date of Inspection:	January 6, 2014	Start / End Time:	4:15PM to 4:55PM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off				
Describe present phase of construction:	Excavation for crane pad at site 1 Silt fencing in place No problems or discharges observed				
Type of Inspection: ☐Regular ☐Pre-storm event ☐ During storm event ☐Post-storm event					
Weather Information					
Has it rained since the last inspection?  ☑ Yes □No					
If yes, provide: Storm Start Date & Time: 1/6/2014 2AM Storm Duration (hrs): 10 Approximate Rainfall: 0.79					
Weather at time of this inspection? 28° overcast breezy					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection?  ☐Yes ☐No					
Are there any discharges at the time of inspection?  ☐Yes ☐No					
Describe location of any discharges from the site:					