CONSTRUCTION SITE INSPECTION REPORT

Community of the commun	THE POST OF THE PO			
General Information	Wind Calabas at Caseth			
Project Name:	Wind Colebrook South			
Location:	Winsted- Norfolk Road			
CT DEP Tracking No.	Colebrook, Connecticut CSC Petition 983 Report No. 142			
Date of Inspection:				
Date of hispection.	Water 31, 2014	Start / End Time.	10:45AM to 11:30AM	
Inspector's Name(s):	Roger Hurlbut	Roger Hurlbut		
Inspector's Title(s):	Project Engineer			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off			
Describe present phase of construction:	No work on site Approximately 3+/- in Intermittent rain since 3/28/	/2014		
Type of Inspection: □Regular □Pre-storm e	vent	ent ☑Post-storm e	event	
Weather Information				
Has it rained since the last ins ☑ Yes □No	pection?			
If yes, provide: Storm Start Date & Time: 3-	28-14 12:00PM Storm I	Ouration (hrs): Approxi	mate Rainfall: 3.1-in	
Weather at time of this inspec	tion? 31° overcast breezy			
Discharge Information (A)				
Do you suspect that discharge ☐Yes ☑No	s may have occurred since th	e last inspection?		
Are there any discharges at th ☐Yes ☐No	e time of inspection?			
Describe location of any discharges from the site:				

INSPECTOR CERTIFICATION Project: Wind Colebrook South Project Location: Winsted- Norfolk Road Colebrook CT Contractor: No work being done Address: Phone: Fax:

CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description	(1) Report No.
3/7/14	☑ Inspection	ı	Siting Council
	☐ Maintenance	By R Hurlbut LEI	#138
3/12/14	☑ Inspection	by Kitanout EE1	Siting Council
	☐ Maintenance	By: R Hurlbut LEI	#139
	☑ Inspection	by. Refraitour BEI	Siting Council
3/20/14	☐ Maintenance	By: R Hurlbut LEI	#140
	☑ Inspection	by. Refraitour Edit	Siting Council
3/28/14	☐ Maintenance	By: R Hurlbut LEI	#141
	☑ Inspection		Siting Council
3/31/14	☐ Maintenance	By: R Hurlbut LEI	#142
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		

SITE-SPECIFIC BMPs

BIIL	-SPECIFIC BMPs	<u> </u>		
(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed Date for correction action / responsion party	
1	Anti Tracking Pad	☑Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	☑Yes □No		
3	Temp Sediment Basins	⊠Yes □No		
4	Sediment & Erosion Control Barriers	□Yes ☑No	Silt fence needs to be installed at TST 2	After snow melts
5	Temp ground cover	□Yes ☑No	Temp seeding need to be done in vicinity of TST 2 & detention basin 2 on Tower 1 site	After snow melt
6	Temp ground cover	□Yes ☑No	Tower 2 area should be temporarily seeded & mulched	After snow melt
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	□Yes ☑No	□Yes □No	Inactive slopes adjacent to basin 2 need to be stabilized	As snow melts
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☑Yes □No	☑Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	☑Yes □No	☑Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	☑Yes □No	☑Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	☑Yes □No	☑Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

GENERAL INSPECTION COMMENTS AND EXPLANATION

GENERAL INSPECTION COMMENTS AND EXPLANATION
General Inspection Comments (D)
There has been no runoff from the site due to depth of snow cover
Is other descriptive information attached to this inspection report?
□Yes ☑No
Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
☐Yes ☐No Silt fence at TST # 2 Tower 1 Area not installed
Are additional BMP's required?
□Yes ☑No
Does the plan need to be updated?
□Yes □No
Explanation of additional BMP and Plan update requirements:
Name: Roger Hurlbut
(Please print) Signature: Roper Hurlbut
Signature:
Title: Independent(3 rd party) Inspector Date: 3/31/2014