| General Information | | | |
|--|---|-------------------|---------------------|
| Project Name: | Wind Colebrook South | | |
| Location: | Winsted- Norfolk Road Colebrook, Connecticut | | |
| CT DEP Tracking No. | CSC Petition 983 | Report No. | 151 |
| Date of Inspection: | May 29, 2014 | Start / End Time: | 12:30 PM to 1:00 PM |
| Inspector's Name(s): | Roger Hurlbut | | |
| Inspector's Title(s): | Project Engineer | | |
| Inspector's Contact Information: | LENARD ENGINEERING INC 860 379-6669 off ice | | |
| Describe present phase of construction: | No work on site | | |
| Type of Inspection: ØRegular Pre-storm event During storm event Post-storm event | | | |
| Weather Information | | | |
| Has it rained since the last inspection? ☑ Yes □No If yes, provide: Storm Start Date & Time 5/29/14 8:43AM Storm Duration (hrs):0.5Hrs Approximate Rainfall: 0.04 | | | |
| Weather at time of this inspection? 63° Sunny clear | | | |
| Discharge Information (A) | | | |
| Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No | | | |
| Are there any discharges at the time of inspection? □Yes ☑No | | | |
| Describe location of any discharges from the site: | | | |

INSPECTOR CERTIFICATION

| Project: | Wind Colebrook South | | |
|-------------------|-----------------------|--|--|
| Project Location: | Winsted- Norfolk Road | | |
| | Colebrook CT | | |
| Contractor: | No work being done | | |
| Address: | | | |
| | | | |
| | | | |
| Phone: | | | |
| Fax: | | | |

CONSTRUCTION INSPECTION & MAINTENANCE LOG

| Date | Activity | Description | (1) Report No. |
|---------|--|-------------------|------------------------|
| 5/1/14 | ☑ Inspection☑ Maintenance | By R Hurlbut LEI | Siting Council #147 |
| 5/12/14 | ☑ Inspection☑ Maintenance | By: R Hurlbut LEI | Siting Council #148 |
| 5/16/14 | ☑ Inspection❑ Maintenance | By: R Hurlbut LEI | Siting Council #149 |
| 5/23/14 | InspectionMaintenance | By: R Hurlbut LEI | Siting Council #150 |
| 5/29/14 | ☑ Inspection❑ Maintenance | By: R Hurlbut LEI | Siting Council #151 |
| | InspectionMaintenance | | |

SITE-SPECIFIC BMPs

| (B) | BMP Description | BMP Installed and Operating | Corrective Action Needed | Date for corrective action / responsible |
|-----|---|--------------------------------|--|---|
| ~ / | real real real real real real real real | Properly? | | party |
| 1 | Anti Tracking Pad | ⊠Yes □No | None | |
| 2 | Sediment & Erosion Control Barriers around perimeter of site | ⊠Yes □No | | |
| 3 | Temp Sediment Basins | ⊠Yes □No | | |
| 4 | Sediment & Erosion Control Barriers | □Yes ØNo | Silt fence needs to be installed at TST 2 | After snow melts |
| 5 | Temp ground cover | □Yes ØNo | Temp seeding need to be done in vicinity of TST 2 & detention basin 2 on Tower 1 site | Slopes adjacent to sediment basins have been seeded & are growing 5/30/14 |
| 6 | Temp ground cover | □Yes ØNo | Tower 2 area should be temporarily seeded & mulched | Seeded areas have sprouted & are growing 5/30/14 |
| 7 | | □Yes □No | | |
| 8 | | □Yes □No | | |
| 9 | | □Yes □No | | |
| 10 | | □Yes □No | | |
| 11 | | □Yes □No | | |
| 12 | | □Yes □No | | |
| 13 | | □Yes □No | | |
| 14 | | □Yes □No | | |
| 15 | | □Yes □No | | |
| 17 | | □Yes □No | | |
| 18 | | □Yes □No | | |

OVERALL SITE ISSUES

| | ERALL SITE ISSUES | , | | | |
|-----|--|--------------|-------------|--|--|
| (C) | BMP/activity | Implemented? | Maintained? | Corrective Action | Date for corrective action/responsible person |
| 1 | Are all slopes and disturbed areas not actively being worked properly stabilized? | □Yes ØNo | □Yes □No | Inactive slopes adjacent to basin 2 need to be stabilized | Slopes in vicinity of detention basins have sprouted 5/30/14 |
| 2 | Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs? | ⊠Yes □No | ⊠Yes ⊐No | | |
| 3 | Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained? | ⊠Yes □No | ØYes □No | | |
| 4 | Are discharge points and receiving waters free of sediment deposits? | ⊠Yes □No | ⊠Yes □No | | |
| 5 | Are storm drain inlets properly protected? | □Yes □No | □Yes □No | | N/A |
| 7 | Is trash/litter from work areas collected and placed in covered dumpsters? | ⊠Yes □No | ⊠Yes □No | | |

| (C) | BMP/activity | Implemented? | Maintained? | Corrective Action | Date for corrective action/responsible person |
|-----|---|--------------|-------------|-------------------|--|
| 8 | Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained? | □Yes □No | □Yes □No | | N/A |
| 9 | Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material? | □Yes □No | □Yes □No | | N/A |
| 10 | Are materials that are potential stormwater contaminants stored inside or under cover? | □Yes □No | □Yes □No | | N/A |
| 11 | Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled? | □Yes □No | □Yes □No | | N/A |
| 12 | (Other) | □Yes □No | □Yes □No | | |
| 13 | (Other) | □Yes □No | □Yes □No | | |

Wind Colebrook South

GENERAL INSPECTION COMMENTS AND EXPLANATION

General Inspection Comments (D)

Some seeding of exposed soil areas has been undertaken & seed is starting to grow

Is other descriptive information attached to this inspection report? \Box Yes \Box No

| Plan Information (E) |
|--|
| Were all current plan BMP's in place at the time of inspection? □Yes ☑No Silt fence at TST # 2 Tower 1 Area not installed |
| Are additional BMP's required? □Yes ☑No |
| Does the plan need to be updated? |
| □Yes ⊠No |
| Explanation of additional BMP and Plan update requirements: |

| Name: | Roger Hurlbut |
|----------------|---------------|
| (Please print) | P II II + |
| Signature: _ | Roper Hur But |
| - | |

Title: <u>Independent(3rd party)</u> Inspector Date: <u>5/30/2014</u>