General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983	Report No.	159		
Date of Inspection:	July 26, 2014	Start / End Time:	12:00PM to 12:30 PM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office				
Describe present phase of construction:	No work on site				
Type of Inspection:   ☑ Regular □ Pre-storm event   □ During storm event □ Post-storm event					
Weather Information					
Has it rained since the last inspection? ☑ Yes □ No If yes, provide: Storm Start Date & Time 7/23/14 8:00 PM Storm Duration (hrs): 1.5+/- Approximate Rainfall: >0.60-in					
Weather at time of this inspection? 74° Clear					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No					
Are there any discharges at the time of inspection? □Yes ☑No					
Describe location of any discharges from the site:					

# INSPECTOR CERTIFICATION

Project:	Wind Colebrook South
Project Location:	Winsted- Norfolk Road
	Colebrook CT
Contractor:	No work being done
Address:	
Phone:	
Fax:	

# CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description	(1) Report No.
7/5/14	<ul><li>✓ Inspection</li><li>❑ Maintenance</li></ul>	By R Hurlbut LEI	Siting Council #156
7/12/14	<ul><li>✓ Inspection</li><li>❑ Maintenance</li></ul>	By: R Hurlbut LEI	Siting Council #157
7/15/14	<ul><li>✓ Inspection</li><li>❑ Maintenance</li></ul>	By: R Hurlbut LEI	Siting Council #158
7/26/14	<ul><li>✓ Inspection</li><li>❑ Maintenance</li></ul>	By: R Hurlbut LEI	Siting Council #159
	<ul><li>Inspection</li><li>Maintenance</li></ul>	By:	
	<ul><li>Inspection</li><li>Maintenance</li></ul>		

## SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	⊠Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	⊠Yes □No		
3	Temp Sediment Basins	⊠Yes □No		
4	Sediment & Erosion Control Barriers	□Yes ØNo	Silt fence needs to be installed at TST 2	After snow melts
5	Temp ground cover	□Yes ØNo	Temp seeding need to be done in vicinity of TST 2 & detention basin 2 on Tower 1 site	Slopes adjacent to sediment basins have been seeded & are growing
6	Temp ground cover	□Yes ØNo	Tower 2 area should be temporarily seeded & mulched	Seeded areas have are growing 6/27/14
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

# OVERALL SITE ISSUES

	CRALL SITE ISSUES				
(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	□Yes ØNo	□Yes □No	Inactive slopes adjacent to basin 2 need to be stabilized	Slopes in vicinity of detention basins are growing & stable 6/27/14
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	⊠Yes □No	⊠Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	⊠Yes □No	ØYes □No		
4	Are discharge points and receiving waters free of sediment deposits?	⊠Yes □No	ØYes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	⊠Yes □No	⊠Yes ⊐No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

## Wind Colebrook South

#### GENERAL INSPECTION COMMENTS AND EXPLANATION

General Inspection Comments (D)

Some seeding of exposed soil areas has been undertaken & seed is starting to grow

Is other descriptive information attached to this inspection report?  $\Box$  Yes  $\Box$  No

Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
□Yes ☑No Silt fence at TST # 2 Tower 1 Area not installed
Are additional BMP's required?
$\Box$ Yes $\blacksquare$ No
Does the plan need to be updated?
$\Box$ Yes $\blacksquare$ No
Explanation of additional BMP and Plan update requirements:

Name:	Roger Hurlbut	
(Please print	it) I (I +	
Signature:	t) Roper Hur But	_
C		

Title: <u>Independent(3<sup>rd</sup> party)</u> Inspector Date: <u>7/28/14</u>