General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	164
Date of Inspection:	August 28, 2014	Start / End Time:	4:45 PM to 5:15 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection: ☐ Regular ☐ Pre-storm e  Weather Information	vent During storm ev	vent ☑ Post-storm	event
Has it rained since the last ins  ✓ Yes □ No	pection?		
If yes, provide: Storm Start Date & Time Au	g 27 6Pm Storm Duratio	on 1.5 Hrs Approximate	e Rainfall: 0.16-in
Weather at time of this inspec	tion? 74° clear		
Discharge Information (A)			
Do you suspect that discharge ☐Yes ☐No	s may have occurred since	the last inspection?	
Are there any discharges at th ☐Yes ☑No	e time of inspection?		
Describe location of any disch	narges from the site:		

# INSPECTOR CERTIFICATION Project: Wind Colebrook South Project Location: Winsted- Norfolk Road Colebrook CT Contractor: No work being done Address: Phone: Fax:

### CONSTRUCTION INSPECTION & MAINTENANCE LOG

		D ::	(1) D (1)
Date	Activity	Description	(1) Report No.
8/1/14	☑ Inspection		Siting Council
	☐ Maintenance	By T Parsons LEI	#160
8/6/14	☑ Inspection		Siting Council
	☐ Maintenance	By: T Parsons LEI	#161
8/13/14	☑ Inspection		Siting Council
	☐ Maintenance	By: R Hurlbut LEI	#162
9/21/14	☑ Inspection		Siting Council
8/21/14	☐ Maintenance	By: R Hurlbut LEI	#163
0/20/14	☑ Inspection	Des D. Headhard, J. E.L.	Siting Council
8/28/14	☐ Maintenance	By: R Hurlbut LEI	#164
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		

# SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	☑Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	☑Yes □No		
3	Temp Sediment Basins	☑Yes □No		
4	Sediment & Erosion Control Barriers	✓Yes □No		
5	Temp ground cover	☑Yes □No		
6	Temp ground cover	☑Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

## **OVERALL SITE ISSUES**

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	⊠Yes □No	□Yes □No	Driveway access was regarded to reduce erosion	
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☑Yes □No	☑Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	☑Yes □No	☑Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	☑Yes □No	⊠Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	☑Yes □No	⊠Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

### GENERAL INSPECTION COMMENTS AND EXPLANATION

GENERAL INSPECTION COMMENTS AND EXPLANATION
General Inspection Comments (D)
Gravel driveway access to site has been regarded to reduce erosion
Is other descriptive information attached to this inspection report?
□Yes ☑No
Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
✓ Yes □No
Are additional BMP's required?
□Yes ☑No
Does the plan need to be updated?
□Yes ☑No
Explanation of additional BMP and Plan update requirements:
Name: Roger Hurlbut
(Please print) Roper Hurlbut
Signature:
Title: Independent(3 <sup>rd</sup> party) Inspector Date: 9/2/2014