General Information				
Project Name:	Wind Colebrook South			
Location:	Winsted- Norfolk Road			
	Colebrook, Connecticut CSC Petition 983 Report No. 174			
CT DEP Tracking No.		Report No.	174	
Date of Inspection:	Oct 31, 2014 Start / End Time: 4:45PM to 5:15PM			
Inspector's Name(s):	Roger Hurlbut			
Inspector's Title(s):	Project Engineer			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office			
Describe present phase of construction:	No work on site			
Type of Inspection: □ Regular □ Pre-storm event □ During storm event □ Post-storm event				
Weather Information				
Has it rained since the last ins ☑Yes □ No	pection?			
If yes, provide: Storm Start Date & Time Oct 26 2:30Am Storm Duration 2 Hrs Approximate Rainfall: >0.12				
Weather at time of this inspection? 45 Overcast				
Discharge Information (A)				
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No				
Are there any discharges at the time of inspection? ☐Yes ☐No				
Describe location of any discl	narges from the site:			

INSPECTOR CERTIFICATION Project: Wind Colebrook South Project Location: Winsted- Norfolk Road Colebrook CT Contractor: No work being done Address: Phone: Fax:

CONSTRUCTION INSPECTION & MAINTENANCE LOG

		D : :	(1) D (N
Date	Activity	Description	(1) Report No.
10/2/14	☑ Inspection		Siting Council
	☐ Maintenance	By R Hurlbut LEI	#169
10/5/14	☑ Inspection		Siting Council
10/3/14	☐ Maintenance	By: R Hurlbut LEI	#170
10/9/14	☑ Inspection		Siting Council
10/9/14	☐ Maintenance	By: R Hurlbut LEI	#171
10/16/14	☑ Inspection		Siting Council
10/16/14	☐ Maintenance	By: R Hurlbut LEI	#172
10/22/14	☐ Inspection	Dva D Hardbut I EI	Siting Council
10/23/14	☐ Maintenance	By: R Hurlbut LEI	#173
10/21/14	☐ Inspection	D. D. Hardhat J. E.I.	Siting Council
10/31/14	☐ Maintenance	By: R Hurlbut LEI	#174
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		

SITE-SPECIFIC BMPs

	-SPECIFIC DWFS	BMP Installed		Date for corrective
(B)	BMP Description	and Operating Properly?	Corrective Action Needed action / responsible party	
1	Anti Tracking Pad	☑Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	☑Yes □No	Fence has been cut or lowered in stabilized areas to allow movement of animals	
3	Temp Sediment Basins	☑Yes □No	Stable and functioning	
4	Sediment & Erosion Control Barriers	✓Yes □No		
5	Temp ground cover	☑Yes □No	A majority of site is stable and growing good vegetation	
6		□Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	☑Yes □No	☑Yes □No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☑Yes □No	☑Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	☑Yes □No	☑Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	☑Yes □No	☑Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	☑Yes □No	☑Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

GENERAL INSPECTION COMMENTS AND EXPLANATION

GENERAL INSI ECTION COMMENTS AND EXILEMENTATION				
General Inspection Comments (D)				
No work currently being undertaken and a majority of the site has well established vegetation.				
One gravel area is level and has adequate S&E controls				
Is other descriptive information attached to this inspection report? ☐Yes ☐No				
Plan Information (E)				
Were all current plan BMP's in place at the time of inspection? ☑Yes □No				
Are additional BMP's required? ☐Yes ☐No				
Does the plan need to be updated? ☐Yes ☐No				
Explanation of additional BMP and Plan update requirements:				
Name:Roger Hurlbut				
(Please print) Signature: Roper Hur but				
Signature:				
Title: <u>Independent(3rd party) Inspector</u> Date: <u>11/3/2014</u>				