General Information				
Project Name:	Wind Colebrook South			
Location:	Winsted- Norfolk Road			
	Colebrook, ConnecticutCSC Petition 983Report No.178			
CT DEP Tracking No.		Report No.	178	
Date of Inspection:	Nov 24, 2014	Start / End Time:	7:30Am to 8:00AM	
Inspector's Name(s):	Roger Hurlbut			
Inspector's Title(s):	Project Engineer			
Inspector's Contact Information:	LENARD ENGINEERING 860 379-6669 office	INC		
Describe present phase of construction:	No work on site			
Type of Inspection: P Regular Pre-storm ev	vent <b>D</b> During storm ev	vent Post-storm e	event	
Weather Information				
Has it rained since the last inspection? ☑Yes □P No If yes, provide: Storm Start Date & Time 11-24-14 3:12 AM Storm Duration 6 Hrs Approximate Rainfall: >0.79-in				
Weather at time of this inspection? 55°F Overcast/light rain				
Discharge Information (A)				
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No				
Are there any discharges at the time of inspection? □Yes ☑No				
Describe location of any discharges from the site:				

# INSPECTOR CERTIFICATION

Project:	Wind Colebrook South		
Project Location:	Winsted- Norfolk Road		
	Colebrook CT		
Contractor:	No work being done		
Address:			
Phone:			
Fax:			

# CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description	(1) Report No.
11/7/14	<ul><li>✓ Inspection</li><li>❑ Maintenance</li></ul>	By R Hurlbut LEI	Siting Council #175
11/13/14	<ul><li>✓ Inspection</li><li>❑ Maintenance</li></ul>	By: R Hurlbut LEI	Siting Council #176
11/17/14	<ul><li>☑ Inspection</li><li>❑ Maintenance</li></ul>	By: R Hurlbut LEI	Siting Council #177
11/24/14	<ul><li>✓ Inspection</li><li>❑ Maintenance</li></ul>	By: R Hurlbut LEI	Siting Council #178
	<ul><li>Inspection</li><li>Maintenance</li></ul>		

## SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	⊠Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	⊠Yes □No	Fence has been cut or lowered in stabilized areas to allow movement of animals	
3	Temp Sediment Basins	⊠Yes □No	Stable and functioning	
4	Sediment & Erosion Control Barriers	⊠Yes □No		
5	Temp ground cover	⊠Yes □No	A majority of site is stable and growing good vegetation	
6		□Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

# OVERALL SITE ISSUES

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	⊠Yes □No	⊠Yes □No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	⊠Yes □No	⊠Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	⊠Yes □No	⊠Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	⊠Yes □No	ØYes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	ØYes □No	⊠Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

## Wind Colebrook South

#### GENERAL INSPECTION COMMENTS AND EXPLANATION

General Inspection Comments (D)

No work currently being undertaken and a majority of the site has well established vegetation.

One gravel area is level and has adequate S&E controls

Is other descriptive information attached to this inspection report?  $\Box$  Yes  $\Box$  No

Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
$\square$ Yes $\square$ No
Are additional BMP's required?
$\Box$ Yes $\blacksquare$ No
Does the plan need to be updated?
$\Box$ Yes $\blacksquare$ No
Explanation of additional BMP and Plan update requirements:

Name:	Roger Hurlbut
(Please print)	P II II +
Signature:	Roper Hurlbut
-	

Title: <u>Independent(3<sup>rd</sup> party)</u> Inspector Date: <u>12/1/2014</u>