



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut *Roger Hurlbut*  
**Date:** Dec 29, 2014  
**Re:** BNE Wind Colebrook South

---

Attached are environmental erosion and sediment control monitoring reports numbers 182 and 183 for the period Dec 13, thru Dec 26, 2014

No work on site & areas are stable

CC Greg Zupkus BNE Energy

| General Information  |   |                   |                    |
|--|---|-------------------|--------------------|
| Project Name:  | Wind Colebrook South                            |                   |                    |
| Location:  | Winsted- Norfolk Road<br>Colebrook, Connecticut |                   |                    |
| CT DEP Tracking No.  | CSC Petition 983                                | Report No.        | <b>182</b>         |
| Date of Inspection:  | Dec 18, 2014                                    | Start / End Time: | 4:00 PM to 4:30 PM |
| Inspector's Name(s):   | Roger Hurlbut                                   |                   |                    |
| Inspector's Title(s):  | Project Engineer                                |                   |                    |
| Inspector's Contact Information:   | LENARD ENGINEERING INC<br>860 379-6669 office   |                   |                    |
| Describe present phase of construction:  | No work on site                                 |                   |                    |
| Type of Inspection:<br><input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event                                    |   |                   |                    |
| Weather Information  |   |                   |                    |
| Has it rained since the last inspection?<br><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br>If yes, provide:<br>Storm Start Date & Time 12/16 & 17/2014    Storm Duration    Approximate Rainfall 0.19 & 0.17 |   |                   |                    |
| Weather at time of this inspection? 33°F    Cldy   |   |                   |                    |
| Discharge Information (A)  |   |                   |                    |
| Do you suspect that discharges may have occurred since the last inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No   |   |                   |                    |
| Are there any discharges at the time of inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No   |   |                   |                    |
| Describe location of any discharges from the site:   |   |                   |                    |

| General Information  |   |                   |                    |
|--|---|-------------------|--------------------|
| Project Name:  | Wind Colebrook South                            |                   |                    |
| Location:  | Winsted- Norfolk Road<br>Colebrook, Connecticut |                   |                    |
| CT DEP Tracking No.  | CSC Petition 983                                | Report No.        | <b>183</b>         |
| Date of Inspection:  | Dec 24, 2014                                    | Start / End Time: | 2:00 PM to 2:30 PM |
| Inspector's Name(s):   | Roger Hurlbut                                   |                   |                    |
| Inspector's Title(s):  | Project Engineer                                |                   |                    |
| Inspector's Contact Information:   | LENARD ENGINEERING INC<br>860 379-6669 office   |                   |                    |
| Describe present phase of construction:  | No work on site                                 |                   |                    |
| Type of Inspection:<br><input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event                                      |   |                   |                    |
| Weather Information  |   |                   |                    |
| Has it rained since the last inspection?<br><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No<br>If yes, provide:<br>Storm Start Date & Time 12/23 & 24/2014    Storm Duration    Approximate Rainfall    0.13& 0.36 |   |                   |                    |
| Weather at time of this inspection? 41°F    Overcast light rain  |   |                   |                    |
| Discharge Information (A)  |   |                   |                    |
| Do you suspect that discharges may have occurred since the last inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No   |   |                   |                    |
| Are there any discharges at the time of inspection?<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No   |   |                   |                    |
| Describe location of any discharges from the site:   |   |                   |                    |