General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road		
	Colebrook, ConnecticutCSC Petition 983Report No.184		
CT DEP Tracking No.		Report No.	184
Date of Inspection:	Dec 31, 2014	Start / End Time:	2:00 PM to 2:30 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING 860 379-6669 office	INC	
Describe present phase of construction:	No work on site		
Type of Inspection: ☑ Regular □Pre-storm ev	vent During storm ever	nt Post-storm e	event
Weather Information			
Has it rained since the last inspection? □Yes ☑No			
If yes, provide: Storm Start Date & Time 12/23 & 24/2014 Storm Duration Approximate Rainfall 0.13& 0.36			
Weather at time of this inspection? 25°F PT Cldy			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No			
Are there any discharges at the time of inspection? □Yes ☑No			
Describe location of any discharges from the site:			

INSPECTOR CERTIFICATION

Project:	Wind Colebrook South		
Project Location:	Winsted- Norfolk Road		
	Colebrook CT		
Contractor:	No work being done		
Address:			
Phone:			
Fax:			

CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description	(1) Report No.
12/5/14	☑ Inspection❑ Maintenance	By R Hurlbut LEI	Siting Council #179
12/7/14	✓ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #180
12/10/14	☑ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #181
12/18/14	✓ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #182
12/24/14	☑ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #183
12/31/14	☑ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #184
	InspectionMaintenance		

SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	⊠Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	⊠Yes □No	Fence has been cut or lowered in stabilized areas to allow movement of animals	
3	Temp Sediment Basins	⊠Yes □No	Stable and functioning	
4	Sediment & Erosion Control Barriers	⊠Yes □No		
5	Temp ground cover	⊠Yes □No	A majority of site is stable and growing good vegetation	
6		□Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	⊠Yes □No	⊠Yes □No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	⊠Yes □No	⊠Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	⊠Yes □No	⊠Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	⊠Yes □No	ØYes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	ØYes □No	⊠Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

Wind Colebrook South

GENERAL INSPECTION COMMENTS AND EXPLANATION

General Inspection Comments (D)

No work currently being undertaken and a majority of the site has well established vegetation.

One gravel area is level and has adequate S&E controls

Is other descriptive information attached to this inspection report? \Box Yes \Box No

Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
⊠Yes □No
Are additional BMP's required?
□Yes ☑No
Does the plan need to be updated?
□Yes ☑No
Explanation of additional BMP and Plan update requirements:

Name:	_Roger Hurlbut
(Please print	
Signature:) Roper Hurlbut
C	

Title: <u>Independent(3rd party)</u> Inspector Date: <u>12/31/2014</u>