General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road		
	Colebrook, ConnecticutCSC Petition 983Report No.188		
CT DEP Tracking No.		Report No.	188
Date of Inspection:	Jan 30, 2015	Start / End Time:	4:30 PM to 5:00PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING 860 379-6669 office	INC	
Describe present phase of construction:	No work on site Ground is frozen & snow covered		
Type of Inspection: ☑ Regular □Pre-storm ev			
Weather Information			
Has it rained since the last inspection? □Yes ☑No If yes, provide: Storm Start Date & Time Storm Duration			
Weather at time of this inspection? 25°F cldy			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No			
Are there any discharges at the time of inspection? □Yes ☑No			
Describe location of any discharges from the site:			

INSPECTOR CERTIFICATION

Project:	Wind Colebrook South		
Project Location:	Winsted- Norfolk Road		
	Colebrook CT		
Contractor:	No work being done		
Address:			
Phone:			
Fax:			

CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description	(1) Report No.
1-8-15	✓ Inspection❑ Maintenance	By R Hurlbut LEI	Siting Council #185
1-16-15	✓ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #186
1-19-15	✓ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #187
1-30-15	✓ Inspection❑ Maintenance	By: R Hurlbut LEI	Siting Council #188
	☑ Inspection□ Maintenance		
	✓ Inspection❑ Maintenance		
	InspectionMaintenance		

SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	⊠Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	⊠Yes □No	Fence has been cut or lowered in stabilized areas to allow movement of animals	
3	Temp Sediment Basins	⊠Yes □No	Stable and functioning	
4	Sediment & Erosion Control Barriers	⊠Yes □No		
5	Temp ground cover	⊠Yes □No	A majority of site is stable and growing good vegetation	
6		□Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	⊠Yes □No	⊠Yes □No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	⊠Yes □No	⊠Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	⊠Yes □No	⊠Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	⊠Yes □No	⊠Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	⊠Yes □No	⊠Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

Wind Colebrook South

GENERAL INSPECTION COMMENTS AND EXPLANATION

General Inspection Comments (D)

No work currently being undertaken and a majority of the site has well established vegetation.

One gravel area is level and has adequate S&E controls

Is other descriptive information attached to this inspection report? \Box Yes \Box No

Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
⊠Yes □No
Are additional BMP's required?
\Box Yes \blacksquare No
Does the plan need to be updated?
\Box Yes \blacksquare No
Explanation of additional BMP and Plan update requirements:

Name:	Roger Hurlbut
(Please print)	Roper Hur Ibut
Signature: _	10per Hur Ibur

Title: <u>Independent(3rd party)</u> Inspector Date: <u>2/6/2015</u>