Memorandum

To: Dr. Michael Klemens

From: Roger Hurlbut Roger Hurlbut

Date: | March 19, 2015

Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 194and 195 for the period March 7, 2015 thru March 20, 2015

Ground is frozen & snow covered.

.

CC Greg Zupkus BNE Energy

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983	Report No.	194		
Date of Inspection:	March 13, 2015	Start / End Time:	7:30 AM to 8:00AM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office				
Describe present phase of construction:	Ground is frozen & snow covered				
Type of Inspection: ☑ Regular □ Pre-storm event □ During storm event □ Post-storm event					
Weather Information					
Has it rained since the last inspection? □Yes ☑No					
If yes, provide:					
Storm Start Date & Time Storm Duration Approximate Rainfall					
Weather at time of this inspection? 17°F Pt Cldy					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No					
Are there any discharges at the time of inspection? ☐Yes ☐No					
Describe location of any discharges from the site:					

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983	Report No.	195		
Date of Inspection:	March 16, 2015	Start / End Time:	7:30 AM to 8:00AM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office				
Describe present phase of construction:	Ground is frozen & snow covered				
Type of Inspection: □Regular □Pre-storm event □During storm event □Post-storm event					
Weather Information					
Has it rained since the last inspection? ☑Yes □No					
If yes, provide: Storm Start Date & Time3/14/15 9AM Storm Duration 9Hrs Approximate Rainfall 0.57in					
Weather at time of this inspection? 28°F Pt Cldy					
Discharge Information (A)					
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No					
Are there any discharges at the time of inspection? ☐Yes ☑No					
Describe location of any discharges from the site:					