Memorandum

To: Dr. Michael Klemens

From: Roger Hurlbut Roger How but

Date: May 1, 2015

Re: BNE Wind Colebrook South

Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 201, 202 and 203 for the period April 18, 2015 thru May 1, 2015

I was on site yesterday and addition controls will be installed today Mike I will get you the CT DEEP reports for April on Monday or Tuesday

.

CC Greg Zupkus BNE Energy Sam McGriff Ryan Company

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road				
	Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983	Report No.	201		
Date of Inspection:	April 21, 2015	Start / End Time:	4:00 PM to 4:30 PM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office				
Describe present phase of construction:	Site development equipment has been mobilized Entry access has been widened and regraded.				
Type of Inspection: □Regular □Pre-storm event □During storm event □Post-storm event					
Weather Information					
Has it rained since the last inspection? ✓ Yes □No					
If yes, provide:					
Storm Start Date & Time 4/20/2015 5:504AM Storm Duration 23Hrs Approximate Rainfall 1+					
Weather at time of this inspection? 50°F Overcast					
Discharge Information					
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No					
Are there any discharges at th ☐Yes ☐No	e time of inspection?				
Describe location of any discharges from the site:					

General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983	Report No.	202		
Date of Inspection:	April 24, 2015	Start / End Time:	4:00 PM to 4:30 PM		
Inspector's Name(s):	Roger Hurlbut				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office				
Describe present phase of construction:	Area for storm water pool at entrance has been cleared & grubbed, silt fence installed around perimeter.				
Type of Inspection: ☑Regular □Pre-storm event □During storm event □Post-storm event					
Weather Information					
Has it rained since the last inspection? ☐Yes ☑No					
If yes, provide:					
Storm Start Date & Time Storm Duration Approximate Rainfall Weather at time of this inspection? 39°F Pt sunny					
Discharge Information De von guarant that discharges may have accurred since the last inspection?					
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☐No					
Are there any discharges at the time of inspection? ☐Yes ☑No					
Describe location of any discharges from the site:					

General Information						
Project Name:	Wind Colebrook South	Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut					
CT DEP Tracking No.	CSC Petition 983	Report No.	203			
Date of Inspection:	April 30, 2015	Start / End Time:	2:30 PM to 4:30 PM			
Inspector's Name(s):	Roger Hurlbut					
Inspector's Title(s):	Project Engineer					
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office					
Describe present phase of construction:	Area for storm water pool at entrance has been cleared & grubbed, silt fence installed around perimeter. Contractor working on site in vicinity of Tower 1 S&E controls to be installed on 5/1/15 include: Anti tracking pad at entrance Addition S&E controls will be installed north of the access road in the vicinity of Sta 3+00 Water bars across the road will be installed					
Type of Inspection: ☑Regular □Pre-storm e	vent During storm eve	ent Post-storm	event			
Weather Information						
Has it rained since the last ins ☐Yes ☐No	spection?					
If yes, provide: Storm Start Date & Time Storm Duration Approximate Rainfall						
Weather at time of this inspec	Weather at time of this inspection? 60°F Pt sunny					
Discharge Information						
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No						
Are there any discharges at thus a superior of the discharges at	ne time of inspection?					
Describe location of any disc	harges from the site:					