General Information					
Project Name:	Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983 Report No. 203				
Date of Inspection:	April 30, 2015 Start / End Time: 2:30 PM to 4:30 PM				
Inspector's Name(s):	Roger Hurlbut	Roger Hurlbut			
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office				
Describe present phase of construction:	Area for storm water pool at entrance has been cleared & grubbed, silt fence installed around perimeter. Contractor working on site in vicinity of Tower 1 S&E controls to be installed on 5/1/15 include: Anti tracking pad at entrance Addition S&E controls will be installed north of the access road in the vicinity of Sta 3+00 Water bars across the road will be installed				
Type of Inspection: ☑Regular □Pre-storm event □During storm event □Post-storm event Weather Information					
Has it rained since the last inspection? ☐Yes ☐No					
If yes, provide: Storm Start Date & Time Storm Duration Approximate Rainfall					
Weather at time of this inspection? 60°F Pt sunny					
Discharge Information					
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☐No					
Are there any discharges at the time of inspection? □Yes ☑No					
Describe location of any discharges from the site:					

INSPECTOR CERTIFICATION

Project:	Wind Colebrook South	
Duningt I postion.	Winsted- Norfolk Road	
Project Location:	Colebrook CT	
Contractor:		
Address:		
Phone:		
Fax:		

CONSTRUCTION INSPECTION & MAINTENANCE LOG

CONSTI	RUCTION INSPECT	TON & MAINTENANCE LOG	
Date	Activity	Description	(1) Report No.
4/2/15	✓ Inspection✓ Maintenance	By R Hurlbut LEI	Siting Council #197
4/8/15	✓ Inspection✓ Maintenance	By: R Hurlbut LEI	Siting Council #198
4/9/15	✓ Inspection✓ Maintenance	By: R Hurlbut LEI	Siting Council #199
4/18/15	✓ Inspection✓ Maintenance	By: R Hurlbut LEI	Siting Council #200
4/21/15	✓ Inspection✓ Maintenance	By: R Hurlbut LEI	Siting Council #201
4/24/15	☑Inspection☑ Maintenance	By: R Hurlbut LEI	Siting Council #202
4/30/15	✓ Inspection✓ Maintenance	By: R Hurlbut LEI	Siting Council #203
5/1/15	☐ Inspection ☐ Maintenance	Installed ant tracking pad, water bars & additional S&E barriers	
	☐ Inspection☐ Maintenance		

SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	✓Yes □No	None - new tracking pad installed at entrance off Flag Hill Rd	5/1/15 Denovo
2	Sediment & Erosion Control Barriers around perimeter of site	⊠Yes □No	Fence has been cut or lowered in stabilized areas to allow movement of animals	None necessary
3	Temp Sediment Basins	☑Yes □No	Stable and functioning	None necessary
4	Sediment & Erosion Control Barriers	✓Yes □No	New Fencing has been installed around active areas	
5	Temp ground cover	✓Yes □No	Non active surfaces are stable	
6		□Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

	EKALL SITE ISSUES				· · · · · · · · · · · · · · · · · · ·
(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	⊠Yes □No	⊠Yes □No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☑Yes □No	☑Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	☑Yes □No	☑Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	☑Yes □No	⊠Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No	Nothing installed yet	N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	☑Yes □No	⊠Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	☑Yes □No	□Yes □No		
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

GENERAL INSPECTION COMMENTS AND EXPLANATION

GENERAL INSPECTION COMMENTS AND EXPLANATION
General Inspection Comments (D)
Site work has been reactivated with clearing grubbing and surface formation being undertaken in
vicinity of Tower 1 & 2 locations
Is ather descriptive information attached to this inspection percent?
Is other descriptive information attached to this inspection report? ☐Yes ☐No
Tes Eno
Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
☑Yes □No
Are additional BMP's required?
□Yes ☑No
Does the plan need to be updated?
□Yes ☑No
Explanation of additional BMP and Plan update requirements:
2. priminustra or unum 2.111 umu 1.1um up umo 1.0 quito monto.
Name:Roger Hurlbut
(Please print) Roper Hur but
Signature: _ Toper How bux
·
Title: Independent(3 rd party) Inspector Date: 5/4/2015

Wind Colebrook South March 2015