


Michael W. Klemens, LLC
POB 432
Falls Village, CT 06031
November 8th, 2015

Melanie Bachman
Acting Executive Director
CT Siting Council
[Via Email to Siting.Council@CT.gov](mailto:Siting.Council@CT.gov)

Dear Ms. Bachman:

Please find enclosed the one hundred and second bi weekly third party environmental monitoring reports prepared by Lenard Engineering for the Colebrook South Site Wind Turbine Site (Petition 983) as well as the October DEEP storm water reports. The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. If you require additional information, please do not hesitate to contact me.

Sincerely,

A handwritten signature in cursive script, appearing to read "Michael W. Klemens".

Michael W. Klemens, PhD
860-824-8185 (land)
203-448-8068 (mobile)



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: October 29, 2015
Re: BNE Wind Colebrook South

Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 233 and 234 for the period Oct 17, 2015 thru October 30, 2015.

No problems observed. Some erosion within disturbed areas, but nothing to offsite areas.

I have continued making siting council reports because the site has not been stabilized. (Vegetation is just beginning to sprout & road was not paved) Hopefully paving is finished this week and next weeks predicted temperatures allow for more vegetation growth.

CC Greg Zupkus, BNE Energy

| General Information | | | |
|--|--|-------------------|------------------|
| Project Name: | Wind Colebrook South | | |
| Location: | Winsted- Norfolk Road Colebrook, Connecticut | | |
| CT DEP Tracking No. | CSC Petition 983 CT GSN 002270 | Report No. | 233 |
| Date of Inspection: | October 25, 2015 | Start / End Time: | 3:00PM to 3:30PM |
| Inspector's Name(s): | Roger Hurlbut | | |
| Inspector's Title(s): | Project Engineer | | |
| Inspector's Contact Information: | LENARD ENGINEERING INC 860 379-6669 office | | |
| Describe present phase of construction: | <p>Sediment and Erosion controls in place and functioning properly.</p> <p>Towers 1 & 2 have been completed but are not on line yet Site grading, top soiling and hydroseeding of most of the disturbed areas has been completed. Road is being graded prior to paving</p> | | |
| Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event | | | |
| Weather Information | | | |
| Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time Hrs10/25/15 4:20 AM Storm Duration 4.5 Approximate Rainfall 0.15 | | | |
| Weather at time of this inspection? 55°F Clear light clouds | | | |
| Discharge Information | | | |
| Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | |
| Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | |
| Describe location of any discharges from the site: -. | | | |

| General Information | | | |
|---|---|-------------------|------------|
| Project Name: | Wind Colebrook South | | |
| Location: | Winsted- Norfolk Road Colebrook, Connecticut | | |
| CT DEP Tracking No. | CSC Petition 983 CT GSN 002270 | Report No. | 234 |
| Date of Inspection: | October 29, 2015 | Start / End Time: | 8AM to 9AM |
| Inspector's Name(s): | Roger Hurlbut | | |
| Inspector's Title(s): | Project Engineer | | |
| Inspector's Contact Information: | LENARD ENGINEERING INC 860 379-6669 office | | |
| Describe present phase of construction: | <p>Site grading, top soiling and hydroseeding of most of the disturbed areas has been completed.</p> <p>Vegetation is just beginning to sprout</p> <p>Road paving is being undertaken</p> <p>Some riling and erosion on site no discharges off site</p> | | |
| Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event | | | |
| Weather Information | | | |
| Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 10/28/15 2:30pm Storm Duration 16 Hrs Approximate Rainfall 1.6 | | | |
| Weather at time of this inspection? 62°F partly cloudy | | | |
| Discharge Information | | | |
| Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | |
| Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | |
| Describe location of any discharges from the site: -. | | | |



**Connecticut Department of
Energy & Environmental Protection**
Bureau of Materials Management & Compliance Assurance
Water Permitting & Enforcement Division

**General Permit for the Discharge of Stormwater and Dewatering Wastewaters from
Construction Activities, issued 8/21/13, effective 10/1/13**
Stormwater Monitoring Report

SITE INFORMATION

Permittee: BNE Energy

Mailing Address: 29 South Main Street, Town Center, Suite 200, West Hartford, CT 06107

Business Phone: (800) 450-0503 ext.: _____ Fax: _____

Contact Person: _____ Title: _____

Site Name: Wind Colebrook South

Site Address: 17 & 29 Flagg Hill Rd, Colebrook, CT

Receiving Water (name, basin): Farmington 4302

Stormwater Permit No. GSN 002270

SAMPLING INFORMATION (Submit a separate form for each outfall)

Outfall Designation: C-201A Date/Time Collected: Oct 29, 2015 9:AM

Outfall Location(s) (lat/lon or map link): 41.9648 -73.1410

Person Collecting Sample: Roger hurlbut, PE, Lenard Engineering, Inc.

Storm Magnitude (inches): 1.6 inches Storm Duration (hours): 16 hours

Size of Disturbed Area at any time: 12 Acres

MONITORING RESULTS

| Sample # | Parameter | Method | Results (units) | Laboratory (if applicable) |
|----------|-----------|-------------------|-----------------|----------------------------|
| 1 | Turbidity | Hach DR 900 meter | 4 | |
| 2 | Turbidity | Hach DR 900 meter | 7 | |
| 3 | Turbidity | Hach DR 900 meter | 1 | |
| 4 | Turbidity | Hach DR 900 meter | 3 | |

(provide an attachment if more than 4 samples were taken for this outfall)

Avg = 4

STATEMENT OF ACKNOWLEDGMENT

I certify that the data reported on this document were prepared under my direction or supervision in accordance with the General Permit for the Discharge of Stormwater and Dewatering Wastewaters from Construction Activities. The information submitted is, to the best of my knowledge and belief, true, accurate and complete.

Authorized Official: _____

Signature: _____ Date: _____

Please send completed form to:

DEPARTMENT OF ENERGY & ENVIRONMENTAL PROTECTION
BUREAU OF MATERIALS MANAGEMENT AND COMPLIANCE ASSURANCE
79 ELM STREET
HARTFORD, CT 06106-5127
ATTN: NEAL WILLIAMS

| General Information | | | |
|---|---|-------------------|------------|
| Project Name: | Wind Colebrook South | | |
| Location: | Winsted- Norfolk Road Colebrook, Connecticut | | |
| CT DEP Tracking No. | CSC Petition 983 CT GSN 002270 | Report No. | 234 |
| Date of Inspection: | October 29, 2015 | Start / End Time: | 8AM to 9AM |
| Inspector's Name(s): | Roger Hurlbut | | |
| Inspector's Title(s): | Project Engineer | | |
| Inspector's Contact Information: | LENARD ENGINEERING INC 860 379-6669 office | | |
| Describe present phase of construction: | <p>Site grading, top soiling and hydroseeding of most of the disturbed areas has been completed.</p> <p>Vegetation is just beginning to sprout</p> <p>Road paving is being undertaken</p> <p>Some riling and erosion on site no discharges off site</p> | | |
| Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event | | | |
| Weather Information | | | |
| Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 10/28/15 2:30pm Storm Duration 16 Hrs Approximate Rainfall 1.6 | | | |
| Weather at time of this inspection? 62°F partly cloudy | | | |
| Discharge Information | | | |
| Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | |
| Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | |
| Describe location of any discharges from the site: -. | | | |

INSPECTOR CERTIFICATION

| | |
|-------------------|---------------------------------------|
| Project: | Wind Colebrook South |
| Project Location: | Winsted- Norfolk Road Colebrook CT |
| Contractor: | Canton Village Construction |
| Address: | CVC currently on site for paving only |
| Phone: | |
| Fax: | |

CONSTRUCTION INSPECTION & MAINTENANCE LOG

| Date | Activity | Description | (1) Report No. |
|------------|--|-------------------|---------------------|
| 10-8-2015 | <input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | By R Hurlbut LEI | Siting Council #231 |
| 10-14-2015 | <input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | By: R Hurlbut LEI | Siting Council #232 |
| 10-25-2015 | <input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | By: R Hurlbut LEI | Siting Council #233 |
| 10-29-2015 | <input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | By: R Hurlbut LEI | Siting Council #234 |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |
| | <input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance | | |

SITE-SPECIFIC BMPs

| (B) | BMP Description | BMP Installed and Operating Properly? | Corrective Action Needed | Date for corrective action / responsible party |
|-----|--|---|--|--|
| 1 | Anti Tracking Pad | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | None - new tracking pad installed at entrance off Flag Hill Rd | None necessary |
| 2 | Sediment & Erosion Control Barriers around perimeter of site | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Fence has been cut or lowered in stabilized areas to allow movement of animals | None necessary |
| 3 | Temp Sediment Basins | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Stable and functioning | None necessary |
| 4 | Sediment & Erosion Control Barriers | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | New Fencing has been installed around active areas | |
| 5 | Temp ground cover | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Non active surfaces are stable | |
| 6 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 7 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 8 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 9 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 10 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 11 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 12 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 13 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 14 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 15 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 17 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 18 | | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |

OVERALL SITE ISSUES

| (C) | BMP/activity | Implemented? | Maintained? | Corrective Action | Date for corrective action/responsible person |
|-----|---|---|---|--|---|
| 1 | Are all slopes and disturbed areas not actively being worked properly stabilized? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 2 | Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 3 | Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 4 | Are discharge points and receiving waters free of sediment deposits? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 5 | Are storm drain inlets properly protected? | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | Installed drains are elevated and do not require protection at this time | N/A |
| 7 | Is trash/litter from work areas collected and placed in covered dumpsters? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |


| (C) | BMP/activity | Implemented? | Maintained? | Corrective Action | Date for corrective action/responsible person |
|-----|--|---|---|-------------------|---|
| 8 | Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained? | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | | N/A |
| 9 | Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 10 | Are materials that are potential stormwater contaminants stored inside or under cover? | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | | N/A |
| 11 | Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled? | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 12 | (Other) | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 13 | (Other) | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | | |

GENERAL INSPECTION COMMENTS AND EXPLANATION

| |
|--|
| General Inspection Comments (D) |
| Towers have been erected, Planting/hydroseeding of exposed areas has been completed, Access is being paved as of 10/29 Site Contractor (Denovo) has completed work & removed equipment from site Necessary temporary S&E controls are in place |
| |
| |
| Is other descriptive information attached to this inspection report? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |

| |
|--|
| Plan Information (E) |
| Were all current plan BMP's in place at the time of inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Are additional BMP's required? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Does the plan need to be updated? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Plans for as constructed site will be necessary |
| Explanation of additional BMP and Plan update requirements: |

Name: Roger Hurlbut

Signature:  (Please print)

Title: Independent(3rd party) Inspector Date: 11/4/2015