


Michael W. Klemens, LLC
POB 432
Falls Village, CT 06031
June 27, 2015

Melanie Bachman
Acting Executive Director
CT Siting Council
Via Email to Siting.Council@CT.gov



Dear Ms. Bachman:

Please find enclosed the ninety-third bi weekly third party environmental monitoring reports prepared by Lenard Engineering of the Colebrook South Site Wind Turbine Site (Petition 983). The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. The 2015 annual amphibian monitoring report of the two cryptic vernal pools on site was filed electronically earlier today.

If you require additional information, please do not hesitate to contact me.

Sincerely,

A handwritten signature in cursive script, appearing to read "Michael W. Klemens".

Michael W. Klemens, PhD
860-824-8185 (land)
203-448-8068 (mobile)



Lenard Engineering Inc. Civil, Environmental, and Hydrogeological Consultants
140 Willow Street – Suite #8 Winsted, CT 06098 Tel: 860-379-6669 Fax: 860-738-1272

Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: June 26, 2015
Re: BNE Wind Colebrook South

Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 211, 212, 213 and 214 for the period June 13, 2015 thru June 26, 2015.

Work is progressing and they have been attentive to installing S&E controls as necessary.

CC Greg Zupkus, BNE Energy
Sam McGriff, Ryan Company

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	211
Date of Inspection:	June 15, 2015	Start / End Time:	7AM to 8AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Contractor constructing roadway & tower bases preparations Sediment and Erosion controls in place and functioning properly. Runoff from site was clear.		
Type of Inspection:	<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 6/15/15 3 AM Storm Duration: Continual Approximate Rainfall >1.5 at time of inspection			
Weather at time of this inspection? 61°F Rain			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	212
Date of Inspection:	June 21, 2015	Start / End Time:	8:30AM to 9:30AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Contractor constructing roadway & tower bases preparations Sediment and Erosion controls in place and functioning properly. Runoff from site was clear.		
Type of Inspection:	<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 6/20/15 3 PM Storm Duration: Intermittent 19hr Approximate Rainfall +/- .9 in			
Weather at time of this inspection? 66°F Rain			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	213
Date of Inspection:	June 24, 2015	Start / End Time:	7:30AM to 9:30AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	<p>Contractor constructing roadway & tower bases preparations</p> <p>Sediment and Erosion controls in place and functioning properly.</p> <p>Runoff from site was clear.</p> <p>Repairs or additional controls necessary see attached memo</p>		
Type of Inspection:			
<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time Intense Thunderstorms in PM Storm Duration: .5 Hr Approximate Rainfall +/- .8 in			
Weather at time of this inspection? 62°F Pt Sunny			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			



Memorandum

To: Sam McGriff (Ryan Company)
From: Roger Hurlbut *Roger Hurlbut*
Date: June 24, 2015
Re: BNE Wind Colebrook South

Today's inspections indicated there were no problems or discharges from the Colebrook site as a result of yesterday's rain. However the following items should be addressed prior to the next expected storm event.

Additional sediment & erosion barriers should be installed at the bottom of the power trench in the vicinity of the electrical connectors at the northeast corner of the property (Dashiell Sheet 10).

The silt fence to the north of TST1 /Stormwater pond (Dashiel Sheet 11) near the entrance to the site should be repaired /enhanced. Recent activity has knocked portions of it over.

Additional S&E controls should be installed upstream of the Town Catch Basin immediately north (downhill) of the construction entrance. Either hay bales or silt fencing could be used to insure runoff from the site is directed overland away from the CB .

As a result of today's concrete deliveries Flag Hill Rd should be swept and the antitracking pad at the construction entrance should be refreshed.

CC Greg Zupkus, BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	214
Date of Inspection:	June 26, 2015	Start / End Time:	7:00AM to 7:30AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	<p>Contractor constructing roadway & tower bases preparations</p> <p>Sediment and Erosion controls in place and functioning properly.</p> <p>Runoff from site was clear.</p> <p>Repairs or additional controls listed in 6/24/15 memo had been implemented</p>		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time Storm Duration: Approximate Rainfall			
Weather at time of this inspection? 62°F overcast			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			