

Michael W. Klemens, LLC
POB 432
Falls Village, CT 06031
July 30, 2015

Melanie Bachman
Acting Executive Director
CT Siting Council
Via Email to Siting.Council@CT.gov

Dear Ms. Bachman:

Please find enclosed the ninety-fifth bi weekly third party environmental monitoring reports prepared by Lenard Engineering of the Colebrook South Site Wind Turbine Site (Petition 983). The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. If you require additional information, please do not hesitate to contact me.

Sincerely,



Michael W. Klemens, PhD
860-824-8185 (land)
203-448-8068 (mobile)



Lenard Engineering Inc. Civil, Environmental, and Hydrogeological Consultants

140 Willow Street – Suite #8 Winsted, CT 06098

Tel: 860-379-6669

Fax: 860-738-1272

Memorandum

To: Dr. Michael Klemens

From: Roger Hurlbut *Roger Hurlbut*

Date: July 24, 2015

Re: BNE Wind Colebrook South

Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 218 and 219 for the period July 11, 2015 thru July 24, 2015.

No problems observed, discussed additional minor S&E controls with S. McGriff Components are being delivered and assembled.

CC Greg Zupkus, BNE Energy
Sam McGriff, Ryan Company

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	218
Date of Inspection:	July 15, 2015	Start / End Time:	6:45PM to 7:15 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	<p>Contractor constructing roadway & tower base areas</p> <p>Sediment and Erosion controls in place and functioning properly.</p> <p>Heavy downpour to east of site but soils on site were dusty dry</p>		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time 7/14/15 8:00AM Storm Duration: 1.5 hrs Approximate Rainfall 0.08-in			
Weather at time of this inspection? 75°F pt cldy			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	219
Date of Inspection:	July 23, 2015	Start / End Time:	1:45PM to 2:30 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	<p>Contractor receiving and assembling tower components and preparing for erection</p> <p>Sediment and Erosion controls in place and functioning properly.</p>		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time	Storm Duration:	Approximate Rainfall	
Weather at time of this inspection? 75°F sunny light breeze			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			