Michael W. Klemens, LLC POB 432 Falls Village, CT 06031 July 31, 2015

Melanie Bachman
Acting Executive Director
CT Siting Council
Via Email to Siting.Council@CT.gov

Dear Ms. Bachman:

Please find enclosed the July DEEP storm water reports and a single third party environmental monitoring report (96th) prepared by Lenard Engineering of the Colebrook South Site Wind Turbine Site (Petition 983). The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. If you require additional information, please do not hesitate to contact me.

Sincerely,

Michael W. Klemens, PhD

860-824-8185 (land)

Offiles a Rhung

203-448-8068 (mobile)

General Information				
Project Name:	Wind Colebrook South			
Location:	Winsted- Norfolk Road Colebrook, Connecticut			
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270 Report No. 220			
Date of Inspection:	July 31, 2015	Start / End Time:	7:20 AM to 8:15 AM	
Inspector's Name(s):	Todd Parsons			
Inspector's Title(s):	Project Engineer			
Inspector's Contact Information:	LENARD ENGINEERING 860 379-6669 office	INC		
Describe present phase of construction:	Contractor receiving and assembling tower components and preparing for erection Sediment and Erosion controls in place and functioning properly. Contractor has components on site and is preparing to construct outlet for sediment basin at intersection of driveway and Flagg Hill Road			
Type of Inspection: □Regular □Pre-storm e	vent During storm even	nt ☑Post-storm e	wont	
Weather Information	vent	it EI Ost-storii e	event	
Has it rained since the last inspection? ✓ Yes □No				
If yes, provide: Storm Start Date & Time 7/30/15 4:00 PM Storm Duration: <1hr Approximate Rainfall 0.1"				
Weather at time of this inspection? 70°F sunny light breeze				
Discharge Information				
Do you suspect that discharges may have occurred since the last inspection? □Yes ☑No				
Are there any discharges at the time of inspection? ☐Yes ☐No				
Describe location of any discharges from the site:				

.

General Information					
Project Name:	oject Name: Wind Colebrook South				
Location:	Winsted- Norfolk Road Colebrook, Connecticut				
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	D			
Date of Inspection:	July 31, 2015	Start / End Time:	7:30AM to 8:15AM		
Inspector's Name(s):	Todd Parsons				
Inspector's Title(s):	Project Engineer				
Inspector's Contact Information:	LENARD ENGINEERING 860 379-6669 office	INC			
Describe present phase of construction:	Contractor receiving and assembling tower components and preparing for erection Sediment and Erosion controls in place and functioning properly. All sediment contained by silt fencing around disturbed areas or Temporary Sediment Basins. Components for outlet structure at sediment basin at intersection of driveway and Flagg Hill Road are on-site and contractor preparing to install. No runoff occurring				
Type of Inspection: □Regular □Pre-storm event □During storm event □Post-storm event Weather Information Has it rained since the last inspection? □Yes □No					
If yes, provide: Storm Start Date & Time 7/30/15 4:00PM Storm Duration: <1hr Approximate Rainfall 0.1 in					
Weather at time of this inspection? 70°F sunny light breezy					
Discharge Information					
Do you suspect that discharges may have occurred since the last inspection? ☐Yes ☑No					
Are there any discharges at the time of inspection? ☐Yes ☑No					
Describe location of any discharges from the site:					

INSPECTOR CERTIFICATION

Project:	Wind Colebrook South	
Project Leastion:	Winsted- Norfolk Road	
Project Location:	Colebrook CT	
Contractor:	Denovo Construction	
Address:	100 S Wacker Drive, STE LL1-50	
Chicago, Il. 60606		
Michael Vails, Site Manager		
Phone:	Cell at site 312-806-2433	
Fax:	ax: 312-733-9566	

CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description Description	(1) Report No.
7.1.2015	☑ Inspection	-	Siting Council
7-1-2015	☐ Maintenance	By R Hurlbut LEI	#216
7 10 2015	☑ Inspection		Siting Council
7-10-2015	☐ Maintenance	By: R Hurlbut LEI	#217
7-15-2015	☑ Inspection		Siting Council
7-13-2013	☐ Maintenance	By: R Hurlbut LEI	#218
7-23-2015	☑ Inspection		Siting Council
7-23-2013	☐ Maintenance	By: R Hurlbut LEI	#219
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		
	☐ Inspection		
	☐ Maintenance		

SITE-SPECIFIC BMPs

h .	DI Len le Divil 3			
(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	☑Yes □No	None - new tracking pad installed at entrance off Flag Hill Rd	None necessary
2	Sediment & Erosion Control Barriers around perimeter of site	⊠Yes □No	Fence has been cut or lowered in stabilized areas to allow movement of animals	None necessary
3	Temp Sediment Basins	☑Yes □No	Stable and functioning	None necessary
4	Sediment & Erosion Control Barriers	✓Yes □No	New Fencing has been installed around active areas	
5	Temp ground cover	☑Yes □No	Non active surfaces are stable	
6		□Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

	EXALL SITE ISSUES	<u>-</u>			
(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	⊠Yes □No	☑Yes □No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☑Yes □No	☑Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	☑Yes □No	☑Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	☑Yes □No	☑Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No	Nothing installed yet	N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	☑Yes □No	ĭYes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	☑Yes □No	□Yes □No		
10	Are materials that are potential stormwater contaminants stored inside or under cover?	☑Yes □No	□Yes □No		
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	☑Yes □No	□Yes □No		
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

GENERAL INSPECTION COMMENTS AND EXPLANATION

OLIVERAL INSI ECTION COMMENTS AND EXICATION
General Inspection Comments (D)
Site work is being undertaken in vicinity of Tower 1 & 2 locations and access road Bases for the
towers have been constructed
Is other descriptive information attached to this inspection report?
Yes ⊠No
ares Eno
Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
✓Yes □No
Are additional BMP's required?
☐Yes ☐No Additional S&E added along power access cleared area
Does the plan need to be updated?
□Yes □No
Explanation of additional BMP and Plan update requirements:
Name:Todd Parsons
(Please print)
$M = \binom{N}{N}$
Signatura: Jall Ke
Signature:
Title: <u>Independent(3rd party) Inspector</u> Date: <u>7/31/2015</u>



Connecticut Department of Energy & Environmental Protection

Bureau of Materials Management & Compliance Assurance Water Permitting & Enforcement Division

General Permit for the Discharge of Stormwater and Dewatering Wastewaters from Construction Activities, issued 8/21/13, effective 10/1/13 Stormwater Monitoring Report

SITE INFORMATION

Permittee: BNE Ener	gy					
Mailing Address: 29 South Main Street, Town Center, Suite 200, West Hartford, CT 06107						
Business Phone: (800	0) 450-0503	ext.:	Fax:			
Contact Person:		Title	e:			
Site Name: Wind Col	ebrook South					
Site Address: 17 & 29	Flagg Hill Rd, Colebro	ook, CT				
Receiving Water (nam	ne, basin): Farmington	4302				
Stormwater Permit No	. GSN 002270					
SAMPLING INFORM	ATION (Submit a sep	arate form for each outfa	all)			
Outfall Designation: _		Date/Time Co	ollected:			
Outfall Location(s) (lat	/lon or map link):					
Person Collecting San	nple: No sample collec	ted All runoff from site wa	as clear - S&E controls fu	inctioning properly		
Storm Magnitude (incl	nes):	Storm	Duration (hours):			
	a at any time: 12 Acres					
MONITORING RESULTS						
Sample #	Sample # Parameter Method Results (units) Laboratory (if applicable)					
1	Turbidity		Clear runoff July 2015			
2	Turbidity		Clear runoff July 2015			
3	Turbidity		Clear runoff July 2015			
	Turbidity		Clear runoff July 2015			
(provide an attachment if more than 4 samples were taken for this outfall) Avg =						
for the Discharge of Stor	orted on this document v	Wastewaters from Constructi	ction or supervision in accordion Activities. The informat	rdance with the General Permit ion submitted is, to the best of		
Authorized Official:						
Signature: Date:						
Please send completed form to: DEPARTMENT OF ENERGY & ENVIRONMENTAL PROTECTION BUREAU OF MATERIALS MANAGEMENT AND COMPLIANCE ASSURANCE 79 ELM STREET						

DEEP-WPED-SMR-015 1 of 1 Rev. 9/3/13

HARTFORD, CT 06106-5127 ATTN: NEAL WILLIAMS