


Michael W. Klemens, LLC
POB 432
Falls Village, CT 06031
September 4, 2015

Melanie Bachman
Acting Executive Director
CT Siting Council
Via Email to Siting.Council@CT.gov



Dear Ms. Bachman:

Please find enclosed the ninety-eighth bi weekly third party environmental monitoring reports prepared by Lenard Engineering for the Colebrook South Site Wind Turbine Site (Petition 983) as well as the August DEEP stormwater reports. The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. If you require additional information, please do not hesitate to contact me.

Sincerely,

Michael W. Klemens, PhD
860-824-8185 (land)
203-448-8068 (mobile)



Lenard Engineering Inc. Civil, Environmental, and Hydrogeological Consultants
140 Willow Street – Suite #8 Winsted, CT 06098 Tel: 860-379-6669 Fax: 860-738-1272

Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: Sept 4, 2015
Re: BNE Wind Colebrook South


Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 225 and 226 for the period August 22, 2015 thru Sept 4, 2015.

No problems observed.

CC Greg Zupkus, BNE Energy
Sam McGriff, Ryan Company

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	225
Date of Inspection:	August 28, 2015	Start / End Time:	7:00AM to 8:30 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Sediment and Erosion controls in place and functioning properly. Towers 1 & 2 have been erected and work on power transmission lines is being undertaken Access road drainage is being installed		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, provide: Storm Start Date & Time Storm Duration Approximate Rainfall			
Weather at time of this inspection? 54°F sunny light breeze			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	226
Date of Inspection:	September 4, 2015	Start / End Time:	7:00AM to 8:30 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Sediment and Erosion controls in place and functioning properly. Towers 1 & 2 have been erected and work on power transmission lines is being undertaken Access road drainage is being installed		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time	Storm Duration	Approximate Rainfall	
Weather at time of this inspection? 68°F sunny light breeze			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			



**Connecticut Department of
Energy & Environmental Protection**
Bureau of Materials Management & Compliance Assurance
Water Permitting & Enforcement Division

**General Permit for the Discharge of Stormwater and Dewatering Wastewaters from
Construction Activities, issued 8/21/13, effective 10/1/13**
Stormwater Monitoring Report

SITE INFORMATION

Permittee: BNE Energy

Mailing Address: 29 South Main Street, Town Center, Suite 200, West Hartford, CT 06107

Business Phone: (800) 450-0503 ext.: _____ Fax: _____

Contact Person: _____ Title: _____

Site Name: Wind Colebrook South

Site Address: 17 & 29 Flagg Hill Rd, Colebrook, CT

Receiving Water (name, basin): Farmington 4302

Stormwater Permit No. GSN 002270

SAMPLING INFORMATION (Submit a separate form for each outfall)

Outfall Designation: C-201A Date/Time Collected: August 11, 2015 10:15 AM

Outfall Location(s) (lat/lon or map link): 41.9648 -73.1410

Person Collecting Sample: Todd Parsons, PE, Lenard Engineering, Inc.

Storm Magnitude (inches): 0.75 inches Storm Duration (hours): 5 hours

Size of Disturbed Area at any time: 12 Acres

MONITORING RESULTS

Sample #	Parameter	Method	Results (units)	Laboratory (if applicable)
1	Turbidity	Hach DR 900 meter	13	
2	Turbidity	Hach DR 900 meter	37	
3	Turbidity	Hach DR 900 meter	37	
4	Turbidity	Hach DR 900 meter	29	

(provide an attachment if more than 4 samples were taken for this outfall)

Avg = 29

STATEMENT OF ACKNOWLEDGMENT

I certify that the data reported on this document were prepared under my direction or supervision in accordance with the General Permit for the Discharge of Stormwater and Dewatering Wastewaters from Construction Activities. The information submitted is, to the best of my knowledge and belief, true, accurate and complete.

Authorized Official: _____

Signature: _____ Date: _____

Please send completed form to:

DEPARTMENT OF ENERGY & ENVIRONMENTAL PROTECTION
BUREAU OF MATERIALS MANAGEMENT AND COMPLIANCE ASSURANCE
79 ELM STREET
HARTFORD, CT 06106-5127
ATTN: NEAL WILLIAMS

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	225
Date of Inspection:	August 28, 2015	Start / End Time:	7:00AM to 8:30 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Sediment and Erosion controls in place and functioning properly. Towers 1 & 2 have been erected and work on power transmission lines is being undertaken Access road drainage is being installed		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time	Storm Duration	Approximate Rainfall	
Weather at time of this inspection? 54°F sunny light breeze			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			

INSPECTOR CERTIFICATION

Project:	Wind Colebrook South
Project Location:	Winsted- Norfolk Road Colebrook CT
Contractor:	Denovo Construction
Address:	100 S Wacker Drive, STE LL1-50 Chicago, Il. 60606 <i>Michael Vails, Site Manager</i>
Phone:	Cell at site 312-806-2433
Fax:	312-733-9566

CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description	(1) Report No.
8-7-2015	<input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance	By T Parsons LEI	Siting Council #221
8-12-2015	<input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance	By: T Parsons LEI	Siting Council #222
8-17-2015	<input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance	By: R Hurlbut LEI	Siting Council #223
8-21-2015	<input checked="" type="checkbox"/> Inspection <input type="checkbox"/> Maintenance	By: R Hurlbut LEI	Siting Council #224
8-28-2015	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance	By: R Hurlbut LEI	Siting Council #225
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		
	<input type="checkbox"/> Inspection <input type="checkbox"/> Maintenance		

SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	None - new tracking pad installed at entrance off Flag Hill Rd	None necessary
2	Sediment & Erosion Control Barriers around perimeter of site	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Fence has been cut or lowered in stabilized areas to allow movement of animals	None necessary
3	Temp Sediment Basins	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Stable and functioning	None necessary
4	Sediment & Erosion Control Barriers	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	New Fencing has been installed around active areas	
5	Temp ground cover	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Non active surfaces are stable	
6		<input type="checkbox"/> Yes <input type="checkbox"/> No		
7		<input type="checkbox"/> Yes <input type="checkbox"/> No		
8		<input type="checkbox"/> Yes <input type="checkbox"/> No		
9		<input type="checkbox"/> Yes <input type="checkbox"/> No		
10		<input type="checkbox"/> Yes <input type="checkbox"/> No		
11		<input type="checkbox"/> Yes <input type="checkbox"/> No		
12		<input type="checkbox"/> Yes <input type="checkbox"/> No		
13		<input type="checkbox"/> Yes <input type="checkbox"/> No		
14		<input type="checkbox"/> Yes <input type="checkbox"/> No		
15		<input type="checkbox"/> Yes <input type="checkbox"/> No		
17		<input type="checkbox"/> Yes <input type="checkbox"/> No		
18		<input type="checkbox"/> Yes <input type="checkbox"/> No		

OVERALL SITE ISSUES

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
4	Are discharge points and receiving waters free of sediment deposits?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
5	Are storm drain inlets properly protected?	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No	Nothing installed yet	N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
10	Are materials that are potential stormwater contaminants stored inside or under cover?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
11	Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
12	(Other)	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
13	(Other)	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		

GENERAL INSPECTION COMMENTS AND EXPLANATION

General Inspection Comments (D)
Towers 1 & 2 have been erected, Site stabilization work is being undertaken in vicinity of Tower 1 & 2 locations and access road
Is other descriptive information attached to this inspection report? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Plan Information (E)
Were all current plan BMP's in place at the time of inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Are additional BMP's required? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Does the plan need to be updated? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Explanation of additional BMP and Plan update requirements: <i>Additional S&E added along power access cleared area, were added</i>

Name: Roger Hurlbut

Signature: *Roger Hurlbut* (Please print)

Title: Independent(3rd party) Inspector Date: 9/4/2015