


Michael W. Klemens, LLC  
POB 432  
Falls Village, CT 06031  
September 21, 2015



Melanie Bachman  
Acting Executive Director  
CT Siting Council  
[Via Email to Siting.Council@CT.gov](mailto:Via_Email_to_Siting_Council@CT.gov)

Dear Ms. Bachman:

Please find enclosed the ninety-ninth bi weekly third party environmental monitoring reports prepared by Lenard Engineering for the Colebrook South Site Wind Turbine Site (Petition 983). The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. If you require additional information, please do not hesitate to contact me.

Sincerely,

A handwritten signature in cursive script, appearing to read "Michael W. Klemens".

Michael W. Klemens, PhD  
860-824-8185 (land)  
203-448-8068 (mobile)



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut *Roger Hurlbut*  
**Date:** Sept 18, 2015  
**Re:** BNE Wind Colebrook South

---

Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 227 and 228 for the period Sept 5, 2015 thru Sept 18, 2015. There has been no rain since my inspection Sept 14.

No problems observed.

CC Greg Zupkus, BNE Energy  
Sam McGriff, Ryan Company

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	227
Date of Inspection:	September 11, 2015	Start / End Time:	7:00AM to 8:30 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Sediment and Erosion controls in place and functioning properly.  Towers 1 & 2 have been erected and work on power transmission lines is being undertaken Access road drainage is being installed		
Type of Inspection:	<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide: Storm Start Date & Time 9/10/15 10PM    Storm Duration 8HR    Approximate Rainfall 0.68-in			
Weather at time of this inspection? 60°F    overcast    light breeze			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	228
Date of Inspection:	September 14, 2015	Start / End Time:	7:00AM to 8:30 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	<p>Sediment and Erosion controls in place and functioning properly.</p> <p>Towers 1 &amp; 2 have been erected and work on power transmission lines is being undertaken</p> <p>Access road drainage is being installed</p> <p>Discussed cleaning entrance &amp; tracking pad with S McGriff</p>		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
<b>Weather Information</b> Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 9/12& 13/2015 Inter showers    Storm Duration 5HR +/- each day Approximate Rainfall 0.48in			
Weather at time of this inspection? 53°F    most cldy light breeze			
<b>Discharge Information</b> Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Describe location of any discharges from the site: -.			