

Michael W. Klemens, LLC  
POB 432  
Falls Village, CT 06031  
November 13<sup>th</sup>, 2015

Melanie Bachman  
Acting Executive Director  
CT Siting Council  
[Via Email to Siting.Council@CT.gov](mailto:Siting.Council@CT.gov)

Dear Ms. Bachman:

Please find enclosed the one hundred and third bi weekly third party environmental monitoring reports prepared by Lenard Engineering for the Colebrook South Site Wind Turbine Site (Petition 983). The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. If you require additional information, please do not hesitate to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael W. Klemens". The signature is fluid and cursive, with the first name being the most prominent.

Michael W. Klemens, PhD  
860-824-8185 (land)  
203-448-8068 (mobile)



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut *Roger Hurlbut*  
**Date:** Nov 13, 2015  
**Re:** BNE Wind Colebrook South

---

Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 235 and 236 for the period Oct 31, 2015 thru Nov 14, 2015.

I have continued making siting council reports because the site is not stabilized yet. Paving has been completed and vegetation is doing better, but still sparse

CC Greg Zupkus, BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	<b>235</b>
Date of Inspection:	Nov 5, 2015	Start / End Time:	7:15AM to 8AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Site grading, top soiling and hydroseeding has been completed. Vegetation is just beginning to sprout Road paving has been completed.		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time	Storm Duration	Approximate Rainfall	
Weather at time of this inspection? 44°F Overcast			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	<b>236</b>
Date of Inspection:	Nov 12, 2015	Start / End Time:	11:15AM to 12:10PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Site grading, top soiling and hydroseeding has been completed. Vegetation is just beginning to sprout Road paving has been completed.		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time                      Storm Duration    48 Hrs    Approximate Rainfall                      0.63-in			
Weather at time of this inspection? 48°F    Overcast to light drizzle			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			