



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: January 4, 2012
Re: Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 3 through 5 for the period December 19 through December 30, 2011. Work at the site consisted of: continued tree cutting, installation of the temporary access road from the shared/common driveway, clearing and grubbing for turbine site # 1 and access road to site # 2.

Report # 3 inspection (12/22/2011) was a normal weekly inspection.


Reports # 4&5 inspections were conducted within 24 hrs of a rainfall event greater than 0.5inches. E&S controls were in place and no erosion or sediment discharges had occurred.


As of 12/30/11 no tree cutting, clearing or earthwork for turbine sites 1 or 3 had been undertaken within 100-ft of the delineated federal wetlands.

CC C Jones Civil 1
G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	3
Date of Inspection:	December 22, 2011	Start / End Time:	1:30 / 3:30
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	<p>Contractor clearing & grubbing Turbine 1 area Erosion & sediment control fencing in from clearing limit flag #191 through #178 From 177 through 174+/- ledge rock encountered and wood chips were installed From 174+/- to 171 to 159 to 156+/- Fencing installed - double row from 171 to 159</p> <p>Contractor just starting access rd from 434 to 441 no fence in place – will be installed 12/23 per discussion with contractor after site inspection.</p> <p>Wood cutting continued from Tower # 2 area toward 115/47</p> <p>Stones had been placed on access road to 148/433</p> <p>Haybales /silt fence in place from 198 through 192</p>		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time:	Storm Duration (hrs):	Approximate Rainfall (in):	
12/21 3:30	12 hrs	0.4 to 0.5 in	
Weather at time of this inspection? Partly cloudy mild 45° to 48° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Normal runoff no evidence of sediment discharges observed			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

SITE INSPECTOR 12/22/11





General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	4
Date of Inspection:	December 23, 2011	Start / End Time:	1:30 / 3:00
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	<p>No work being done on site</p> <p>clearing & grubbing Turbine 1 area Erosion & sediment control fencing in from clearing limit flag #191 through #178 From 177 through 174+- ledge rock encountered and wood chips were installed From 174+- to 171 to 159 to 156+- Fencing installed - double row from 171 to 159</p> <p>Contractor had started access rd from 434 to 441 no fence in place, but ground is soft & no sediment has moved from disturbed area.</p> <p>Haybales /silt fence in place from 198 through 192</p>		
Type of Inspection:	<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time:	Storm Duration (hrs):	Approximate Rainfall (in):	
12/23 12:30AM	7 hrs	0.5 to 0.6 in	
Weather at time of this inspection? Partly cloudy mild 45° to 48° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Normal runoff no evidence of sediment discharges observed			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	5
Date of Inspection:	December 28, 2011	Start / End Time:	7:45 / 8:30
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	<p>No work being done on site</p> <p>clearing & grubbing Turbine 1 area Erosion & sediment control fencing in from clearing limit flag #191 through #178 From 177 through 174+/- ledge rock encountered and wood chips were installed From 174+/- to 171 to 159 to 156+/- Fencing installed - double row from 171 to 159</p> <p>Contractor had installed silt fence along access rd from 434 to 441</p> <p>Haybales /silt fence in place from 198 through 192</p>		
Type of Inspection:	<input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time:	Storm Duration (hrs):	Approximate Rainfall (in):	
12/27 5 PM	6.5 hrs	> 0.6 in	
Weather at time of this inspection? Overcast intermittent sleet 33° to 35° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Normal runoff no evidence of sediment discharges observed			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			