



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut
Date: January 27, 2012
Re: Wind Colebrook South

Roger Hurlbut

Attached are environmental erosion and sediment control monitoring reports numbers 8 and 9 for the period January 14 through January 27, 2012.

Work at the site consisted of: Installation of sediment and erosion control fencing and cleanup at both Turbine 1 & 2 sites.

Report # 8 inspection (1/19/12) was a normal weekly inspection.

Report # 9 inspections were conducted within 24 hrs of a rainfall/snowfall event E&S controls were in place and no erosion or sediment discharges had occurred.

As of 1/27/12 there is no construction equipment on the site.

CC C Jones Civil 1
G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	8
Date of Inspection:	January 19 2012	Start / End Time:	1:15 to 2:15
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	<p>Site contractor cleaning up and moving boulders</p> <p>Turbine 1 area:- Contractor had installed temporary sediment & erosion berms in vicinity of 185</p> <p>Turbine 2 area:- Contractor had straighten up fence, installed additional fence from 41 to 47 and then over to 112. They had also installed temporary sediment & erosion berms in vicinity of 44&43 and 465 & 466</p> <p>Additional haybale and woodchip berms had been placed along haul roads</p>		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No ground has snow cover			
If yes, provide: Storm Start Date & Time: Storm Duration (hrs): . Approximate Rainfall (in):			
Weather at time of this inspection? Sunny light breeze 22 – 25 ° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	9
Date of Inspection:	January 27 2012	Start / End Time:	1:30 to 2:45
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	1/27/2012 No excavation work presently being done on site Earth moving equipment has been removed from site		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No ground has snow cover			
If yes, provide: Storm Start Date & Time: 1/26/12 1:30 Storm Duration (hrs): 12 Approximate Rainfall (in): .5+/-..			
Weather at time of this inspection? Overcast - foggy 33-34 ° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			