



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: February 23, 2012
Re: Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 12 and 13 for the period January 28 through February 9, 2012.

Work at the site consisted of: Stripping & stockpiling topsoil had been performed prior to 2/17/12, but it does not appear that any site work was done in the last week .

Report # 12 inspection (2/17/12) was a combined weekly inspection and after rainfall of only 0.25 inches

Report # 13 inspection (2/23/12) was a normal weekly inspection

CC C Jones Civil 1
G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	12
Date of Inspection:	February 17, 2012	Start / End Time:	12:50 to 2:15
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	2/17/12 No work being done during inspection Contractor had been Stripping & stockpiling topsoil in eastern portion of Tower Site 1		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time: 2/17/12 5:30 AM Storm Duration (hrs): 5 Approximate Rainfall (in):0.25			
Weather at time of this inspection? Pt Cloudy 40 ° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	13
Date of Inspection:	February 23 2012	Start / End Time:	1:10 to 2:30
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off 860 208-1351 cell		
Describe present phase of construction:	2/24/12 Does not appear to have been any site work since last inspection		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time: 2/22/12 10 AM Storm Duration (hrs): 1.5 Approximate Rainfall (in):Trace			
Weather at time of this inspection? Pt Cloudy 42 ° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

