

Remote Field Review




Proposed Solar Energy Facility
0 Exley Road
Plainfield, Connecticut

Prepared For:
VEROGY

Prepared By:
Solli Engineering, LLC

VEROGY

 **SOLLI**
ENGINEERING



LEGEND

	PROPERTY LINE
	SOLAR SETBACK LINE
	7' TALL CHAIN LINK FENCE
	LIMIT OF DISTURBANCE
	ELECTRIC CONDUIT
	TRINA 540W MODULES
	CONCRETE EQUIPMENT PAD
	GRAVEL ACCESS DRIVE
	PHOTO POINT LOCATION

Rev. #:	Date	Description

SOLLI
ENGINEERING
501 Main Street, Monroe, CT 06468
T: (203) 880-5455 | F: (203) 880-9695

Drawn By: RHF
Checked By: KMS
Project #: 24120501
Plan Date: 08/12/25
Scale: 1" = 200'

Project: PROPOSED SOLAR
PHOTOVOLTAIC ARRAY
0 EXLEY ROAD
PLAINFIELD, CONNECTICUT

Sheet Title:
REMOTE FIELD
REVIEW FIGURE

SHEET #:
FIGURE 1

Approximate Location of
Interconnection Point

Approximate Location of
Proposed Utility Poles

Existing State Road
(CT 14)



Approximate Location of
Proposed Gravel Access
Driveway

Approximate Location of
Proposed Chain Link
Double Swing Gate




Photo 1: Existing Gravel Road Looking Northwest

Existing Farm Path



Photo 1: Existing Gravel Road Looking East


Existing Stockpile
to be Relocated


Approximate Location of
Proposed Gravel Access Road



Photo 1: Existing Gravel Road Looking Southeast

Approximate Location of
Proposed Utility Poles





Approximate Location of
Proposed Gravel Access Road

Existing Wetlands



Photo 2: Existing Farm Path
Looking North




Photo 2: Existing Farm Path
Looking East



Photo 2: Existing Farm Path
Looking South

Approximate Location of
Proposed Chain Link Fence



Approximate Location of
Proposed Gravel Access Road

Approximate Location of
Proposed Gravel Equipment Pad




Photo 3: Existing Farm Path
Looking West



Photo 3: Existing Farm Path
Looking North



Photo 3: Existing Farm Path
Looking East



Proposed Parking Area




Photo 4: Looking North



Photo 4: Looking South

Existing Wetlands

Approximate Location of
Proposed Chain Link Fence



Photo 4: Looking West




Photo 4: Looking East




Photo 5: Looking North



Photo 5: Looking South

Approximate Location of
Proposed Chain Link Fence

Existing Wetlands




Photo 5: Looking West



Photo 5: Looking East

Approximate
Location of Proposed
Chain Link Fence

Existing Wetlands




Photo 6: Looking West



Photo 6: Looking North



Photo 6: Looking East




Photo 7: Looking North



Photo 7: Looking South




Photo 7: Looking West



Photo 7: Looking East




Photo 8: Looking North



Photo 8: Looking South




Photo 8: Looking West



Photo 8: Looking East




Photo 9: Looking North



Photo 9: Looking South





Photo 9: Looking West



Photo 9: Looking East



Approximate Location of
Proposed Gravel Access Road



Photo 10: Existing Nursery Looking North



Photo 10: Existing Nursery Looking South

Existing Farm Path




Photo 10: Existing Nursery Looking West



Photo 10: Existing Nursery Looking East

Existing Farm Path



Photo 11: Existing Nursery Looking North




Photo 11: Existing Nursery Looking South

Approximate Location
of Proposed Chain
Link Fence

Existing Farm Path




Photo 11: Existing Nursery Looking West



Photo 11: Existing Nursery Looking East




Existing Farm Path



Photo 12: Existing Nursery Looking North



Photo 12: Existing Nursery Looking South



Approximate Location of
Proposed Utility Poles

Approximate Location
of Proposed Gravel
Access Road

Existing Farm Path



Photo 12: Existing Nursery Looking West



Photo 12: Existing Nursery Looking East

Approximate Location of
Proposed Chain Link Fence

Existing Fence



Photo 13: Existing Farm Path Looking North




Photo 13: Existing Farm Path Looking South

Approximate Location of
Proposed Chain Link Fence




Photo 13: Existing Farm Path Looking West



Photo 13: Existing Farm Path Looking East

Existing Farm Path



Photo 14: Looking North



Photo 14: Looking South

Approximate Location of
Proposed Gravel Access Road

Approximate Location of
Proposed Chain Link
Double Swing Gate




Photo 14: Looking West



Photo 14: Looking East

Approximate Location of
Proposed Gravel Access Road




Photo 15: Looking East



Photo 15: Looking South

Approximate Location of
Proposed Gravel Access Road



Photo 16: Looking Northwest



Photo 16: Looking East

Approximate Location of
Proposed Parking Area

Existing Building

Approximate Location of
Proposed Chain Link Fence



Photo 17: Looking North



Photo 17: Looking South

Approximate Location of
Proposed Chain Link
Double Swing Gate

Approximate
Location of Proposed
Gravel Access Road

Approximate Location
of Proposed Gravel
Equipment Pad



Photo 17: Looking West



Photo 17: Looking East



Existing Building



Photo 18: Looking South



Photo 18: Looking West



Photo 19: Looking North



Photo 19: Looking South

Existing Building



Photo 19: Looking West



Photo 19: Looking East

Existing Building



Photo 20: Looking North



Photo 20: Looking South



Photo 20: Looking West



Photo 20: Looking East

Existing Building



Photo 21: Looking North




Photo 21: Looking South



Photo 21: Looking West



Photo 21: Looking East



Approximate Location of
Proposed Chain Link Fence



Photo 22: Looking South



Photo 22: Looking West



Photo : Looking North





Photo 23: Looking Southwest



Photo 23: Looking Northwest



Existing Building



Photo 24: Looking North



Photo 24: Looking South




Photo 24: Looking West




Photo 24: Looking East



Photo 25: Looking North



Photo 25: Looking East



Existing Field Stone Wall



Photo 26: Looking North



Photo 26: Looking South

Approximate Location of
Proposed Chain Link Fence