

STATE PROJECT NO.:

0046-0127

CITY/TOWN:


EAST WINDSOR



STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION



OFFICE OF  
ENGINEERING



DATE:

JANUARY 2018

**Form: Asset Photos**

**Inspection type:** Fracture Critical,Routine

**Inspection Date:** 2/25/2019

**Inspected by:** Baker Engineering

**Bridge No:** 01524

**Town:** EAST WINDSOR

**Carried:** ROUTE 191

**Crossed:** SCANTIC RIVER

**Inventory Route:** Non-NHS



Photo Number: 1

Photo Taken: 02/25/2019

Bridge ID.



Photo Number: 2

Photo Taken: 02/27/2019

Typical underside, looking west.

**Form: Asset Photos**

**Inspection type:** Fracture Critical,Routine

**Inspection Date:** 2/25/2019

**Inspected by:** Baker Engineering

**Bridge No:** 01524

**Town:** EAST WINDSOR

**Carried:** ROUTE 191

**Crossed:** SCANTIC RIVER

**Inventory Route:** Non-NHS



Photo Number: 3

Photo Taken: 02/25/2019

North elevation.



Photo Number: 4

Photo Taken: 02/25/2019

South elevation.



**Form: Asset Photos**

**Inspection type:** Fracture Critical,Routine

**Inspection Date:** 2/25/2019

**Inspected by:** Baker Engineering

**Bridge No:** 01524

**Town:** EAST WINDSOR

**Carried:** ROUTE 191

**Crossed:** SCANTIC RIVER

**Inventory Route:** Non-NHS



Photo Number: 5

Photo Taken: 02/25/2019

Bridge from the west approach.



Photo Number: 6

Photo Taken: 02/25/2019

Bridge from the east approach.

**Form: Asset Photos**

**Inspection type:** Fracture Critical,Routine

**Inspection Date:** 2/25/2019

**Inspected by:** Baker Engineering

**Bridge No:** 01524

**Town:** EAST WINDSOR

**Carried:** ROUTE 191

**Crossed:** SCANTIC RIVER

**Inventory Route:** Non-NHS



Photo Number: 7

Photo Taken: 02/25/2019

West approach from the bridge.



Photo Number: 8

Photo Taken: 02/25/2019

East approach from the bridge.



**Form: Asset Photos**

**Inspection type:** Fracture Critical,Routine

**Inspection Date:** 2/25/2019

**Inspected by:** Baker Engineering

**Bridge No:** 01524

**Town:** EAST WINDSOR

**Carried:** ROUTE 191

**Crossed:** SCANTIC RIVER

**Inventory Route:** Non-NHS



Photo Number: 9

Photo Taken: 02/25/2019

Typical top of deck, looking east.



Photo Number: 10

Photo Taken: 02/27/2019

Panel 4, bay 11, deck splices near floorbeam 5, note the laminated rust at the ends of the splice plates.

**Form: Asset Photos**

**Inspection type:** Fracture Critical,Routine

**Inspection Date:** 2/25/2019

**Inspected by:** Baker Engineering

**Bridge No:** 01524

**Town:** EAST WINDSOR

**Carried:** ROUTE 191

**Crossed:** SCANTIC RIVER

**Inventory Route:** Non-NHS



Photo Number: 15

Photo Taken: 02/25/2019

Southeast metal beam rail transition to the bridge rail. Note the tear at the metal beam rail at the connection.



Photo Number: 16

Photo Taken: 02/27/2019

Deck rib 2 sliding expansion bearing at abutment 1. Note the impact rust between the sliding plate and masonry plate.



**Form: Asset Photos**

**Inspection type:** Fracture Critical,Routine

**Inspection Date:** 2/25/2019

**Inspected by:** Baker Engineering

**Bridge No:** 01524

**Town:** EAST WINDSOR

**Carried:** ROUTE 191

**Crossed:** SCANTIC RIVER

**Inventory Route:** Non-NHS

---



Photo Number: 43

Photo Taken: 02/25/2019

Upstream, north channel.



Photo Number: 44

Photo Taken: 02/25/2019

Downstream, south channel.