



Photo 7A: Wetland A2; MIRA Property; note floodplain terraces dominated by annuals in the herb layer, poorly to very poorly drained; facing northwesterly



Photo 8A: Wetland A2 (MIRA Property); note silt staining several feet above soil auger, indicating flood level; facing northwesterly



Photo 7B: Wetland B2; western section; note Phragmites in background; facing southeasterly



Photo 8B: Wetland B2, western extent; facing easterly




Photo 9A: Wetland A2 (MIRA Property); note higher moderately well drained floodplain terrace to the left; facing southerly




Photo 10A: Wetland A2; Town Property; note landfill in the background; facing easterly



Photo 9B: Wetland B3; southeastern corner; note Phragmites in background; facing northwesterly



Photo 10B: Wetland B3, eastern edge; facing westerly

Wetlands and Watercourses – Wallingford Renewable Energy
Photos taken in October and November 2017, by REMA Ecological Services, LLC



Photo 11A: Wetland A2; MIRA Property; facing northerly




Photo 12A: Wetland A2; western bank of Q. River, across from MIRA Property; showing amplitude of flooding and erosive forces; facing westerly



Photo 11B: Old abandoned access roadway between Wetlands B3 and B4; facing easterly



Photo 12B: Wetland B3, barred owl at the southwestern forested section



Photo 13B: Wetland B3, Mile-a-minute vine infestation in the wetland's eastern section



Photo 14B: Wetland B3, Phragmites and mile-a-minute vine; eastern section; facing northerly



Photo 15B: Wetland B3; mosaic of *Phragmites* and young trees and shrubs; facing northwesterly



Photo 16B: Wetland B3, southern section; facing northeasterly



Photo 17B: Wetland B3, southwest corner; very poorly drained



Photo 18B: Wetland B4; southeastern corner; note steep hillside in background; facing southeasterly

Wetlands and Watercourses – Wallingford Renewable Energy
Photos taken in October and November 2017, by REMA Ecological Services, LLC




Photo 19B: Wetland B4; northeasterly forested section; hillside seepage; facing southwesterly



Photo 20B: Wetland B4; northern section; facing westerly



Photo 21B: Wetland B4; facing southwesterly




Photo 22B: Wetland B4; northwestern section; facing southeasterly

Wetlands and Watercourses – Wallingford Renewable Energy
Photos taken in October and November 2017, by REMA Ecological Services, LLC



Photo 23B: Wetland B4; ditched watercourse draining swamp; facing southwesterly



Photo 24B: Wetland B4, edge disturbance; eastern hillslope; facing easterly



Photo 25B: Wetland B4; western extent; facing southerly




Photo 26B: Old abandoned access roadway separating Wetlands B5 and off-site wetlands to the south; also location of proposed wetland crossing; facing easterly