

From: [Aja Chase](#)
To: [CSC-DL Siting Council](#)
Subject: EM-AT&T-034-221109
Date: Tuesday, August 4, 2026 2:37:48 PM
Attachments: [image001.png](#)
[CT5069 - FCCA - 02.03.2026.pdf](#)

EXTERNAL EMAIL: This email originated from outside of the organization. Do not click any links or open any attachments unless you trust the sender and know the content is safe.

Good Afternoon CSC,
Please find the FCCA and photo of overall work completed, attached, for the site below. If you need any other information, please reach out. Thank you!

66 Sugar Hollow Road	Danbury	EM-AT&T-034-221109	10070924	WSCTB0008482
----------------------	---------	--------------------	----------	--------------

Kindly,



Aja Chase
Senior Construction Manager
ATT NE MCA
MANA NTW RO B&O RE Construction Mgmt B
Phone: 401-952-6205
Please use the @ function in emails that need my attention.
OOO Alert: 6/18-6/26

Final Report of Special Inspections

Project: CT5069

Location: 66 SUGAR HOLLOW ROAD DANBURY, CT 06810

Owner: AT&T

Engineer of Record: Scott Brantley, P.E.

TEP OPCO, LLC

To the best of my information, knowledge and belief, the Special Inspections required by Chapter 17 for the project have been performed and all discovered discrepancies have been reported and resolved.

Representatives of TEP OPCO, LLC performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on September 20th, 2025.

Based on my knowledge, information and belief the wireless installation substantially conforms to the approved plans, IBC 2021 with 2022 CT State Building Code Amendments, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-322), and the following:

1. Final Construction Drawings dated 10/22/2020, prepared by B + T GRP.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications. This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Scott Brantley, P.E.
(Type or print name)

Signature

2/3/2026

Date

TEP Engineering, PLLC PEC 0002212

