ENVIRONMENTAL COMPLIANCE MONITORING



July/August 2016 Summary Report

Project: Verizon Wireless Southington East Street Facility APT Project #: CT1412300

Address: 99 East Street, Southington, Connecticut

Regulatory Compliance Permitting Agency & Permit ID:				
ACOE NED □:				
CT Siting Council ⊠: Docket No.455 Decision Order Date: May 14, 2015 CTDEEP IWRD □:				
CTDEEP NDDB ⊠: Determination No: 201508910				
Resource Protection Program:				
Rare Species	Species Name: spotted turtle			
Aquifer Protection Area				
Vernal Pool				
Dates of Inspection				
Report #		Date		
5		July 14, 2016		
6		August 18, 2016		
Compliance Species Observed During Inspection: Yes □ No ⊠				
Species Name: N/A				
# Species: N/A				
Condition of Species: N/A				
Date Reported to CTDEEP: N/A				
Non-Compliance Species Observed During Inspection: Yes □ No ⊠				
Species Name: N/A				
# Species: N/A Condition of Species: N/A				
condition of Species, N/A				

Inspection Report #	Type of Corrective Action	Date Corrective Action Implemented
5	Minor Silt Fence Repair	7/15/16
6	None	N/A

Comments:

Modifications:

- June 24, 2016 Modify gravel access road French Mattress section because it currently is built up too high above existing grade and will conflict with agricultural use of property. Does not create an issue with compliance monitoring. Centek Engineering to approve design modification. August 18, 2016 Access road will not have to install a French Mattress because they do not anticipate any cross drainage from across road. Centek has approved change.
- June 24, 2016 Add retaining wall on west and north sides to hold back soil. Does not create an issue with compliance monitoring. Centek Engineering to approve design modification.
- June 24, 2016 Modify evergreen screening plantings around compound. Proposed species may be susceptible to droughty soil conditions. Select alternate species to withstand drought (i.e., Red Cedar, etc.).
- August 18, 2016 Will need to remove west end of silt fence for property owner to replant field and contractor will reset after same is done.

NOTES: All erosion controls in good condition.