

124 Grove Street Suite 215 Franklin, MA 02038

508.298.1500 PHONE 508.298.1501 FAX

www.TRCsolutions.com

March 20, 2018,

Mr. Robert Stein, Chairman Connecticut Siting Council Ten Franklin Square New Britain, CT 06051

Subject: Docket No. 468, Plumtree Substation to Brookfield Junction 115-kV Project

Decision and Order Condition #4 – Independent Environmental Inspector Report

Dear Mr. Stein,

Please find enclosed the Biweekly Independent Environmental Inspector Report, Report #12, for the March 8th, and March 15th, 2018 inspection events for the construction of the Eversource Plumtree Substation to Brookfield Junction 115-kV Project.

If you have any questions, please contact me at kobrion@trcsolutions.com or (508) 298-1009.

Sincerely,

Kevin M. O'Brion

Environmental Scientist/Project Manager

TRC Environmental Corp.

Enclosure

cc- Ian Cole (email), Eversource

TRC Files
Paul Cyr-TRC

Docket No. 468- Development and Management Plan Inspection

The Connecticut Siting Council (CSC) issued to the Connecticut Light and Power Company (d.b.a. as Eversource Energy [Eversource]) a Certificate of Environmental Compatibility and Public Need (Certificate) for the Southwest Connecticut Reliability Project, specifically the Plumtree to Brookfield 115-kV Transmission Line and the Plumtree Substation in Bethel (Project). For the Project, Eversource is in the process of constructing a new 3.4-mile, overhead electric transmission line between its Plumtree Substation in the Town of Bethel and its Brookfield Junction Substation in the Town of Brookfield, and also making minor related modifications to the Stony Hill Substation in Brookfield and Plumtree Substation in Bethel. In addition, two existing 115-kV line entries to Stony Hill Substation are being reconfigured as part of the Project. These electrical system modifications are located within Eversource's existing right-of-way (ROW) or substation properties in Fairfield County, Connecticut. Pursuant to the CSC's approval of the Project, this report presents the results of the weekly inspections of the Project's conformance to the CSC-approved Development & Management (D&M) Plans, performed by the CSC's independent environmental inspector pursuant to Certificate Condition 4.

ROW/SUBSTATIONS

Interim Week Inspection:

Date: 03/08/2018

Inspector: Paul Cyr

Rain Event: See Below- NWS snowfall totals

Locations Inspected (by Town, D&M Plan Map Sheet,

and Structure Number/Site:

Inspection canceled due to weather. Heavy snowfall across the state occurred on Wednesday (3/7/18) into Thursday (3/8/18). Supreme canceled site work for Wednesday and snow removal activities began Thursday afternoon and into Friday. As of 1800 hrs on 3/7/18 Danbury registered 10.9", as of 2330 hrs on 3/7/18 Brookfield registered 12.8" and Bethel registered 11.0", and as of 0330 hrs on 3/8/18 New Fairfield registered 26.8" and Newtown 24.3" of snowfall.

Work Observed: (by D&M Plan Map Sheet and Structure Number/Site)

As reported by Marleigh Sullivan (BSI Group) on 3/9/18 for activities that occurred during the week:

This week, civil crews continued west of Old Sherman Turnpike (preparing gravel access/work surfaces and matted access and work surfaces). They anticipate finishing the workpad to str.1011 today and they finished the gravel surfaces west Old Sherman. Snow removal, Project-wide, was started yesterday afternoon and continues today. After today or tomorrow morning, Supreme will be switching to another project for two weeks and will either start up off of Hearthstone or the east side of Old Sherman Turnpike.

ROW/SUBSTATIONS

Bi-Weekly Week Inspection:

Date: 03/15/2018

Inspector: Paul Cyr

Rain Event:

Locations Inspected (by Town, D&M Plan Map

Sheet, and Structure Number/Site:

-Danbury, Map 06, Str1013, Str1012, Str1011, and Wetland W1 (rare species protection protocols)

-Brookfield, Exhibit 2B Vol 2 D&M Plan, Stony Hill

Substation

Work Observed: (by D&M Plan Map Sheet and Structure Number/Site)

Supreme is off Site this week. Miller Drilling will be setting up and starting to drill (drilled shaft foundation) at Str1000 today.

Areas of Inspection		Observations	Recommended Action/s:	Corrected Action/s:
cent Roadways	Interim Week	Inspection canceled due to snow event.		
Access Roads and Adjacent Roadways	Bi-Week	Snow and/or ice covered at the time of this inspection.	N/A	
Vegetative Clearing Limits (Including trees to save or danger trees noted.	Interim Week	Inspection canceled due to snow event.		
getative Clearing Limits (Inclu	Bi-Week	N/A	N/A	

WaterCrossings	Interim Week	Inspection canceled due to snow event.		
WaterCrossing	Bi-Week	None observed at the time of this inspection.	N/A	

Erosion and Sedimentation Controls	Interim Week	Inspection canceled due to snow event.		
Erosion and Sedin	Bi-Week	E&S controls inspected were installed per Eversources BMPs and maintained accordingly.	N/A	
Inland Wetland & Watercourse encroachment & mitigation	Interim Week	Inspection canceled due to snow event.		

Inland Wetland and Watercourse encroachment and mitigation (Continued from previous page)	Bi-Week	No issues observed	N/A	
Spills and Material Storage	Interim-Week	Inspection canceled due to snow event.		
Spills and N	Bi-Week	None observed, none reported.	N/A	

igered Species	Interim Week	Inspection canceled due to snow event.		
Rare, Threatened, and Endangered Species	Bi-Week	Areas are properly flagged and visible signage is present.	N/A	
Comments Due to the p	: oredaw	umentation on hours (0630) of the inspection conducted eigh Sullivan (BSC Group) which were col		
Open Item	ns fro	m previous inspections:		
Closed Ite	ms fro	om previous inspections:		

Page 07 of 10 Plumtree-Brookfield Biweekly CSC Report #12 03/15/2018

and certify that based on reasonable investigat	with the information submitted in this document and all attachments tion, including my inquiry of those individuals responsible for mation is true, accurate and complete to the best of my knowledge and
가 있는 경기를 가게 되었다. 전에 가게 하면 있는 경기를 하고 있는 것이 되었다. 그리고 있는 것이 되었다. 그리고 있다면 다른 사람들이 되었다. 그리고 있다면 없다고 있다. 그리고 있다면 없다고	nts made in this document or its attachments may be punishable as a 2a-6 under Section 53a-157 of the Connecticut General Statutes.
Independent Field Inspector:	Tang R. Cy
Paviewer:	

Next likely scheduled inspection: 3/22/2018

Photograph Log Southwest Connecticut Reliability Project Plumtree To Brookfield Junction



Photo 1: 03/15/2018, Bethel: Map 01, setting up equipment at Str1000 to start drilling structure base foundation hole. Photo taken facing east towards Str1000 and the Plumtree Substation.

Photo Credit: Marleigh Sullivan (BSC Group).



Photo 2: 03/15/2018, Bethel: Map 01, setting up equipment at Str1000 to start drilling structure base foundation hole. Photo taken facing east towards Str1000 and the Plumtree Substation. Photo Credit: Marleigh Sullivan (BSC Group).

Date:	Photographs Taken By:	Page No.	Town/s	Report/No.	SWCT
03/15/2018	Marleigh Sullivan (BSC Group)	08 of 10	Bethel to Brookfield	Biweekly Report #12	RELIABILITY PROJECT

Photograph Log Southwest Connecticut Reliability Project Plumtree To Brookfield Junction



Photo 3: 03/15/2018, Danbury: Map 06, pull pad construction completed east of Str1012, area graded and stone base material placed to final grade. Photo taken facing west towards Str1012. Photo Credit: Marleigh Sullivan (BSC Group).



Photo 4: 03/15/2018, Danbury: Map 06, timber mat constructed pads and access road from Str1012 south to Str1011 through Wetland W1. Photo taken facing South from Str1012 to Str1011 in the distance.

Photo Credit: Marleigh Sullivan (BSC Group).

Date:	Photographs Taken By:	Page No.	Town/s	Report/No.	SWCT
03/15/2018	Marleigh Sullivan (BSC Group)	09 of 10	Bethel to Brookfield	Biweekly Report #12	RELIABILITY PROJECT

Photograph Log Southwest Connecticut Reliability Project Plumtree To Brookfield Junction



Photo 5: 03/15/2018, Danbury: Map 06, timber mat constructed work pad at Str1011. Photo taken facing south towards Str1011. Photo Credit: Marleigh Sullivan (BSC Group).

Date:	Photographs Taken By:	Page No.	Town/s	Report/No.	SWCT
03/15/2018	Marleigh Sullivan (BSC Group)	10 of 10	Bethel to Brookfield	Biweekly Report #12	RELIABILITY PROJECT