General Information				
Project Name:	Wind Colebrook South			
Location:	Winsted- Norfolk Road Colebrook, Connecticut			
CT DEP Tracking No.	CSC Petition 983	Report No.	155	
Date of Inspection:	June 26, 2014 Start / End Time: 7:30AM to 8:00A			
Inspector's Name(s):	Roger Hurlbut			
Inspector's Title(s):	Project Engineer			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off ice			
Describe present phase of construction:	No work on site			
Type of Inspection: ☐ Regular ☐ Pre-storm e Weather Information		ent Post-storm	event	
Has it rained since the last ins ✓ Yes No	pection?			
If yes, provide: Storm Start Date & Time 6/2	6/14 12AM Storm Durati	on (hrs): 3+/- Approxim	nate Rainfall: >0.3-in	
Weather at time of this inspec	tion? 67° Overcast			
Discharge Information (A)				
Do you suspect that discharge ☐Yes ☑No	s may have occurred since t	he last inspection?		
Are there any discharges at th ☐Yes ☐No	e time of inspection?			
Describe location of any disch	narges from the site:			

INSPECTOR CERTIFICATION Project: Wind Colebrook South Project Location: Winsted- Norfolk Road Colebrook CT Contractor: No work being done Address: Phone: Fax: CONSTRUCTION INSPECTION & MAINTENANCE LOG Date Activity Description (1) Report No. 10 Siting Counter Siting Counter South

(1) Report No. Date Siting Council 5/6/14 ☐ Maintenance #152 By R Hurlbut LEI ☑ Inspection Siting Council 5/13/14 ☐ Maintenance #153 By: R Hurlbut LEI Siting Council **☑** Inspection 6/21/14 ☐ Maintenance #154 By: R Hurlbut LEI **☑** Inspection Siting Council 6/26/14 ☐ Maintenance By: R Hurlbut LEI #155 ☐ Inspection By: ☐ Maintenance ☐ Inspection ☐ Maintenance

SITE-SPECIFIC BMPs

				T
(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	☑Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	☑Yes □No		
3	Temp Sediment Basins	☑Yes □No		
4	Sediment & Erosion Control Barriers	□Yes ☑No	Silt fence needs to be installed at TST 2	After snow melts
5	Temp ground cover	□Yes ☑No	Temp seeding need to be done in vicinity of TST 2 & detention basin 2 on Tower 1 site	Slopes adjacent to sediment basins have been seeded & are growing
6	Temp ground cover	□Yes ☑No	Tower 2 area should be temporarily seeded & mulched	Seeded areas have are growing 6/27/14
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

	ENALL SITE ISSUES				
(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	□Yes ☑No	□Yes □No	Inactive slopes adjacent to basin 2 need to be stabilized	Slopes in vicinity of detention basins are growing & stable 6/27/14
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☑Yes □No	☑Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	☑Yes □No	☑Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	☑Yes □No	⊠Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	☑Yes □No	⊠Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

GENERAL INSPECTION COMMENTS AND EXPLANATION

GENERAL INSPECTION COMMENTS AND EXPLANATION
General Inspection Comments (D)
Some seeding of exposed soil areas has been undertaken & seed is starting to grow
Is other descriptive information attached to this inspection report?
☐Yes ☐No
Plan Information (E)
Were all current plan BMP's in place at the time of inspection?
☐Yes ☐No Silt fence at TST # 2 Tower 1 Area not installed
Are additional BMP's required?
□Yes ☑No
Does the plan need to be updated?
□Yes □No
Explanation of additional BMP and Plan update requirements:
Name:Roger Hurlbut
(Please print) Signature: Toper Hur but
The state of the s
Title: Independent(3 rd party) Inspector Date: 6/27/14