

Crown Castle 3 Corporate Park Drive, Suite 101 Clifton Park, NY 12065

January 10, 2020

Melanie A. Bachman Executive Director Connecticut Siting Council 10 Franklin Square New Britain, CT 06051



RE: Construction Close Out – BU 806387 APP 441482

14 Route 80, Killingworth, Connecticut

EM-SPRINT-070-180813



Dear Ms. Bachman:

This letter is to confirm that all construction activity has been completed pursuant to the conditions of approval as stated in the Council's decision dated **September 4, 2018**. Please see enclosed passing modification inspection pursuant to conditions of approval numbers one and two.

Please contact me should you have any questions.

Sincerely,

Anne Marie Zsamba

Network Real Estate Specialist

3 Corporate Park Drive, Suite 101

Clifton Park, NY 12065

(201) 236-9224

AnneMarie.Zsamba@crowncastle.com

Engineered Tower Solutions, PLLC 3227 Wellington Court Raleigh, NC 27615 Office: (919) 782-2710 Kyle.Evans@ets-pllc.com

Date: January 15, 2019

Dan Vadney Crown Castle USA, Inc. 3 Corporate Park Drive, Suite 101 Clifton Park, NY 12065

Subject:

Modification Inspection Report

Crown Castle Designation:

Crown Castle BU Number:

806387

ENGINEERED TOWER

SOLUTIONS, PLLC

Crown Castle Site Name:

HRT 088 943629

Crown Castle JDE Job Number:

447439

Engineering Firm Designation:

Engineered Tower Solutions, PLLC Project Number: 184720

Site Data:

#14 Route 80, KILLINGWORTH, CT, MIDDLESEX County

Latitude 41° 21' 26.43", Longitude -72° 31' 11.83"

160 Foot - Self Support Tower

Engineered Tower Solutions, PLLC is pleased to submit this "Modification Inspection Report" (MI Report) to Crown Castle for the modification/reinforcement to the subject structure. This Modification Inspection (MI) was performed in accordance with Crown Castle CED-SOW-10007 Modification Inspection SOW, Contract Documents, and Crown Castle Purchase Order number 1272517. The purpose of this MI is to confirm that the modification installation configuration and workmanship are in accordance with the contract document(s) listed in Table 2. The MI is not a review of the adequacy or effectiveness of the modification/reinforcement solution.

Table 1 - General Information

	Company	Contact	Dates on Site
MI Vendor	Engineered Tower Solutions, PLLC	Kyle Evans, PE, CWI	N/A
MI Crew Lead	Engineered Tower Solutions, PLLC	Hunter Thomas, EI, CWI	1/10/2019
Assistant Inspector	Engineered Tower Solutions, PLLC	Edward Richardson	1/10/2019
			□ EOR

Table 2 - Documents

Document(s)	Remarks	Source
Tower Modification drawings, 12/4/2017; PJF Job #: 37517-3262.003.8800	Joseph P. Jacobs, PE; WO#: 1493848 Application ID: 396862	CCI Sites Doc Number: 7235023

Based on our inspection, Engineered Tower Solutions, PLLC determines this project:

☒ PASSING MI

The configuration, materials and/or workmanship of the modifications are installed in accordance with the Contract Documents and no deficiencies were found.

☐ FAILING MI

The configuration, materials and/or workmanship of the modifications are <u>NOT</u> installed in accordance with the Contract Documents. The rejection is based on non-conformance in the following area(s):


- ☐ Materials (see detail below)
- ☐ Workmanship (see detail below)
- ☐ Configuration (see detail below)

ANY DEVIATIONS FROM ORIGINAL DESIGN OR MI CHECKLIST REQUIREMENTS THAT HAVE BEEN APPROVED SHALL BE NOTED HERE:

 used A36 grade 3/16" plate for the (3) 3/16" x 2" x 2" spacer plate on the center stitch bolt. EOR APPROVED

We at Engineered Tower Solutions, PLLC appreciate the opportunity of providing our continuing professional services to you and Crown Castle. If you have any questions or need further assistance on this or any other projects please give us a call.

Respectfully submitted,



PE Seal