



Engineers  
Planners  
Surveyors  
Landscape Architects  
Environmental Scientists

2000 Midlantic Drive, Suite 100  
Mount Laurel, NJ 08054  
T: 856.797.0412  
F: 856.722.1120  
www.maserconsulting.com

July 13, 2021

Department of Administrative Services  
Office of the State Building Inspector  
450 Columbus Blvd. Suite 1303  
Hartford, CT 06103

Re: AT&T: CT2070 – New Fairfield SR37-SR39  
302 Ball Pond Road  
New Fairfield, CT 06812  
MC Project No. 18963030A

To Whom it May Concern,

At the request of Qualtek Wireless, Maser Consulting has reviewed the post construction photographs and As-Built drawings, received from Qualtek Wireless on April 22, 2021, of the completed antenna upgrade at the above referenced telecommunications facility. Upon reviewing the aforementioned photographs and drawings, it has been determined that the equipment has generally been installed in accordance with the approved Rev 7 construction drawing prepared by Maser Consulting, dated December 1, 2020.

Variations from the construction drawings include the following:

| Photo Number   | Remarks  | Findings   |
|--|--|------------|
| 2021-03-08 at 1.47.37 PM (1)<br>2021-03-08 at 1.47.45 PM (2)<br>2021-03-08 at 1.59.03 PM (3) | RRHs mounted on monopole collar mount.                               | Negligible |
| 2021-03-08 at 1.47.32 PM (1)<br>2021-03-08 at 2.00.26 PM (1)                                 | 8 Gauge DC Cables Installed  | Negligible |
| 2021-03-08 at 2.00.29 PM<br>2021-03-08 at 2.00.36 PM   | Proposed fiber tray not installed (Fiber tray used was pre-existing) | Negligible |

The above difference is considered **INCONSEQUENTIAL** and is considered to be in accordance with all state and local requirements. This evaluation of the as-built condition is based solely on the provided as-built drawings and photographs. This evaluation is only valid for the linear and discrete appurtenances listed in the referenced documents.

Any equipment that has been installed after the as-built photographs were taken is not part of this evaluation. Further, any equipment that has been installed, but was not captured in the provided as-built photographs, is not part of this evaluation. Maser Consulting reserves the right to amend this evaluation if more information is provided.