




CONSTRUCTION SERVICES

of Branford, LLC

August 8, 2016

Ms. Melanie Bachman, Acting Executive Director
Connecticut Siting Council
Ten Franklin Square
New Britain, CT 06051




EM-Crown-132-150420: May 11, 2015
300 Governor's Highway, South Windsor

ORIGINAL

Dear Ms. Bachman:

Please be advised that the work approved per the above referenced Exempt Modification has been completed in accordance with the terms and conditions of the approval. Attached please find the Modification Inspection Report prepared by FDH/Velocitel Engineers. Please let me know if there is anything else you may require.

Respectfully submitted,
Crown Castle

By 
Raymond J. Lemley, consultant
Ray@iwsllc.net
203-499-8631



ENGINEERING INNOVATION

6521 Meridian Dr.
 Raleigh, NC 27616
 (919) 755-1012 P
 (919) 755-1031 F

December 3, 2015

John McGee
 Project Manager ETA
 Crown Castle
 3530 Toringdon Way
 Suite 300
 Charlotte, NC 28277

Subject: Modification Inspection Report

Crown Castle Designation: Crown Castle BU Number: 828054
 Crown Castle Site Name: South Windsor/Rt 5

Inspection Firm Designation: FDH Velocitel Project Number: 15BZLZ1500

Site Data: 300 Governors Highway, South Windsor, CT 06074
 Latitude: 41° 50' 0.4" Longitude: -72° 36' 11.0"
 169' Monopole

Velocitel, Inc., d.b.a. FDH Velocitel is pleased to submit this "Modification Inspection Report" (MI Report) to Crown Castle USA, Inc. for the modification/reinforcement to the subject structure. This Modification Inspection (MI) was performed in accordance with Crown Castle ENG-SOW-10007 Modification Inspection SOW, Contract Documents, and Crown Castle Purchase Order number 776101. The purpose of this MI is to confirm that the modification installation configuration and workmanship are in accordance with the contract document(s) listed in Table 2. The MI is not a review of the adequacy or effectiveness of the modification/reinforcement solution.

Table 1 – General Information

| | Company | Contact |
|--------------------------------------|------------------------------|---------------------------------------|
| MI Inspector | FDH Velocitel | Charles E. Teal, EI 919-755-1012 |
| Independent | EOR | Turnkey |
| Modification Design EOR | Paul J. Ford and Company | Justin T. Kline, PE 918-587-4630 |
| General Contractor | LCC Deployment Services Inc. | Keith A. Stackhouse 856-810-1658 |
| Sub to the General Contractor | Centek Engineering, Inc. | Erik Armas 203-488-0580 |
| Field CWI for the General Contractor | Materials Testing, Inc. | William J. Soucy, CWI 203-468-5216 |
| Field NDE for the General Contractor | Materials Testing, Inc. | William J. Soucy, CWI 203-468-5216 |

Table 2 – Design Documents

| Document(s) | Remarks | Source |
|-----------------------------|--|-------------------------------------|
| Tower Modification Drawings | Paul J. Ford and Company Project No. 37513-1535.002.7700 R1 Dated 12-09-14 | Crown Castle CCI Doc No. 5429690 |

Based on our inspection, *FDH Velocitel* determines this project:

X_PASSING MI

The configuration, materials and/or workmanship of the modifications are installed in accordance with the Contract Documents and no deficiencies were found.

All observations were performed after construction was complete, and *FDH Velocitel* was not present during the construction phase.

We at *FDH Velocitel* appreciate the opportunity of providing our continuing professional services to you and Crown Castle USA. If you have any questions or need further assistance on this or any other projects please give us a call.

Respectfully submitted,

Dennis D. Abel, P.E.
Connecticut License No. 23247

