

How to Locate an Environmental Protection Agency (EPA) Renovation, Repair and Painting (RRP) Certified Firm

EPA RRP RULE

EPA RRP Rule:

As of April 22, 2010, the EPA **requires** firms that conduct renovations, remodeling or paint removal activities on residential houses, apartments, and child-occupied facilities built before 1978, to:

- be credentialed as “certified firm” with the EPA,
- have certified employees in the use of lead-safe work practices, and
- use lead-safe work practices that minimize occupants’ exposure to lead hazards must be followed

LOCATE A CERTIFIED FIRM

To locate a certified firm with EPA:

- 1) Go to: <https://cdxapps.epa.gov/ocspp-oppt-lead/firm-location-search>
- 2) Select “**Renovator**”, complete the form on the website then click on the “Search” button (a list of firms will be generated).

MORE INFORMATION

To locate a DPH-licensed lead consultant:

If clearance dust wipe sampling is needed, a DPH-licensed lead consultant must be hired. To generate a list go to: <https://www.elicense.ct.gov/Lookup/GenerateRoster.aspx>

For more assistance:

Please contact the Lead Hazard Reduction and Control Section’s website at www.ct.gov/preventlead.