


ORIGINAL

June 16, 2017

Mr. Robert Stein
Connecticut Siting Council
10 Franklin Square
New Britain, CT 06051



Re: Docket No. Petition 1293 - Asset Condition Improvements NESC

Dear Mr. Stein:

This letter provides the response to requests for the information listed below.

Response to CSC-01 Interrogatories dated 06/09/2017
CSC-001, 002

Very truly yours,

A handwritten signature in black ink that reads "Kathleen Shanley" with a small "ldr" written above the end of the name.

Kathleen Shanley
Manager
Transmission, Siting
As Agent for CL&P
dba EversourceEnergy

cc: Service List

CL&P dba Eversource Energy
Docket No. Petition 1293

Data Request CSC-01
Dated: 06/09/2017
Q-CSC-001
Page 1 of 1

Witness: NO WITNESS
Request from: Connecticut Siting Council

Question:

Please provide a photographic example of the existing damaged transmission structures.


Response:

Attached are pictures of 5 structures showing extensive damage including woodpecker holes, mechanical connection degradation, bracing pulling away from the pole, split pole and rotten wood.


Structure 12120




Structure 12127




Structure 12144



Structure 12148



Structure 12178



Woodpecker damage

Mechanical connection degradation
(oxidized bolts and oxidation fused
connections)

Woodpecker damage

Mechanical connection
degradation (oxidized bolts
and oxidation fused
connections)

Mechanical connection degradation
(oxidized bolts and oxidation fused
connections)

CL&P dba Eversource Energy
Docket No. Petition 1293

Data Request CSC-01
Dated: 06/09/2017
Q-CSC-002
Page 1 of 1

Witness: NO WITNESS
Request from: Connecticut Siting Council

Question:

Please provide a photographic simulation of the new structures that would be installed as part of this project.

Response:

Attached is a photographic simulation, which includes a photo of the existing Structure #12142 and the simulation of the replacement Structure #12142 located northeast of East Cotton Hill Road in Portland.

||Docket No. Petition 1293
||Data Request CSC-01
||Dated 06/09/2017
||Q-CSC-002, Page 1 of 2



EXISTING

3424 LINE


STRUCTURE 12142

LOCATION

EAST COTTON HILL ROAD, PORTLAND, CT

ORIENTATION

NORTHEAST



EVERSOURCE

||Docket No. Petition 1293
||Data Request CSC-01
||Dated 06/09/2017
||Q-CSC-002, Page 2 of 2



REPLACEMENT

3424 LINE

STRUCTURE 12142

LOCATION

EAST COTTON HILL ROAD, PORTLAND, CT

ORIENTATION

NORTHEAST



EVERSOURCE