General Information				
Project Name:	Wind Colebrook South			
Location:	Winsted- Norfolk Road			
	Colebrook, Connecticut CSC Petition 983	1/0		
CT DEP Tracking No.		Report No.	168	
Date of Inspection:	Sept 27, 2014	Start / End Time:	2:00PM to 2:30 PM	
Inspector's Name(s):	Roger Hurlbut	Roger Hurlbut		
Inspector's Title(s):	Project Engineer			
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office			
Describe present phase of construction:	No work on site			
Type of Inspection: ☑ Regular □ Pre-storm event □ During storm event □ Post-storm event				
Weather Information				
Has it rained since the last ins ☐Yes ☐ No	spection?			
If yes, provide: Storm Start Date & Time	Storm Duration Ap	proximate Rainfall:		
Weather at time of this inspec	etion? 77° pt cldy			
Discharge Information (A)				
Do you suspect that discharge ☐Yes ☑No	es may have occurred since t	he last inspection?		
Are there any discharges at the ☐Yes ☑No	ne time of inspection?			
Describe location of any disc	harges from the site:			

INSPECTOR CERTIFICATION Project: Wind Colebrook South Project Location: Winsted- Norfolk Road Colebrook CT Contractor: No work being done Address: Phone: Fax:

CONSTRUCTION INSPECTION & MAINTENANCE LOG

Date	Activity	Description	(1) Report No.
9/5/14	✓ Inspection✓ Maintenance	By R Hurlbut LEI	Siting Council #165
9/12/14	✓ Inspection✓ Maintenance	By: T Parsons LEI	Siting Council #166
9/19/14	✓ Inspection✓ Maintenance	By: R Hurlbut LEI	Siting Council #167
9/27/14	✓ Inspection✓ Maintenance	By: R Hurlbut LEI	Siting Council #168
	☐ Inspection☐ Maintenance		
	☐ Inspection☐ Maintenance		
	☐ Inspection ☐ Maintenance		

SITE-SPECIFIC BMPs

(B)	BMP Description	BMP Installed and Operating Properly?	Corrective Action Needed	Date for corrective action / responsible party
1	Anti Tracking Pad	☑Yes □No	None	
2	Sediment & Erosion Control Barriers around perimeter of site	☑Yes □No		
3	Temp Sediment Basins	☑Yes □No		
4	Sediment & Erosion Control Barriers	☑Yes □No		
5	Temp ground cover	☑Yes □No		
6	Temp ground cover	☑Yes □No		
7		□Yes □No		
8		□Yes □No		
9		□Yes □No		
10		□Yes □No		
11		□Yes □No		
12		□Yes □No		
13		□Yes □No		
14		□Yes □No		
15		□Yes □No		
17		□Yes □No		
18		□Yes □No		

OVERALL SITE ISSUES

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	☑Yes □No	☑Yes □No		
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☑Yes □No	☑Yes □No		
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	☑Yes □No	☑Yes □No		
4	Are discharge points and receiving waters free of sediment deposits?	☑Yes □No	☑Yes □No		
5	Are storm drain inlets properly protected?	□Yes □No	□Yes □No		N/A
7	Is trash/litter from work areas collected and placed in covered dumpsters?	☑Yes □No	☑Yes □No		

(C)	BMP/activity	Implemented?	Maintained?	Corrective Action	Date for corrective action/responsible person
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	□Yes □No	□Yes □No		N/A
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	□Yes □No	□Yes □No		N/A
10	Are materials that are potential stormwater contaminants stored inside or under cover?	□Yes □No	□Yes □No		N/A
11	Are non- stormwater discharges (e.g., wash water, dewatering) properly controlled?	□Yes □No	□Yes □No		N/A
12	(Other)	□Yes □No	□Yes □No		
13	(Other)	□Yes □No	□Yes □No		

GENERAL INSPECTION COMMENTS AND EXPLANATION

GENERAL INSPECTION COMMENTS AND EXPLANATION	
General Inspection Comments (D)	
Gravel driveway access to site has been regarded to reduce erosion	·
Is other descriptive information attached to this inspection report?	
□Yes □No	
Plan Information (E)	
Were all current plan BMP's in place at the time of inspection?	
☑Yes □No	
Are additional BMP's required?	
□Yes ☑No	
Does the plan need to be updated?	
□Yes ☑No	
Explanation of additional BMP and Plan update requirements:	
Name: Roger Hurlbut	
(Please print)	
Signature:	
Title: Independent(3 rd party) Inspector Date: 10/2/2014	