EM-SPELOT-025-130118

INFINIGY & Design. Build. Deliver.

479 Rte 17 North | Mahwah, NJ 07430 Phone: 201-962-7888 | Fax: 201-962-7889 www.infinigy.com

October 29, 2014

Melanie A. Bachman Acting Executive Director Connecticut Siting Council 10 Franklin Square New Britain, CT 06051

DECENVED OCT 3 0 2014

CONNECTICUT SITING COUNCIL

Re: NV_CT03XC044 Post Inspection Report 751 Higgins Avenue Cheshire, CT

Dear Ms. Bachman,

Enclosed you will find a stamped Post Build/Special Inspections Report for the above referenced site.


This inspection concluded that, "Based on this review the project was observed to be completed in general conformance to the project requirements."

Feel free to contact me if you have any questions or need additional information.

Sincerely,

Tina Lopez

Project Manager Mobile | 646-275-5410 479 Route 17 North | Suite 1A | Mahwah, NJ | 07430 tlopez@infinigy.com





Infinigy Engineering 1033 Watervliet Shaker Road Albany, NY 12205

Attn: Ms. Elizabeth Gregory

E: egregory@infinigy.com

Re: Summary of Special Inspections

Lattice Telecommunications Tower, Antenna Upgrade

Site CT03XC044

Cheshire, Connecticut

Terracon Project No. J2141231 Task 6

Dear Ms. Gregory

Terracon Consultants, Inc. (Terracon) is pleased to submit this Summary of Special Inspections for the above-referenced tower project. We provided Special Inspections services related to antenna mount upgrades. A Terracon Field Report has been issued under separate cover.

The site is located at 751 Higgins Road in Cheshire, Connecticut and has been developed with an approximately 254-foot high self-supporting lattice telecommunications tower and associated equipment cabinets and identified on the project drawings as Site CT03XC044. The project consists of replacing existing antennas and their structural mounts.

On October 20, 2014, a Terracon Steel Inspector/International Code Council Bolting Special Inspector visited the site to review previously installed antenna mounts and fastening assemblies for general conformance to the project requirements. Our field review was completed without issue. Based on this review the project was observed to be completed in general conformance to the project requirements.

This Summary of Special Inspections is submitted as a professional opinion of the project conditions as of the date of our visit. Based on observations, which were completed at a specific time and specific location, Terracon is of the opinion that the foregoing is representative of the project to date. This report in no way relieves any party responsible for the project related construction from meeting the requirements imposed by contract or other means, including commonly accepted industry practices. To the best of our information, knowledge and belief, the Special Inspections required for this project, have been performed and discovered discrepancies have been reported and resolved. If you have questions or require further assistance concerning this document, please do not hesitate to contact the undersigned.

Terracon Consultants, Inc. 201 Hammer Mill Road, Rocky Hill, Connecticut 06067 P (860) 721 1900 F (860) 721 1939 terracon.com

Environmental Facilities Geotechnical Materials

Summary of Special Inspections

Lattice Telecommunications Tower Antenna Upgrade ■ Chesire Connecticut October 21, 2014 ■ Terracon Project No. J2141231



We appreciate the opportunity to be of service to you on this project. If you have any questions regarding the information presented in this report or if we can be of further assistance to you, please feel free to contact us.

Sincerely,

Terracon Consultants, Inc.

Timothy J. Derr Special Inspections Representative

/pdc/J2141231

Ryan R. Roy, P.E.
Senior Principal/Division Manager