

Perrone, Michael

From: Mayo, Rachel <rmayo@RC.com>
Sent: Monday, March 02, 2015 4:23 PM
To: Perrone, Michael
Cc: Baldwin, Kenneth
Subject: FW: EM Questions

Mike, we looked into your questions below

On Greenwich EM-VER-057-150213...9 antennas are being replaced with 9 newer model antennas...it was a typo on our end..the quantity for the 2100 MHz replacement should have said three (3) instead of two (2) on the cover page.

ON Branford- EM-VER-014-150217..the structural is correct, we inverted the quantity on the two types antennas.

Sorry for the confusion.

Please let me know if you need additional information.

Rachel A. Mayo
Land Use Analyst

Robinson & Cole LLP
280 Trumbull Street
Hartford, CT 06103
Direct 860.275.8213 | Fax 860.275.8299
rmayo@rc.com | www.rc.com
[Bio](#) | [Contact Card](#)

Robinson+Cole

Boston | Hartford | New York | Providence | Stamford
Albany | Los Angeles | Miami | New London

From: Perrone, Michael [<mailto:Michael.Perrone@ct.gov>]
Sent: Monday, March 02, 2015 3:32 PM
To: Baldwin, Kenneth
Subject: EM Questions

Attorney Baldwin:

EM-VER-057-150213 – 36 Rich Avenue, Greenwich

Are nine antennas being replaced with eight antennas? I just wanted to make sure that was correct.

EM-VER-014-150217 – 405 Brushy Plain Road, Branford

The quantities of the BXA-171085 and BXA-171063 antennas appear to be interchanged. The text says two BXA-171085 antennas and one BXA-171063 antenna. The structural says one BXA-171085 antenna and two BXA-171063 antennas. Is that a typo in the text?

Thanks.

Mike