CROWN CASTLE PROJECT: BU #876315; OAK LANE CC, INC. TOWER (SSUSA; WOODBRIDGE, CT MONOPOLE RETROFIT PROJECT MASTER NOTES DOCUMENT (REV. 2, 1/22/2009)

UPON THE SUCCESSFUL AND COMPLETE INSTALLATION OF THE REINFORCING SYSTEM SPECIFIED IN THESE PLANS, THE REINFORCED POLE MEETS THE WIND DESIGN RECOMMENDATIONS OF THE TIA/EIA-222-F-1996 STANDARD FOR WIND SPEEDS OF 85 MPH AND 38 MPH + 3/4" RADIAL ICE

A. GENERAL NOTES

1. IT SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR TO FIELD VERIFY ALL EXISTING CONDITIONS AND DIMENSIONS PRIOR TO FABRICATION AND CONSTRUCTION. THESE DRAWINGS WERE PREPARED FROM INFORMATION AND DOCUMENTS PROVIDED TO PAUL J. FORD & COMPANY BY CROWN CASTLE. THIS INFORMATION PROVIDED HAS NOT BEEN FIELD VERIFIED BY PAUL J. FORD & COMPANY FOR ACCURACY AND THEREFORE DISCREPANCIES BETWEEN THESE DRAWINGS AND ACTUAL SITE CONDITIONS SHOULD BE ANTICIPATED. ANY DISCREPANCIES AND/OR CHANGES BETWEEN THE INFORMATION CONTAINED IN THESE DRAWINGS AND THE ACTUAL VERIFIED SITE CONDITIONS SHALL BE IMMEDIATELY BROUGHT TO

THESE DRAWINGS AND THE ACTUAL VERIFIED SITE CONDITIONS SHALL BE IMMEDIATELY BROUGHT TO THE ATTENTION OF CROWN CASTLE AND PAUL J. FORD & COMPANY SO THAT ANY CHANGES AND/OR ADJUSTMENTS, IF NECESSARY, CAN BE MADE TO THE DESIGN AND DRAWINGS.

THE EXISTING UNREINFORCED MONOPOLE STRUCTURE DOES NOT HAVE THE STRUCTURAL CAPACITY TO CARRY ALL OF THE ANTENNA AND PLATFORM LOADS SHOWN ON THESE DRAWINGS AT THE REQUIRED MINIMUM TIA/EIA-222-F BASIC WIND SPEEDS. DO NOT INSTALL ANY ADDITIONAL OR NEW ANTENNA AND PLATFORM LOADS UNTIL THE MONOPOLE REINFORCING SYSTEM IS COMPLETELY AND SUCCESSFULLY INSTALL ED.

INSTALLED.

IF MATERIALS, QUANTITIES, STRENGTHS OR SIZES INDICATED BY THE DRAWINGS OR SPECIFICATIONS ARE NOT IN AGREEMENT WITH THESE NOTES, THE BETTER QUALITY AND/OR GREATER QUANTITY, STRENGTH OR SIZE INDICATED, SPECIFIED OR NOTED SHALL BE PROVIDED.

THIS STRUCTURE IS DESIGNED TO BE SELF-SUPPORTING AND STABLE AFTER THE INSTALLATION OF THE

REINFORCING REPAIR SYSTEM HAS BEEN PROPERLY AND ADEQUATELY COMPLETED. IT IS THE CONTRACTOR'S SOLE RESPONSIBILITY TO INSURE THE SAFETY AND STABILITY OF THE MONOPOLE AND ITS COMPONENT PARTS DURING FIELD MODIFICATIONS. THIS INCLUDES, BUT IS NOT LIMITED TO, THE ADDITION OF WHATEVER TEMPORARY BRACING, GUYS OR TIE DOWNS THAT MAY BE NECESSARY. SUCH ADDITION OF WHATEVER TEMPORARY BRACING, GUYS OR TIE DOWNS THAT MAY BE NECESSARY. SUCH MATERIAL SHALL BE REMOVED AND SHALL REMAIN THE PROPERTY OF THE CONTRACTOR AFTER THE COMPLETION OF THE PROJECT. IMPORTANT CUTTING, WELDING AND SAFETY GUIDELINES: THE CONTRACTOR SHALL FOLLOW ALL CROWN CASTLE CUTTING, WELDING, FIRE PREVENTION AND SAFETY GUIDELINES. PRIOR TO CONSTRUCTION, THE CONTRACTOR SHALL OBTAIN A COPY OF THE CURRENT CROWN CASTLE GUIDELINES FROM CROWN CASTLE. PER THE 12-01-2005 CROWN CASTLE DIRECTIVE: "ALL CUTTING AND WELDING ACTIVITIES SHALL BE CONDUCTED IN ACCORDANCE WITH CROWN CASTLE POLICY 'CUTTING AND WELDING PLAN' (DOC#ENG-PLN-10015) ON AN ONGOING BASIS THROUGHOUT THE ENTIRE LIFE OF THE PROJECT".

THE STRUCTURAL CONTRACT DOCUMENTS DO NOT INDICATE THE METHOD OR MEANS OF CONSTRUCTION. THE CONTRACTOR SHALL SUPERVISE AND DIRECT THE WORK AND SHALL BE SOLELY.

CONSTRUCTION. THE CONTRACTOR SHALL SUPERVISE AND DIRECT THE WORK AND SHALL BE SOLELY RESPONSIBLE FOR ALL CONSTRUCTION MEANS, METHODS, TECHNIQUES, SEQUENCES, AND

PROCEDURES. OBSERVATION VISITS TO THE SITE BY THE OWNER AND/OR THE ENGINEER SHALL NOT INCLUDE INSPECTIONS OF THE PROTECTIVE MEASURES OR THE CONSTRUCTION PROCEDURES.

ANY SUPPORT SERVICES PERFORMED BY THE ENGINEER DURING CONSTRUCTION SHALL BE DISTINGUISHED FROM CONTINUOUS AND DETAILED INSPECTION SERVICES WHICH ARE FURNISHED BY THE INSPECTION/TESTING AGENCY. THESE SUPPORT SERVICES PERFORMED BY THE ENGINEER ARE SOLELY FOR THE PURPOSE OF ASSISTING IN QUALITY CONTROL AND IN ACHIEVING CONFORMANCE. WITH CONTRACT DOCUMENTS. THEY DO NOT GUARANTEE CONTRACTOR'S PERFORMANCE AND SHALL NOT BE CONSTRUCTED AS SUPERVISION OF CONSTRUCTION.

ALL MATERIALS AND EQUIPMENT FURNISHED WILL BE NEW AND OF GOOD QUALITY, FREE FROM FAULTS AND DEFECTS AND IN CONFORMANCE WITH THE CONTRACT DOCUMENTS. ANY AND ALL SUBSTITUTIONS MUST BE PROPERLY APPROVED AND AUTHORIZED IN WRITING BY THE OWNER AND ENGINEER PRIOR TO INSTALLATION. THE CONTRACTOR SHALL FURNISH SATISFACTORY EVIDENCE AS TO THE KIND AND

QUALITY OF MATERIALS AND EQUIPMENT BEING SUBSTITUTED.

THE CONTRACTOR SHALL BE RESPONSIBLE FOR INITIATING, MAINTAINING, AND SUPERVISING ALL SAFETY PRECAUTIONS AND PROGRAMS IN CONNECTION WITH THE WORK. THE CONTRACTOR IS RESPONSIBLE TO INSURE THAT THIS PROJECT AND RELATED WORK COMPLIES WITH ALL APPLICABLE LOCAL, STATE, AND FEDERAL SAFETY CODES AND REGULATIONS GOVERNING THIS WORK AS WELL AS CROWN CASTLE SAFETY GUIDELINES.

THE CONTRACTOR SHALL BE RESPONSIBLE FOR PROTECTING ALL EXISTING AND NEW COAXIAL CABLES AND OTHER EQUIPMENT DURING CONSTRUCTION.

ANY EXISTING ATTACHMENTS AND/OR PROJECTIONS ON THE POLE THAT MAY INTERFERE WITH THE INSTALLATION OF THE REINFORCING SYSTEM WILL HAVE TO BE REMOVED, AND/OR RELOCATED, AND/OR REPLACED AND RE-INSTALLED AFTER THE REINFORCING IS SUCCESSFULLY COMPLETED. THE CONTRACTOR SHALL IDENTIFY AND COORDINATE THESE ITEMS PRIOR TO CONSTRUCTION WITH THE OWNER, TESTING AGENCY, AND ENGINEER.

11. ANY AND ALL EXISTING PLATFORMS THAT ARE LOCATED IN AREAS OF THE POLE SHAFT WHERE SHAFT REINFORCING MUST BE APPLIED SHALL BE TEMPORARILY REMOVED OR OTHERWISE SUPPORTED TO PERMIT NEW CONTINUOUS REINFORCEMENT TO BE ATTACHED. AFTER THE CONTRACTOR HAS SUCCESSFULLY INSTALLED THE MONOPOLE REINFORCEMENT SYSTEM, THE CONTRACTOR SHALL ANTENNAS AND/OR COAX CABLES AND/OR OTHER EQUIPMENT BY STEM, THE CONTRACTOR SHALL RE-INSTALL THE PLATFORMS. IN NO CASE SHALL ANY NEW AND/OR ADDITIONAL PLATFORMS AND/OR ANTENNAS AND/OR COAX CABLES AND/OR OTHER EQUIPMENT BE INSTALLED ON THE MONOPOLE UNTIL THE CONTRACTOR HAS SUCCESSFULLY COMPLETED THE INSTALLATION OF ALL OF THE REQUIRED STRUCTURAL REINFORCING SYSTEM COMPONENTS.

B. "LOWHEAT" WELDING PROCEDURES:
ANY AND ALL FIELD WELDING REQUIRED ON THIS PROJECT SHALL BE PERFORMED BY AWS CERTIFIED
WELDERS USING "LOW HEAT" WELDING TECHNIQUES.

FOR THE PURPOSES OF THIS PROJECT, "LOW HEAT" WELDING IS DEFINED AS A CAREFUL AND CONTROLLED WELDING PROCESS, PERFORMED BY EXPERIENCED AWS CERTIFIED WELDERS, SUCH THAT THE CORRECT AMOUNT OF WELD METAL IS DEPOSITED AND IS PROPERLY FUSED IN SUCH A WAY THAT EXCESSIVE AMOUNTS OF HEAT BUILDUP AT THE WELDED JOINT, DUE TO EXCESSIVE MOLTEN WELD METAL POOLING, IS AVOIDED.
THE "LOW HEAT" WELDING PROCESS SHALL BE SET UP SO THAT ANY FIELD WELDING ACTIVITY ON THE

POLE STRUCTURE DOES NOT SCORCH OR OTHERWISE DAMAGE THE EXISTING GALVANIZED SURFACE

ON THE INSIDE OF THE POLE SHAFT IN AND AROUND THE REGION OF THE WELD.

THE "LOW HEAT" WELDING PROCESS, USED IN CONJUNCTION WITH THE CROWN CASTLE COAX
PROTECTION AND FIRE SAFETY GUIDELINES, SHALL BE SET UP SO THAT ANY FIELD WELDING ACTIVITY
ON THE POLE STRUCTURE DOES NOT SCORCH AND/OR OTHERWISE DAMAGE THE EXISTING COAX

ON THE POLE STRUCTURE DOES NOT SCORCH AND/OR OTHERWISE DAMAGE THE EXISTING COAX CABLES THAT RUN ON THE INSIDE AND/OR OUTSIDE OF THE POLE SHAFT IN AND AROUND THE REGION

CABLES ITHAT ROW ON THE INSIDE AND/OR OUTSIDE OF THE POLE SHAFT IN AND AROUND THE REGION OF THE WELD.

"LOW HEAT" WELD DEMONSTRATION REQUIRED: PRIOR TO BEGINNING THE FIELD WELDING FOR THE REINFORCEMENT WORK, THE CONTRACTOR'S AWS CERTIFIED WELDER SHALL DEMONSTRATE THE "LOW HEAT" WELDING PROCESS THAT WILL BE USED ON THIS PROJECT SO THAT CROWN CASTLE REPRESENTATIVES CAN OBSERVE AND VERIFY THAT THE PROPOSED PROCESS DOES NOT DAMAGE THE EXISTING GALVANIZED SURFACE ON THE BACK SIDE OF THE SAMPLE PLATE THAT IS BEING WELDED. THE CONTRACTOR SHALL USE TEMPERATURE MONITORING DEVICES SUCH AS THERMOCOUPLE, HEAT CRAYON, AND/OR INFRARED SENSOR TO MEASURE AND DEMONSTRATE THE TEMPERATURE OF THE STEEL ON THE BACK SURFACE IN THE REGION OF THE WELD. THE "LOW HEAT" WELD DEMONSTRATION SHALL BE CARRIED OUT ON-SITE AND USING A GALVANIZED STEEL PLATE SAMPLE WITH A THICKNESS EQUAL TO THE MINIMUM SHAFT THICKNESS THAT WILL BE REINFORCED. ONLY AFTER THE "LOW HEAT" TECHNIQUES HAVE BEEN SUCCESSFULLY DEMONSTRATED AND ARE APPROVED BY CROWN CASTLE REPRESENTATIVES, CAN THE CONTRACTOR PROCEED WITH THE FIELD WELDING ON THE STRUCTURE. CAUTION: THE CONTRACTOR SHALL CAREFULLY FOLLOW ALL CROWN CASTLE CUTTING, WELDING, FIRE SAFETY, AND ALL OTHER SAFETY GUIDELINES WHICH ALSO INCLUDE "LOW HEAT" WELDING TECHNIQUES. THE CONTRACTOR IS SOLELY RESPONSIBLE FOR MAINTAINING THE SAFETY AND STABILITY OF THE STRUCTURE DURING CONSTRUCTION. THE CONTRACTOR SHALL BE HELD FULLY LIABLE FOR ANY DAMAGE (INCLUDING HEAT AND FIRE DAMAGE CAUSED BY FIELD WELDING) TO THE STRUCTURE AND ANY OF ITS COMPONENTS WHICH OCCURS DURING CONSTRUCTION.

STRUCTURE AND ANY OF ITS COMPONENTS WHICH OCCURS DURING CONSTRUCTION.

C. SPECIAL INSPECTION AND TESTING
ALL WORK SHALL BE SUBJECT TO REVIEW AND OBSERVATION BY THE OWNER'S REPRESENTATIVE AND
THE OWNER'S AUTHORIZED INDEPENDENT INSPECTION AND TESTING AGENCY. REFER TO CROWN
CASTLE DOCUMENT ENG-SOW-10066 FOR SPECIFICATION.

ANY SUPPORT SERVICES PERFORMED BY THE ENGINEER DURING CONSTRUCTION SHALL BE DISTINGUISHED FROM CONTINUOUS AND DETAILED INSPECTION SERVICES WHICH ARE FURNISHED BY OTHERS. THESE SUPPORT SERVICES PERFORMED BY THE ENGINEER ARE PERFORMED SOLELY FOR THE PURPOSE OF ASSISTING IN QUALITY CONTROL AND IN ACHIEVING CONFORMANCE WITH CONTRACT DOCUMENTS. THEY DO NOT GUARANTEE CONTRACTOR'S PERFORMANCE AND SHALL NOT BE CONSTRUED AS SUPERVISION OF CONSTRUCTION.
OBSERVED DISCREPANCIES BETWEEN THE WORK AND THE CONTRACT DOCUMENTS SHALL BE

CORRECTED BY THE CONTRACTOR AT NO ADDITIONAL COST.

AN INDEPENDENT QUALIFIED INSPECTION/TESTING AGENCY SHALL BE SELECTED, RETAINED AND PAID FOR BY THE OWNER FOR THE SOLE PURPOSE OF INSPECTING, TESTING, DOCUMENTING, AND APPROVING ALL WELDING AND FIELD WORK PERFORMED BY THE CONTRACTOR.

ACCESS TO ANY PLACE WHERE WORK IS BEING DONE SHALL BE PERMITTED AT ALL TIMES.
THE INSPECTION AGENCY SHALL SO SCHEDULE THIS WORK AS TO CAUSE A MINIMUM OF INTERRUPTION TO, AND COORDINATE WITH, THE WORK IN PROGRESS. IT IS THE CONTRACTOR'S RESPONSIBILITY TO COORDINATE THE WORK SCHEDULE WITH THE TESTING AGENCY. THE CONTRACTOR SHALL ALLOW FOR ADEQUATE TIME AND ACCESS FOR THE

TESTING AGENCY TO PERFORM THEIR DUTIES.

THE INSPECTION AND TESTING AGENCY SHALL BE RESPONSIBLE TO PERFORM THE FOLLOWING SERVICES FOR THE OWNER. THE TESTING AGENCY SHALL INSPECT THE FOLLOWING ITEMS IN ACCORDANCE WITH THE CONSTRUCTION DRAWINGS. THE TESTING AGENCY SHALL INSPECT ITEMS ON THIS LIST AND OTHER ITEMS AS NECESSARY TO FULFILL THEIR RESPONSIBILITY. THE TESTING AGENCY SHALL UTILIZE EXPERIENCED, TRAINED INSPECTORS INCLUDING AWS CERTIFIED WELDING INSPECTORS (CWI). INSPECTORS SHALL HAVE THE TRAINING, CREDENTIALS, AND EXPERIENCE APPROPRIATE FOR AND COMMENSURATE WITH THE SCOPE AND TYPE OF INSPECTION WORK TO BE PERFORMED.

(1.) PERFORM CONTINUOUS ON-SITE OBSERVATION, INSPECTION, VERIFICATION, AND TESTING DURING THE TIME THE CONTRACTOR IS WORKING ON-SITE. AGENCY SHALL NOTIFY OWNER IMMEDIATELY WHEN FIELD PROBLEMS OR DISCREPANCIES OCCUR.

FOUNDATIONS, CONCRETE, AND SOIL PREPARATION - (NOT REQUIRED)
CONCRETE TESTING PER ACI - (NOT REQUIRED)
STRUCTURAL STEEL

CHECK THE STEEL ON THE JOB WITH THE PLANS. CHECK MILL CERTIFICATIONS.

CHECK MILL CERTIFICATIONS.

CHECK GRADE OF STEEL MEMBERS, AND BOLTS FOR CONFORMANCE WITH DRAWINGS.
INSPECT STEEL MEMBERS FOR DISTORTION, EXCESSIVE RUST, FLAWS AND BURNED HOLES.
CALL FOR LABORATORY TEST REPORTS WHEN IN DOUBT.

CHECK STEEL MEMBERS FOR SIZES, SWEEP AND DIMENSIONAL TOLERANCES.
CHECK FOR SURFACE FINISH SPECIFIED, GALVANIZED.
CHECK BOLT TIGHTENING ACCORDING TO AISC "TURN OF THE NUT" METHOD.

WELDING:

(1.) VERIFY FIELD WELDING PROCEDURES, WELDERS, AND WELDING OPERATORS, NOT DEEMED

PREQUALIFIED, IN ACCORDANCE WITH AWS D1.1.

(2.) INSPECT FIELD WELDED CONNECTIONS IN ACCORDANCE WITH THE REQUIREMENTS SPECIFIED AND IN ACCORDANCE WITH AWS D1.1.

(3.) APPROVE FIELD WELDING SEQUENCE.

(A.) A PROGRAM OF THE APPROVED SEQUENCES SHALL BE SUBMITTED TO THE OWNER BEFORE WELDING BEGINS. NO CHANGE IN APPROVED SEQUENCES MAY BE MADE WITHOUT PERMISSION FROM THE OWNER

(4.) INSPECT WELDED CONNECTIONS AS FOLLOWS AND IN ACCORDANCE WITH AWS D1.1:

INSPECT WELDING EQUIPMENT FOR CAPACITY, MAINTENANCE AND WORKING CONDITIONS. VERIFY SPECIFIED ELECTRODES AND HANDLING AND STORAGE OF ELECTRODES FOR CONFORMANCE TO SPECIFICATIONS INSPECT PREHEATING AND INTERPASS TEMPERATURES FOR CONFORMANCE WITH AWS (C.)

VISUALLY INSPECT ALL WELDS AND VERIFY THAT QUALITY OF WELDS MEETS THE

REQUIREMENTS OF AWS D1.1.

SPOT TEST AT LEAST ONE FILLET WELD OF EACH MEMBER USING MAGNETIC PARTICLE OR

DYE PENETRANT. INSPECT FOR SIZE, SPACING, TYPE AND LOCATION AS PER APPROVED PLANS.

VERIFY THAT THE BASE METAL CONFORMS TO THE DRAWINGS. REVIEW THE REPORTS BY TESTING LABS.

CHECK TO SEE THAT WELDS ARE CLEAN AND FREE FROM SLAG

INSPECT RUST PROTECTION OF WELDS AS PER SPECIFICATIONS.
CHECK THAT DEFECTIVE WELDS ARE CLEARLY MARKED AND HAVE BEEN ADEQUATELY

REPAIRED.

F. SPECIAL INSPECTION OF EXISTING SHAFT-TO-FLANGE WELD CONNECTIONS:

(1.) PRIOR TO CONSTRUCTION, TESTING AGENCY SHALL INSPECT CONDITION OF EXISTING SHAFT-TO-BASE-PLATE WELD CONNECTION. ALSO INSPECT EXISTING STIFFENERS IF PRESENT. THE INSPECTOR SHALL USE THE FOLLOWING INSPECTION METHODS, OR COMBINATION OF METHODS, AS REQUIRED TO IDENTIFY ANY CRACKS: VISUAL, MAGNETIC PARTICLE, AND/OR ULTRA-SONIC. IN ADDITION, OTHER TEST METHODS MAY ALSO BE USED AT THE RECOMMENDATION OF THE TESTING AGENCY AND UPON THE APPROVAL OF THE OWNER AND THE ENGINEER. THE TESTING AGENCY SHALL PROVIDE CAREFUL AND THOROUGH
DOCUMENTATION OF THIS INSPECTION TO THE OWNER AND THE ENGINEER. TESTING AGENCY
SHALL COORDINATE THESE INSPECTION ACTIVITIES WITH THE OWNER'S REQUIRED PROCESSES
AND PROCEDURES. IMPORTANT: THE TESTING AGENCY SHALL IMMEDIATELY REPORT ANY
INDICATIONS OF CRACKS, FRACTURES, DISTRESS, AND/OR CORROSION TO THE OWNER AND
ENGINEER.

AFTER CONSTRUCTION, TESTING AGENCY SHALL INSPECT ANY AND ALL FIELD REPAIRS IMPLEMENTED AS REQUIRED BY THE OWNER FROM THE RESULTS OF THE INSPECTION IN THE PREVIOUS NOTE 5.F.(1.) ABOVE.

REFER TO CROWN CASTLE DOCUMENTS ENG-SOW-10033 AND ENG-BUL-10051 FOR

SPECIFICATIONS.


(1.) COMPILE AND PERIODICALLY SUBMIT DAILY INSPECTION REPORTS TO THE OWNER.

6. THE INSPECTION PLAN OUTLINED HEREIN IS INTENDED AS A DESCRIPTION OF GENERAL AND SPECIFIC THE INSPECTION PLAN OUTLINED HEREIN IS INTENDED AS A DESCRIPTION OF GENERAL AND SPECIFIC ITEMS OF CONCERN. IT IS NOT INTENDED TO BE ALL-INCLUSIVE. IT DOES NOT LIMIT THE TESTING AND INSPECTION AGENCY TO THE ITEMS LISTED. ADDITIONAL TESTING, INSPECTION, AND CHECKING MAY BE REQUIRED AND SHOULD BE ANTICIPATED. THE TESTING AGENCY SHALL USE THEIR PROFESSIONAL JUDGMENT AND KNOWLEDGE OF THE JOB SITE CONDITIONS AND THE CONTRACTOR'S PERFORMANCE TO DECIDE WHAT OTHER ITEMS REQUIRE ADDITIONAL ATTENTION. THE TESTING AGENCY'S JUDGMENT MUST PREVAIL ON ITEMS NOT SPECIFICALLY COVERED. ANY DISCREPANCIES AND PROBLEMS SHALL BE BROUGHT IMMEDIATELY TO THE OWNER'S ATTENTION. RESOLUTIONS ARE NOT TO BE MADE WITHOUT THE OWNER'S REVIEW AND SPECIFIC WRITTEN CONSENT. THE OWNER RESERVES THE RIGHT TO DETERMINE WHAT IS AN ACCEPTABLE RESOLUTION OF DISCREPANCIES AND PROBLEMS.

AFTER EACH INSPECTION, THE TESTING AGENCY WILL PREPARE A WRITTEN ACCEPTANCE OR REJECTION WHICH WILL BE GIVEN TO THE CONTRACTOR AND FILED AS DAILY REPORTS TO THE OWNER. THIS WRITTEN ACTION WILL GIVE THE CONTRACTOR AND FILED AS DAILY REPORTS TO THE OWNER. THIS WRITTEN ACTION WILL GIVE THE CONTRACTOR A LIST OF ITEMS TO BE CORRECTED, PRIOR TO CONTINUING CONSTRUCTION. AND/OR LOADING OF STRUCTURAL ITEMS.

CONTINUING CONSTRUCTION, AND/OR LOADING OF STRUCTURAL ITEMS.

8. RESPONSIBILITY: THE TESTING AGENCY DOES NOT RELIEVE THE CONTRACTOR'S CONTRACTUAL OR STATUTORY OBLIGATIONS. THE CONTRACTOR HAS THE SOLE RESPONSIBILITY FOR ANY DEVIATIONS FROM THE OFFICIAL CONTRACT DOCUMENTS. THE TESTING AGENCY WILL NOT REPLACE THE CONTRACTOR'S QUALITY CONTROL PERSONNEL.



contained herein, i J. Ford and Compai nfidence and shall r tten permission of F pany, issued in II not, without the If Paul J. Ford uced, copied or er than the

PAUL J. FORD AND COMPANY STRUCTURAL ENGINEERS 250 East Broad Street · Suite 1500 · Columbus, Ohio 43215 (614) 221-6679 www.pjfweb.com

3530 TORINGDON WAY, SUITE 300, CHARLOTTE, NC 28277

FAX: (704) 416-4950

BU #876315; OAK LANE CC, INC. TOWER (SSUSA WOODBRIDGE, CT

MONOPOLE REINFORCEMENT AND RETROFIT PROJECT

PROJECT No: 37512-1566 DRAWN BY B.M.S. CHECKED BY T.J.D. APPROVED BY

ISSUE DATE OF PERMIT: 8-24-2012

DATE 8-24-2012 S-1

STRUCTURAL STEEL MATERIALS, FABRICATION, DETAILING, AND WORKMANSHIP SHALL CONFORM TO THE LATEST EDITION OF THE FOLLOWING REFERENCE STANDARDS:

BY THE AMERICAN INSTITUTE OF STEEL CONSTRUCTION (AISC):

(A.) "SPECIFICATION FOR THE DESIGN, FABRICATION AND ERECTION OF STRUCTURAL STEEL

FOR BUILDINGS." "SPECIFICATION FOR STRUCTURAL JOINTS USING ASTM A325 OR A490 BOLTS," AS APPROVED BY THE RESEARCH COUNCIL ON STRUCTURAL CONNECTIONS OF THE ENGINEERING FOUNDATION.

"CODE OF STANDARD PRACTICE FOR STEEL BUILDINGS AND BRIDGES" (PARAGRAPH 4.2.1 (B.)

SPECIFICALLY EXCLUDED).
BY THE AMERICAN WELDING SOCIETY (AWS):
(A.) "STRUCTURAL WELDING CODE - STEEL D1.1." В.

(B.) "SYMBOLS FOR WELDING AND NON-DESTRUCTIVE TESTING"
ANY MATERIAL OR WORKMANSHIP WHICH IS OBSERVED TO BE DEFECTIVE OR INCONSISTENT WITH 2. THE CONTRACT DOCUMENTS SHALL BE CORRECTED, MODIFIED, OR REPLACED AT THE CONTRACTOR'S EXPENSE.

TIGHTEN ALL STRUCTURAL BOLTS, INCLUDING THE AJAX M20 BOLTS WITH SHEAR SLEEVES, ACCORDING TO THE REQUIREMENTS OF THE AISC "TURN OF THE NUT" METHOD. TIGHTEN BOLTS 1/3 TURN PAST THE SNUG TIGHT CONDITION AS DEFINED BY AISC.

WELDED CONNECTIONS SHALL CONFORM TO THE LATEST REVISED CODE OF THE AMERICAN WELDING SOCIETY, AWS D1.1. ALL WELD ELECTRODES SHALL BE E80XX UNLESS NOTED

OTHERWISE ON THE DRAWINGS.

ALL WELDED CONNECTIONS SHALL BE MADE BY WELDERS CERTIFIED BY AWS. CONTRACTOR SHALL SUBMIT WELDERS' CERTIFICATION AND QUALIFICATION DOCUMENTATION TO THE OWNER'S TESTING AGENCY FOR REVIEW AND APPROVAL PRIOR TO CONSTRUCTION.

STRUCTURAL STEEL PLATES SHALL CONFORM TO ASTM A572 GRADE 65 (FY = 65 KSI MIN.) UNLESS

NOTED OTHERWISE ON THE DRAWINGS.
SURFACES OF EXISTING STEEL SHALL BE PREPARED AS REQUIRED FOR FIELD WELDING PER AWS.
SEE SECTION I NOTES REGARDING TOUCH-UP OF GALVANIZED SURFACES DAMAGED DURING
TRANSPORTATION OR ERECTION AND ASSEMBLY AS WELL AS FIELD WELDING. 7.

UNLESS OTHERWISE NOTED, ALL STEEL MEMBERS SHALL BE HOT-DIP GALVANIZED, AFTER FABRICATION, IN ACCORDANCE WITH ASTM A123. SEE SECTION J FOR FURTHER NOTES AND FOR

EXCEPTIONS (IF ANY).

ALL WELDS SHALL BE VISUALLY INSPECTED BY THE OWNER'S APPROVED TESTING AGENCY. OTHER TESTS MAY ALSO BE PERFORMED ON THE WELDS BY THE TESTING AGENCY IN ORDER FOR THEM TO PERFORM THEIR DUTIES FOR THIS PROJECT. THE CONTRACTOR SHALL COOPERATE WITH THE TESTING AGENCY IN THEIR TESTING EFFORTS.

NO WELDING SHALL BE DONE TO THE EXISTING STRUCTURE WITHOUT THE PRIOR APPROVAL AND SUPERVISION OF THE TESTING AGENCY.

FIELD CUTTING OF STEEL:

PRIOR TO ANY FIELD CUTTING, THE CONTRACTOR SHALL MARK THE CUT OUTLINES ON THE STEEL AND THE INSPECTION/TESTING AGENCY SHALL VERIFY PROPOSED LAYOUT, LOCATION,

AND DIMENSIONS.
ANY REQUIRED CUTS IN THE STEEL SHALL BE CAREFULLY CUT BY MECHANICAL METHODS SUCH ANY REQUIRED CUTS IN THE STEEL SHALL BE CAREFULLY CUT BY MECHANICAL METHODS SUCH AS DRILLING, SAW CUTTING, AND GRINDING. THE CONTRACTOR IS RESPONSIBLE TO PREVENT ANY DAMAGE TO THE COAX CABLES, AND/OR OTHER EQUIPMENT AND/OR THE STRUCTURE, DURING THE CUTTING WORK. ANY DAMAGE TO THE COAX CABLES, AND/OR OTHER EQUIPMENT AND/OR THE STRUCTURE, RESULTING FROM THE CONTRACTOR'S ACTIVITIES SHALL BE REPAIRED AT THE CONTRACTOR'S EXPENSE. THE INSPECTION/TESTING AGENCY SHALL CLOSELY AND CONTINUOUSLY MONITOR THIS ACTIVITY.

ALL REQUIRED CUTS SHALL BE CUT WITHIN THE DIMENSIONS SHOWN ON THE DRAWINGS. NO CUTS SHALL EXTEND BEYOND THE OUTLINE OF THE DIMENSIONS SHOWN ON THE DRAWINGS. ALL CUT EDGES SHALL BE GROUND SMOOTH AND DE-BURRED. CUT EDGES THAT ARE TO BE FIELD WELDED SHALL BE PREPARED FOR FIELD WELDING PER AWS D1.1 AND AS SHOWN ON THE DRAWINGS. IT MAY BE NECESSARY TO DRILL STARTER HOLES AS REQUIRED TO MAKE THE CUTS. THE INSPECTION/TESTING AGENCY SHALL ICLOSELY AND CONTINUOUSLY MONITOR THIS

CUTS. THE INSPECTION/TESTING AGENCY SHALL CLOSELY AND CONTINUOUSLY MONITOR THIS

BASE PLATE GROUT
NEW GROUT FOR THE POLE BASE SHALL BE NON-SHRINK, NON-METALLIC, GROUT (EUCO NS GROUT BY EUCLID, OR APPROVED EQUAL) WITH A 7500 PSI MINIMUM COMPRESSIVE STRENGTH. PVC
DRAINAGE PIPES SHALL BE PROVIDED FROM INSIDE THE POLE SHAFT OUT THROUGH THE GROUT DRAINAGE PIPES SHALL BE PROVIDED FROM INSIDE THE POLE SHAFT OUT THROUGH THE GROUT SPACE UNDER THE BASE PLATE IN ORDER TO ALLOW MOISTURE TO ADEQUATELY DRAIN FROM THE INTERIOR OF THE POLE SHAFT. CONTRACTOR SHALL SUBMIT PROPOSED GROUT SPECIFICATION INFORMATION TO THE OWNER FOR REVIEW AND APPROVAL PRIOR TO CONSTRUCTION. CONTRACTOR SHALL FOLLOW GROUT MANUFACTURER'S SPECIFICATIONS FOR COLD WEATHER GROUTING PROCEDURES (IF NECESSARY) AND THE TESTING AGENCY SHALL PREPARE GROUT SAMPLE SPECIMENS FOR COMPRESSIVE STRENGTH TESTING AND VERIFICATION. GROUT SHALL BE INSTALLED TIGHT UNDER BASE PLATE WITH NO VOIDS REMAINING BETWEEN TOP OF EXISTING CONCRETE AND UNDERSIDE OF EXISTING BASE PLATE (EXCEPT FOR DRAIN PIPES). GROUT COMPLETELY SOLID (EXCEPT FOR DRAIN PIPES) UNDER ENTIRE SURFACE OF BASE PLATE FROM OUTSIDE EDGE TO INSIDE EDGE.

FOUNDATION WORK - (NOT REQUIRED)

CAST-IN-PLACE CONCRETE - (NOT REQUIRED)

H. **EPOXY GROUTED REINFORCING ANCHOR RODS - (NOT REQUIRED)**

TOUCH UP OF GALVANIZING
THE CONTRACTOR SHALL TOUCH UP ANY AND/OR ALL AREAS OF GALVANIZING ON THE EXISTING
STRUCTURE OR NEW COMPONENTS THAT ARE DAMAGED OR ABRADED DURING CONSTRUCTION. GALVANIZED SURFACES DAMAGED DURING TRANSPORTATION OR ERECTION AND ASSEMBLY AS WELL AS ANY AND ALL ABRASIONS, CUTS, FIELD DRILLING, AND ALL FIELD WELDING SHALL BE TOUCHED UP WITH TWO (2) COATS OF ZRC-BRAND ZINC-RICH COLD GALVANIZING COMPOUND. FILM THICKNESS PER COAT SHALL BE: WET 3.0 MILS; DRY 1.5 MILS. APPLY PER ZRC (MANUFACTURER) RECOMMENDED PROCEDURES. CONTACT ZRC AT 1-800-831-3275 FOR PRODUCT INFORMATION. CONTRACTOR SHALL CLEAN AND PREPARE ALL FIELD WELDS ON GALVANIZED AND PRIME PAINTED SURFACES FOR TOUCH-UP COATING IN ACCORDANCE WITH AWS D1.1. THE OWNER'S TESTING

AGENCY SHALL VERIFY THE PREPARED SURFACE PRIOR TO APPLICATION OF THE TOUCH-UP

COATING.

G.

THE OWNER'S TESTING AGENCY SHALL TEST AND VERIFY THE COATING THICKNESS AFTER THE CONTRACTOR HAS APPLIED THE ZRC COLD GALVANIZING COMPOUND AND IT HAS SUFFICIENTLY DRIED. AREAS FOUND TO BE INADEQUATELY COATED, SHALL BE RE-COATED BY THE CONTRACTOR AND RE-TESTED BY THE TESTING AGENCY.

HOT-DIP GALVANIZE ALL STRUCTURAL STEEL MEMBERS AND ALL STEEL ACCESSORIES, BOLTS, WASHERS, ETC. PER ASTM A123 OR PER ASTM A153, AS APPROPRIATE.

PROPERLY PREPARE STEEL ITEMS FOR GALVANIZING.
DRILL OR PUNCH WEEP AND/OR DRAINAGE HOLES AS REQUIRED.

ALL GALVANIZING SHALL BE DONE AFTER FABRICATION IS COMPLETED AND PRIOR TO FIELD INSTALLATION.

PERPETUAL INSPECTION AND MAINTENANCE BY THE OWNER
AFTER THE CONTRACTOR HAS SUCCESSFULLY COMPLETED THE INSTALLATION OF THE MONOPOLE
REINFORCING SYSTEM AND THE WORK HAS BEEN ACCEPTED BY THE OWNER, THE OWNER WILL BE
RESPONSIBLE FOR THE LONG TERM AND PERPETUAL INSPECTION AND MAINTENANCE OF THE POLE

AND REINFORCING SYSTEM.
THE MONOPOLE REINFORCING SYSTEM INDICATED IN THESE DOCUMENTS USES REINFORCING COMPONENTS THAT INVOLVE FIELD WELDING STEEL MEMBERS TO THE EXISTING GALVANIZED STEEL POLE STRUCTURE. THESE FIELD WELDED CONNECTIONS ARE SUBJECT TO CORROSION DAMAGE AND DETERIORATION IF THEY ARE NOT PROPERLY MAINTAINED AND COVERED WITH CORROSION PREVENTIVE COATING SUCH AS THE ZRC GALVANIZING COMPOUND SPECIFIED PREVIOUSLY. THE STRUCTURAL LOAD CARRYING CAPACITY OF THE REINFORCED POLE SYSTEM IS DEPENDENT UPON THE INSTALLED SIZE AND QUALITY, MAINTAINED SOUND CONDITION AND STRENGTH OF THESE FIELD WELDED CONNECTIONS. ANY CORROSION OF, DAMAGE TO, FATIGUE, FRACTURE, AND/OR DETERIORATION OF THESE WELDS AND/OR THE CONNECTED COMPONENTS WILL RESULT IN THE LOSS OF STRUCTURAL LOAD CARRYING CAPACITY AND MAY LEAD TO FAILURE OF THE STRUCTURAL SYSTEM. THEREFORE, IT IS IMPERATIVE THAT THE OWNER REGULARLY INSPECTS,

MAINTAINS, AND REPAIRS AS NECESSARY, ALL OF THESE WELDS, CONNECTIONS, AND COMPONENTS FOR THE LIFE OF THE STRUCTURE.

THE OWNER SHALL REFER TO TIA/EIA-222-F-1996, SECTION 14 AND ANNEX E FOR RECOMMENDATIONS FOR MAINTENANCE AND INSPECTION. THE FREQUENCY OF THE INSPECTION AND MAINTENANCE INTERVALS IS TO BE DETERMINED BY THE OWNER BASED UPON ACTUAL SITE AND ENVIRONMENTAL CONDITIONS. PAUL J. FORD & COMPANY RECOMMENDS THAT A COMPLETE AND THOROUGH INSPECTION OF THE ENTIRE REINFORCED MONOPOLE STRUCTURAL SYSTEM BE PERFORMED YEARLY AND/OR AS FREQUENTLY AS CONDITIONS WARRANT. ACCORDING TO TIA/EIA-222-F-1996 SECTION 14.1, NOTE 1: "IT IS RECOMMENDED THAT THE STRUCTURE BE INSPECTED AFTER SEVERE WIND AND/OR ICE STORMS OR OTHER EXTREME LOADING CONDITIONS".



Rights Reserved. This document and a clata contained herein, is proprietary Paul J. Ford and Company, issued in its confidence and shall not, without the or written permission of Paul J. Ford of Company, be reproduced, copied or

PAUL J. FORD AND COMPANY NOL J. FORD AND COMPANY
STRUCTURAL ENGINEERS
250 East Broad Street · Suite 1500 · Columbus, Ohio 43215
(614) 221-6679 www.pifweb.com

3530 TORINGDON WAY, SUITE 300, CHARLOTTE, NC 28277

FAX: (704) 416-4950

PH; (704) 405-6611

BU #876315; OAK LANE CC, INC. TOWER (SSUSA WOODBRIDGE, CT

MONOPOLE REINFORCEMENT AND RETROFIT PROJECT

PROJECT No: 37512-1566 DRAWN BY: B.M.S.

CHECKED BY: T.J.D.

APPROVED BY

ISSUE DATE OF PERMIT: 8-24-2012

DATE: 8-24-2012 S-2

AJAX BOLT NOTE SHEET: REV. 1.2, 01-23-2012

NOTES

- 1. ALL STRUCTURAL BOLTS SHALL BE INSTALLED AND TIGHTENED TO THE PRETENSIONED CONDITION ACCORDING TO THE REQUIREMENTS OF THE AISC 'SPECIFICATION FOR STRUCTURAL JOINTS USING HIGH-STRENGTH BOLTS', DEC. 31, 2009.
- 2. ALL STRUCTURAL BOLTS SHALL BE INSPECTED ACCORDING TO THE REQUIREMENTS OF THE AISC 'SPECIFICATION FOR STRUCTURAL JOINTS USING HIGH-STRENGTH BOLTS', DEC. 31, 2009.
- 3. ALL AJAX M20 BOLTS WITH SHEAR SLEEVES SHALL BE PRETENSIONED AND TIGHTENED UNTIL THE DIRECT TENSION INDICATOR (DTI) WASHERS SHOW THAT THE PROPER BOLT TENSION HAS BEEN REACHED. SEE NOTES AND DETAIL BELOW FOR THE USE OF DIRECT TENSION INDICATOR (DTI) WASHERS WITH THE AJAX M20 BOLTS.
- 4. ALL AJAX BOLTS SHALL BE INSTALLED USING DIRECT TENSION INDICATORS (DTI'S) AND HARDENED WASHERS. DTI'S SHALL BE THE SQUIRTER® STYLE, MADE TO ASTM F959 LATEST REVISION; AND HARDENED WASHERS SHALL CONFORM TO ASTM F436 AND HAVE A HARDNESS OF RC 38 OR HIGHER.

NOTES FOR AJAX M20 'ONE-SIDE' BOLTS WITH DIRECT TENSION INDICATORS (DTI'S):

DTI'S REQUIRED: DTI'S SHALL BE "SELF-INDICATING" SQUIRTER® STYLE DTI'S MADE WITH SILICONE EMBEDDED IN THEM, INSPECTED BY MEANS OF THE VISUAL EJECTION OF SILICONE AS THE DTI PROTRUSIONS COMPRESS. SQUIRTER® DTI'S SHALL BE CALIBRATED PER MANUFACTURER'S INSTRUCTIONS PRIOR TO USE.

THE DIRECT TENSION INDICATOR (DTI) WASHERS SHALL BE THE "SQUIRTER® STYLE" AS MANUFACTURED BY:

APPLIED BOLTING TECHNOLOGY PRODUCTS, INC. 1413 ROCKINGHAM ROAD BELLOWS FALLS, VERMONT, USA 05101 PHONE 1-800-552-1999

WEBSITE: WWW.APPLIEDBOLTING.COM

.

DISTRIBUTORS OF SQUIRTER® DTI'S: HTTP://WWW.APPLIEDBOLTING.COM/APPLIED-BOLTING-DISTRIBUTORS.HTML

<u>DTI:</u> USE DIRECT TENSION INDICATOR (DTI) WASHERS COMPATIBLE WITH 3/4" NOMINAL A325 BOLTS FOR THE AJAX M20 BOLTS. DTI'S SHALL <u>NOT</u> BE HOT-DIP GALVANIZED. DTI'S SHALL BE MECHANICALLY GALVANIZED (MG) BY THE COLD MECHANICAL PROCESS ONLY AS PROVIDED BY THE DTI MANUFACTURER.


HARDENED WASHERS REQUIRED: USE A HARDENED WASHER FOR A 3/4" NOMINAL BOLT BETWEEN THE TOP OF THE DIRECT TENSION INDICATOR (DTI) WASHER AND THE NUT OF THE AJAX M20 BOLTS. HARDENED WASHERS SHALL CONFORM TO ASTM F436 AND HAVE A MINIMUM HARDNESS OF RC 38 OR HIGHER. THE HARDENED WASHERS SHALL BE MECHANICALLY GALVANIZED BY THE COLD MECHANICAL PROCESS. ALTERNATIVELY, CORRECTLY MADE HOT DIP GALVANIZED HARDENED FLAT WASHERS HAVING A MINIMUM HARDNESS OF RC 38 CAN BE USED; CONTRACTOR SHALL PROVIDE DOCUMENTATION OF WASHER SPECIFICATION AND HARDNESS.

NUT LUBRICATION REQUIRED: PROPERLY LUBRICATE THE THREADS OF THE NUT OF THE AJAX BOLT SO THAT IT CAN BE PROPERLY TIGHTENED WITHOUT GALLING AND/OR LOCKING UP ON THE BOLT THREADS. CONTRACTOR SHALL FOLLOW DTI MANUFACTURER INSTRUCTIONS FOR PROPER LUBRICATION AND TIGHTENING.

NOTE: COMPLETELY COMPRESSED DTI'S SHOWING NO VISIBLE REMAINING GAP ARE ACCEPTABLE. DTI WASHERS SHALL BE PLACED DIRECTLY AGAINST THE OUTER AJAX WASHER WITH THE DTI BUMPS FACING AWAY FROM THE AJAX WASHER. PLACE A HARDENED WASHER BETWEEN THE DTI AND THE AJAX NUT. THE DTI BUMPS SHALL BEAR AGAINST THE UNDERSIDE OF A HARDENED FLAT WASHER, NEVER DIRECTLY AGAINST THE NUT.

CONTRACTOR SHALL FOLLOW DTI MANUFACTURER'S INSTRUCTIONS FOR INSTALLATION, LUBRICATION, TIGHTENING AND INSPECTION.

INSPECTION REQUIRED: ALL AJAX BOLTS SHALL BE INSPECTED ACCORDING TO THE REQUIREMENTS OF THE AISC 'SPECIFICATION FOR STRUCTURAL JOINTS USING HIGH-STRENGTH BOLTS', DEC. 31, 2009, BY A QUALIFIED BOLT INSPECTOR. DURING INSTALLATION, THE BOLT INSPECTOR SHALL VERIFY AND DOCUMENT: THE SHOP-DRILLED AND FIELD-DRILLED HOLE SIZES; THE INSTALLATION OF THE AJAX BOLT ASSEMBLY, INCLUDING THE SHEAR SLEEVE PLACEMENT AND NUT LUBRICATION; AND THE CONTRACTOR'S TENSIONING PROCEDURE. IN ADDITION, ALL AJAX BOLTS AND DTI'S SHALL BE VISUALLY INSPECTED ACCORDING TO THE DTI MANUFACTURER'S INSTRUCTIONS. THE BOLT INSPECTOR SHALL PROVIDE COMPLETE PHOTO DOCUMENTATION OF ALL BOLTS AFTER TIGHTENING CLEARLY SHOWING THE CONDITION OF THE DTI'S.



© Copyright 2012, by Paul J. Ford and Company, All Rights Reserved. This document and the data contained herein, is proprietary to Paul J. Ford and Company, issued in strict confidence and shall not, without the prior written permission of Paul J. Ford and Company, be reproduced, copied or used for any purpose other than the intended use for this specific project.

PAUL J. FORD AND COMPANY
STRUCTURAL ENGINEERS
250 East Broad Street · Suite 1500 · Columbus, Ohio 43215
(614) 221-6679

www.pjfweb.com

CROWN CASTLE
3530 TORINGDON WAY, SUITE 300, CHARLOTTE, NC 28277

FAX: (704) 416-4950

BU #876315; OAK LANE CC, INC. TOWER (SSUSA WOODBRIDGE, CT

MONOPOLE REINFORCEMENT AND RETROFIT PROJECT

PROJECT No: 37512-1566 DRAWN BY: B.M.S. CHECKED BY: T.J.D.

APPROVED BY

ISSUE DATE OF PERMIT: 8-24-2012

DATE: 8-24-2012

NOTE: NO DETAILED INFORMATION REGARDING INTERFERENCES WAS PROVIDED. THEREFORE, CONTRACTOR SHALL FIELD VERIFY ALL EXISTING CONDITIONS AND DIMENSIONS BEFORE PROCEEDING WITH THE WORK. REPORT ANY AND ALL DISCREPANCIES TO PAUL J. FORD AND COMPANY AND CROWN CASTLE FIELD PERSONNEL IMMEDIATELY.

THIS POLE REINFORCEMENT DRAWING IS FOR THE POLE DESIGN AND ANTENNA LOADING DOCUMENTED IN THE PJF CO-LOCATION ANALYSIS FOR THIS SITE (PJF#37512-1566), DATED 8-24-2012.

		POLE SPECIFICATIONS	
	POLE SHAPE TYPE:	12-SIDED POLYGON	
TAPER: 0.175033 IN/FT			
	SHAFT STEEL: ASTM A607 GRADE 60, ASTM A572 GRADE 65		
	BASE PL STEEL: ASTM A572 GRADE 60 (60 KSI)		
	ANCHOR RODS: 2 1/4"Ø		
		#18J ASTM A615 GRADE 75	

		SHAFT SEC	TION DAT	Α ·	
SHAFT SECTION	1	PLATE THICKNESS (IN)	LAP SPLICE (IN)	DIAMETER ACROSS FLATS (IN)	
02011011	(, ,,	\···/	()	@ TOP	@ ВОТТОМ
1	47.50	0.2500	45.00	22.000	30.314
2	44.25	0.3125	45.00 57.00	29.158	36.903
3	34.50	0.3750	63.00	35.446	41.485
4	37.50	0.4375	03.00	39.816	46,380
	NOTE: DIME	NSIONS SHOWN DO NOT	INCLUDE GALVANI	ZING TOLERANCES	

CONTRACTOR SHALL PROVIDE ASTM A36 SHIM PLATES BELOW SLIP JOINTS. THE SHIM PLATES SHALL BE PLACED BETWEEN THE NEW SHAFT REINFORCEMENT AND THE EXISTING POLE SHAFT FROM THE SLIP JOINT TO THE NEW SHAFT REINFORCEMENT SPLICE PLATE LOCATION AND A EXTRA LONG "SPLICE SHIM" SHALL BE PLACED BETWEEN THE NEW UPPER AND LOWER SHAFT REINFORCEMENT PLATES AT THE SHAFT REINFORCEMENT

NOTES:

- . ALL STRUCTURAL BOLTS SHALL BE INSTALLED AND TIGHTENED TO THE PRETENSIONED CONDITION ACCORDING TO THE REQUIREMENTS OF THE AISC SPECIFICATION FOR STRUCTURAL JOINTS USING HIGH-STRENGTH BOLTS, DEC. 31, 2009.
- ALL STRUCTURAL BOLTS SHALL BE INSPECTED ACCORDING TO THE REQUIREMENTS OF THE AISC 'SPECIFICATION FOR STRUCTURAL JOINTS USING HIGH-STRENGTH BOLTS', DEC. 31, 2009.
- ALL AJAX M20 BOLTS WITH SHEAR SLEEVES SHALL BE PRETENSIONED AND TIGHTENED UNTIL THE DIRECT TENSION INDICATOR (DTI) WASHERS SHOW THAT THE PROPER BOLT TENSION HAS BEEN REACHED. SEE NOTES AND DETAIL ON SHEET S-3 FOR THE USE OF DIRECT TENSION INDICATOR (DTI) WASHERS WITH THE AJAX M20
- TI'S REQUIRED: * ALL AJAX BOLTS SHALL BE INSTALLED USING DIRECT TENSION INDICATORS (DTI'S) AND HARDENED WASHERS. DTI'S SHALL BE THE SQUIRTER® STYLE, MADE TO ASTM F959 LATEST REVISION; AND HARDENED WASHERS SHALL CONFORM TO ASTM F436 AND HAVE A HARDNESS OF RC 38 OR HIGHER.
- 5. <u>NUT LUBRICATION REQUIRED:</u> * PROPERLY LUBRICATE THE THREADS OF THE NUT OF THE AJAX BOLT SO THAT IT CAN BE PROPERLY TIGHTENED WITHOUT GALLING AND/OR LOCKING UP ON THE BOLT THREADS. CONTRACTOR SHALL FOLLOW DTI MANUFACTURER INSTRUCTIONS FOR PROPER LUBRICATION AND TIGHTENING
- 6. <u>AJAX BOLT HOLE SIZE</u>: ALL SHOP- AND FIELD-DRILLED HOLES SHALL BE NOMINAL 30MM DIAMETER. THE MAXIMUM HOLE DIAMETER PERMITTED IS 1-3/16". REFER TO SHEET S-3.

AS OF 5/30/2012, UNTIL FURTHER NOTICE, CROWN CASTLE WILL ACCEPT AJAX BOLTS TIGHTENED USING AISC "TURN-OF-THE MUT" METHODOLOGY. INSTALLERS SHALL FOLLOW CROWN GUIDELINES FOR AISC "TURN-OF-THE-NUT" METHOD AND ALSO PROVIDE COMPLETE INSPECTION DOCUMENTATION IN THE PMI.

NDE OF THE CIRCUMFERENTIAL WELD OF THE BASE PLATE TO SHAFT CONNECTION IS REQUIRED. PLEASE SEE ENG-SOW-1033 : TOWER BASE PLATE NDE AND ENG-BUL-10051 : NDE REQUIREMENTS FOR MONOPOLE BASE PLATE TO PREVENT CONNECTION FAILURE. NOTIFY THE EOR AND CROWN ENGINEERING IMMEDIATELY IF ANY CRACKS ARE SUSPECTED OR HAVE BEEN IDENTIFIED. THE NDE SHALL INCLUDE ALL SUSTING REINFORCEMENTS THAT HAVE BEEN WELDED TO THE BASE PLATE. FULL PENETRATION WELDING TO THE BASE PLATE REQUIRED AS PART OF THIS ACTIVE REINFORCEMENT DESIGN SHALL BE INCLUDED IN THE NDE SCOPE OF WORK.

REINFORCING BAR SPLICE DETAILS TO BE COORDINATED BY RESPECTIVE CONTRACTORS.

NEW AEROSOLUTIONS MP3 REINFORCING (OPTION #1)

ELEVATION	FLAT#	MP3
0'-6" TO 30'-6"	3, 8 & 14	MP305
30'-6" TO 55'-6"	3, 8 & 14	MP304
65'-0" TO 70'-0"	3, 8 & 14	MP303
I DOLTE CHALL DE A IAVA	20 DOLTE WITH HIC	U CTDEMOTH CHEAD

SLEEVES (ASTM A519 WITH MIN. Fu=105 KSI). CONTACT SUPPLIER FOR MATERIAL (PLATE & BOLTS) AND INSTALLATION PROCEDURES.

NEW SABRE REINFORCING (OPTION #2)

(01 11011 112)		
ELEVATION	FLAT#	MP3
0'-6" TO 30'-6"	3, 8 & 14	. MS-650
30'-6" TO 55'-6"	3, 8 & 14	MS-600
65'-0" TO 68'-6"	3, 8 & 14	MS-450

ALL BOLTS SHALL BE AJAX M20 BOLTS WITH HIGH STRENGTH SHEAR SLEEVES (ASTM A519 WITH MIN. Fu=105 KSI). CONTACT SUPPLIER FOR MATERIAL (PLATE & BOLTS) AND INSTALLATION PROCEDURES.

NEW CCI FLAT PLATE (100 KSI) **REINFORCING (OPTION #3)**

ELEVATION	FLAT#	FLAT PLATE
0'-6" TO 30'-6"	3, 8 & 14	ISP-UR-0754
30'-6" TO 54'-3"	3, 8 & 14	ISP-UR-0754
C4L01 TO 70L01	2 0 0 11	IOD UD 0754

64'-9" TO 70'-3" 3, 8 & 14 ISP-UR-07
NOTES FOR CROWN REINFORCING OPTION (100 KSI) MATERIAL:

1. DO NOT FIELD WELD DIRECTLY TO THE 100 KSI MATERIAL. 64'-9" TO 70'-3' 2. THE 100 KSI MATERIAL SHALL CONFORM TO THE FOLLOWING: A. MATERIAL SHALL BE ASTM A514, GRADE A, GRADE E, or GRADE P, HAVING A MINIMUM TENSILE STRENGTH (Fu) OF 110 KSI AND A

MINIMUM YIELD STRENGTH (Fy) OF 100 KSL B. MATERIAL SHALL BE HEAT TREATED, QUENCHED AND TEMPERED PER ASTM A514.

. MATERIAL SHALL HAVE CHARPY V-NOTCH (CVN) IMPACT VALUES OF NOT LESS THAN 15 FT-LB AT -20 DEGREES F, IN ACCORDANCE

D. MINIMUM INSIDE BEND RADIUS FOR COLD BENDING, PER ASTM A6 TABLE X.4.2, SHALL BE 4.5t MINIMUM.

E. ANY AND ALL WELDING TO THE MATERIAL SHALL BE PERFORMED ACCORDING TO AN APPROVED WELDING PROCEDURE SPECIFICATION (WPS) SUITABLE FOR THE GRADE AND INTENDED USE AND SERVICE. THE WPS SHALL BE DEVELOPED BY A QUALIFIED CWI AND IN ACCORDANCE WITH AWS D1.1. PRIOR TO ANY WORK, FABRICATION OR WELDING, THE WPS SHALL BE SUBMITTED TO CROWN CASTLE AND PAUL J. FORD AND COMPANY FOR REVIEW.

150'-0"

102'-6"


Fy=60 KSI

Fv=65 KSI

SEE CHART

SEE CHART FOR SHAFT REINFORCING INFORMATION

TEM OROMO (OF HOW III)		
ELEVATION	FLAT#	MP3
0'-6" TO 30'-6"	3, 8 & 14	MP305
30'-6" TO 55'-6"	3, 8 & 14	MP304
65'-0" TO 70'-0"	3, 8 & 14	MP303





phts Reserved. This document and ta contained herein, is proprietary I. J. Ford and Company, issued in confidence and shall not, without the united permission of Paul J. Ford ompany, be reproduced, copied or or any purpose offer than the ed use for this specific project.

PAUL J. FORD AND COMPANY STRUCTURAL ENGINEERS
250 East Broad Street · Suite 1500 · Columbus, Ohio 43215
(614) 221-6679 www.pjfweb.com

3530 TORINGDON WAY, SUITE 300, CHARLOTTE, NC 28277 PH: (704) 405-6611 FAX: (704) 416-4950 BU #876315; OAK LANE CC, INC. TOWER (SSUSA WOODBRIDGE, CT

MONOPOLE REINFORCEMENT AND RETROFIT PROJECT

PROJECT No: 37512-1566 DRAWN BY: B.M.S. CHECKED BY

T.J.D.

ISSUE DATE OF PERMIT: 8-24-2012

APPROVED BY S-4 DATE: 8-24-2012

SPECIAL INSPECTION OF EXISTING SHAFT-TO-FLANGE WELD CONNECTIONS:

(1.) PRIOR TO CONSTRUCTION, CONTRACTOR'S INSPECTION AGENCY SHALL INSPECT CONDITION OF EXISTING
SHAFT-TO-BASE-PLATE WELD CONNECTION. ALSO INSPECT EXISTING STIFFENERS IF PRESENT. THE CONTRACTOR'S
INSPECTION AGENCY SHALL USE THE FOLLOWING INSPECTION METHODS, OR COMBINATION OF METHODS, AS REQUIRED
TO IDENTIFY ANY CRACKS: VISUAL, MAGNETIC PARTICLE, AND/OR ULTRA-SONIC. IN ADDITION, OTHER TEST METHODS
MAY ALSO BE USED AT THE RECOMMENDATION OF THE TESTING AGENCY AND UPON THE APPROVAL OF THE OWNER
AND THE ENGINEER. CONTRACTOR SHALL PROVIDE CAREFUL AND THOROUGH DOCUMENTATION OF THIS INSPECTION
TO THE OWNER AND THE ENGINEER RECORE PROCEEDING WITH WORK CONTRACTOR SHALL COORDINATE THESE TO THE OWNER AND THE ENGINEER BEFORE PROCEEDING WITH WORK. CONTRACTOR SHALL COORDINATE THESE INSPECTION ACTIVITIES WITH THE OWNER'S REQUIRED PROCESSES AND PROCEDURES. IMPORTANT: THE TESTING ACENICY SHALL IMMEDIATE IN PEDIATE IN THE TESTING ACENICY SHALL IMMEDIATE IN THE TESTING ACENICY AGENCY SHALL IMMEDIATELY REPORT ANY INDICATIONS OF CRACKS, FRACTURES, DISTRE


THE OWNER AND ENGINEER.
AFTER CONSTRUCTION, TESTING AGENCY SHALL INSPECT ANY AND ALL FIELD WELDS AND FIELD REPAIRS IMPLEMENTED AS REQUIRED BY THE OWNER FROM THE RESULTS OF THE INSPECTION IN THE PREVIOUS NOTE (1) ABOVE.

GENERAL NOTES:

1. AJAX BOLTS ARE TO BE 20 mm Ø WITH CORRESPONDING 29 mm Ø SHEAR SLEEVE WITH MATCHING STEEL GRADE. DRILLED HOLE DIAMETERS IN REINFORCING STEEL AND EXISTING SHAFT SHALL BE 1 3/16" ø MAX.

ALL STEEL SHALL BE HOT-DIP GALVANIZED AFTER FABRICATION IN ACCORDANCE WITH ASTM A123. ALTERNATIVELY, ALL NEW STIFFENER PLATE STEEL REINFORCING MAY BE COLD GALVANIZED AS FOLLOWS: APPLY A MINIMUM OF TWO COATS OF ZRC-BRAND ZINC -RICH COLD GALVANIZING COMPOUND. FILM THICKNESS PER COAT SHALL BE: WET 3.0 MILS; DRY 1.5 MILS. APPLY PER ZRC (MANUFACTURER)
RECOMMENDED PROCEDURES. CONTACT ZRC AT 1-800-831-3275 FOR PRODUCT

3. ALL WELD ELECTRODES SHALL BE E80XX.



PAUL J. FORD AND COMPANY STRUCTURAL ENGINEERS 250 East Broad Street · Suite 1500 · Columbus, Ohio 43215 (614) 221-6679 www.pjfweb.com

CROWN CAST 3530 TORINGDON WAY, SUITE 300, CHARLOTTE, NC 28277

FAX: (704) 416-4950

BU #876315; OAK LANE CC, INC. TOWER (SSUSA WOODBRIDGE, CT

MONOPOLE REINFORCEMENT AND RETROFIT PROJECT

PROJECT No: 37512-1566 DRAWN BY: B.M.S. CHECKED BY:

T.J.D.

ISSUE DATE OF PERMIT: 8-24-2012

APPROVED BY S-5 DATE: 8-24-2012

MODIFICATION INSPECTION NOTES:

GENERAL THE MODIFICATION INSPECTION (MI) IS A VISUAL INSPECTION OF TOWER MODIFICATIONS AND A REVIEW OF CONSTRUCTION INSPECTIONS AND OTHER REPORTS TO ENSURE THE INSTALLATION WAS CONSTRUCTED IN ACCORDANCE WITH THE CONTRACT DOCUMENTS, NAMELY THE MODIFICATION DRAWINGS, AS DESIGNED BY THE ENGINEER OF RECORD (EOR)

THE MI IS TO CONFIRM INSTALLATION CONFIGURATION AND WORKMANSHIP ONLY AND IS NOT A REVIEW OF THE MODIFICATION DESIGN ITSELF, NOR DOES THE MI INSPECTOR TAKE OWNERSHIP OF THE MODIFICATION DESIGN. OWNERSHIP OF THE STRUCTURAL MODIFICATION DESIGN EFFECTIVENESS AND INTEGRITY RESIDES WITH THE EOR AT ALL TIMES.

ALL MPS SHALL BE CONDUCTED BY A CROWN ENGINEERING VENDOR (AEV) OR ENGINEERING SERVICE VENDOR (AESV) THAT IS APPROVED TO PERFORM ELEVATED WORK FOR CROWN. SEE ENG-BUL-10173 LIST OF APPROVED MI VENDORS.

TO ENSURE THAT THE REQUIREMENTS OF THE MI ARE MET, IT IS VITAL THAT THE GENERAL CONTRACTOR (GC) AND THE MI INSPECTOR BEGIN COMMUNICATING AND COORDINATING AS SOON AS A PO IS RECEIVED. IT IS EXPECTED THAT EACH PARTY WILL BE PROACTIVE IN REACHING OUT TO THE OTHER PARTY. IF CONTACT INFORMATION IS NOT KNOWN, CONTACT YOUR CROWN POINT OF CONTACT (POC).

REFER TO ENG-SOW-10007: MODIFICATION INSPECTION SOW FOR FURTHER DETAILS AND REQUIREMENTS.

MI INSPECTOR
THE MI INSPECTOR IS REQUIRED TO CONTACT THE GC AS SOON AS RECEIVING A PO FOR THE MI TO, AT A MINIMUM:

- REVIEW THE REQUIREMENTS OF THE MI CHECKLIST
 WORK WITH THE GC TO DEVELOP A SCHEDULE TO CONDUCT ON-SITE INSPECTIONS, INCLUDING FOUNDATION INSPECTIONS

THE MI INSPECTOR IS RESPONSIBLE FOR COLLECTING ALL GENERAL CONTRACTOR (GC) INSPECTION AND TEST REPORTS, REVIEWING THE DOCUMENTS FOR ADHERENCE TO THE CONTRACT DOCUMENTS, CONDUCTING THE IN-FIELD INSPECTIONS, AND SUBMITTING THE MI REPORT TO CROWN.

GENERAL CONTRACTOR
THE GC IS REQUIRED TO CONTACT THE MI INSPECTOR AS SOON AS RECEIVING A PO FOR THE MODIFICATION INSTALLATION OR TURNKEY

- REVIEW THE REQUIREMENTS OF THE MI CHECKLIST
 WORK WITH THE MI INSPECTOR TO DEVELOP A SCHEDULE TO CONDUCT ON-SITE INSPECTIONS, INCLUDING FOUNDATION INSPECTIONS
 BETTER UNDERSTAND ALL INSPECTION AND TESTING REQUIREMENTS

THE GC SHALL PERFORM AND RECORD THE TEST AND INSPECTION RESULTS IN ACCORDANCE WITH THE REQUIREMENTS OF THE MI

RECOMMENDATIONS
THE FOLLOWING RECOMMENDATIONS AND SUGGESTIONS ARE OFFERED TO ENHANCE THE EFFICIENCY AND EFFECTIVENESS OF DELIVERING A MI REPORT:

- IT IS SUGGESTED THAT THE GC PROVIDE A MINIMUM OF 5 BUSINESS DAYS NOTICE, PREFERABLE 10, TO THE MI INSPECTOR AS TO WHEN THE SITE WILL BE READY FOR THE MI TO BE CONDUCTED.

 THE GC AND MI INSPECTOR COORDINATE CLOSELY THROUGHOUT THE ENTIRE PROJECT.

 WHEN POSSIBLE, IT IS PREFERRED TO HAVE THE GC AND MI INSPECTOR ON-SITE SIMULTANEOUSLY FOR ANY GUY WIRE TENSIONING OR

- WHEN POSSIBLE, IT IS PREFERRED TO HAVE THE GC AND MI INSPECTOR ON-SITE SIMULTANEOUSLY FOR ANY GUY WIRE TENSIONING RE-TENSIONING OPERATIONS. IT IS PREFERRED TO HAVE THE GO. AND MI INSPECTION STO ALLOW FOUNDATION AND MI INSPECTION(S) TO COMMENCE WITH ONE SITE VISIT.

 WHEN POSSIBLE, IT IS PREFERRED TO HAVE THE GC AND MI INSPECTOR ON-SITE DURING THE MI TO HAVE ANY DEFICIENCIES CORRECTED DURING THE INITIAL MI. THEREFORE, THE GC MAY CHOOSE TO COORDINATE THE MI CAREFULLY TO ENSURE ALL CONSTRUCTION FACILITIES ARE AT THEIR DISPOSAL WHEN THE MI INSPECTOR IS ON SITE.

CANCELLATION OR DELAYS IN SCHEDULED MI

IF THE GC AND MI INSPECTOR AGREE TO A DATE ON WHICH THE MI WILL BE CONDUCTED, AND EITHER PARTY CANCELS OR DELAYS, CROWN
SHALL NOT BE RESPONSIBLE FOR ANY COSTS, FEES, LOSS OF DEPOSITS AND/OR OTHER PENALTIES RELATED TO THE CANCELLATION OR
DELAY INCURRED BY EITHER PARTY FOR ANY TIME (E.G. TRAVEL AND LODGING, COSTS OF KEEPING EQUIPMENT ON-SITE, ETC.). IF CROWN
CONTRACTS DIRECTLY FOR A THIRD PARTY MI, EXCEPTIONS MAY BE MADE IN THE EVENT THAT THE DELAY/CANCELLATION IS CAUSED BY
WEATHER OR OTHER CONDITIONS THAT MAY COMPROMISE THE SAFETY OF THE PARTIES INVOLVED.

CORRECTION OF FAILING MI'S

IF THE MODIFICATION INSTALLATION WOULD FAIL THE MI ("FAILED MI"), THE GC SHALL WORK WITH CROWN TO COORDINATE A REMEDIATION

- CORRECT FAILING ISSUES TO COMPLY WITH THE SPECIFICATIONS CONTAINED IN THE ORIGINAL CONTRACT DOCUMENTS AND COORDINATE A SUPPLEMENT MI.
- OR, WITH CROWN'S APPROVAL, THE GC MAY WORK WITH THE EOR TO RE-ANALYZE THE MODIFICATION/REINFORCEMENT USING THE AS-BUILT CONDITION

MI VERIFICATION INSPECTIONS
CROWN RESERVES THE RIGHT TO CONDUCT A MI VERIFICATION INSPECTION TO VERIFY THE ACCURACY AND COMPLETENESS OF PREVIOUSLY COMPLETED MI INSPECTION(S) ON TOWER MODIFICATION PROJECTS.

ALL VERIFICATION INSPECTIONS SHALL BE HELD TO THE SAME SPECIFICATIONS AND REQUIREMENTS IN THE CONTRACT DOCUMENTS AND IN ACCORDANCE WITH ENG-SOW-10007.

VERIFICATION INSPECTION MAY BE CONDUCTED BY AN INDEPENDENT AEV/AESV FIRM AFTER A MODIFICATION PROJECT IS COMPLETED, AS MARKED BY THE DATE OF AN ACCEPTED "PASSING MI" OR "PASS AS NOTED MI" REPORT FOR THE ORIGINAL PROJECT

PHOTOGRAPHS

BETWEEN THE GC AND THE MI INSPECTOR THE FOLLOWING PHOTOGRAPHS, AT A MINIMUM, ARE TO BE TAKEN AND INCLUDED IN THE MI

- PRE-CONSTRUCTION GENERAL SITE CONDITION
 PHOTOGRAPHS DURING THE REINFORCEMENT MODIFICATION CONSTRUCTION/ERECTION AND INSPECTION RAW MATERIALS
- PHOTOS OF ALL CRITICAL DETAILS FOUNDATION MODIFICATIONS
- WELD PREPARATION BOLT INSTALLATION AND TORQUE
- FINAL INSTALLED CONDITION
- SURFACE COATING REPAIR
 POST CONSTRUCTION PHOTOGRAPHS
- FINAL INFIELD CONDITION

PHOTOS OF ELEVATED MODIFICATIONS TAKEN FROM THE GROUND SHALL BE CONSIDERED INADEQUATE.

THIS IS NOT A COMPLETE LIST OF REQUIRED PHOTOS, PLEASE REFER TO ENG-SOW-10007.

	MI CHECKLIST
CONSTRUCTION/INSTALLATION INSPECTIONS AND TESTING REQUIRED (COMPLETED BY EOR)	REPORT ITEM
	PRE-CONSTRUCTION
X	MI CHECKLIST DRAWINGS
X	EOR APPROVED SHOP DRAWINGS
X	FABRICATION INSPECTION
NA	FABRICATOR CERTIFIED WELD INSPECTION
X	MATERIAL TEST REPORT (MTR)
NA	FABRICATOR NDE INSPECTION
X	NDE REPORT OF MONOPOLE BASE PLATE (AS REQUIRED)
X	PACKING SLIPS
DDITIONAL TESTING AND INSPECTIONS:	
	CONSTRUCTION
X	CONSTRUCTION INSPECTIONS
NA	FOUNDATION INSPECTIONS
NA	CONCRETE COMP. STRENGTH AND SLUMP TESTS
NA	POST INSTALLED ANCHOR ROD VERIFICATION
Х .	BASE PLATE GROUT VERIFICATION
X	CONTRACTOR'S CERTIFIED WELD INSPECTION
NA	EARTHWORK: LIFT AND DENSITY
X	ON SITE COLD GALVANIZING VERIFICATION
NA	GUY WIRE TENSION REPORT
X	GC AS-BUILT DOCUMENTS
X	INSPECTION OF BOLT PRETENSION PER AISC BOLT SPEC.
	INSPECTION OF AJAX BOLTS AND DTI'S PER REQUIREMENTS ON SHEET S-3
DITIONAL TESTING AND INSPECTIONS:	
F	POST-CONSTRUCTION
	MI INSPECTOR REDLINE OR RECORD DRAWING(S)
	POST INSTALLED ANCHOR ROD PULL-OUT TESTING
	PHOTOGRAPHS
DITIONAL TESTING AND INSPECTIONS:	-IOTOGRAPHS

NOTE: X DENOTES A DOCUMENT NEEDED FOR THE PMI REPORT NA DENOTES A DOCUMENT THAT IS NOT REQUIRED FOR THE PMI REPORT



PH: (704) 405-6611

PAUL J. FORD AND COMPANY STRUCTURAL ENGINEERS 250 East Broad Street · Suite 1500 · Columbus, Ohio 43215 (614) 221-6679 www.pjfweb.com

3530 TORINGDON WAY, SUITE 300, CHARLOTTE, NC 28277

BU #876315; OAK LANE CC, INC. TOWER (SSUSA WOODBRIDGE, CT MONOPOLE REINFORCEMENT AND RETROFIT PROJECT

PROJECT No: 37512-1566 DRAWN BY: B.M.S. CHECKED BY T.J.D. APPROVED BY

> DATE: 8-24-2012

ISSUE DATE OF PERMIT: 8-24-2012

S-6