



Connecticut DOT

Number: EB-2016-8

Office of Engineering

Date: December 21, 2016

ENGINEERING BULLETIN

Division Chief, Bridges

Revisions to Bridge Inspection Manual

The Department's bridge inspection requirements for Quality Control/Quality Assurance and minimum resolution of Bridge Inspection Report photographs are hereby revised. The new requirements are summarized below and are effective immediately.

Quality Control/Quality Assurance

Chapter 4, "Quality Control/Quality Assurance" of the [Bridge Inspection Manual](#) has been replaced in its entirety. The requirements of the new chapter shall be used for all Department activities and actions involving the safety inspection of bridges and other structures.

Resolution of Inspection Report Photographs

Per this bulletin, photographs in Bridge Inspection Reports shall have a minimum resolution of eight (8) megapixels. The photograph specifications within the [Bridge Inspection Manual](#) have not yet been revised but are hereby superseded.